



not found
near
5/11/24
PIP
3 days
Zeh she. After repair
~~Lump Sum~~ / Part by Part

ASSESSMENT FOR REPAIR : FBW7361S
HONDA ADV750
COE EXPIRY : 14.08.2034

Qty	Description	Repairer's Estimate	1st Survey	Repair Survey	Final Survey
1	RH - HAND GUARD	109.89	✓		
1	EXHAUST MUFFLER	981.00	X		
1	REAR TYRE SPLASH GUARD	98.10	✓		
		1,188.99			

ground ✓
X
Dange ✓
102

Special Nett Items

STEERING CONE & BEARING	11	130.00	X		
FRONT FORK ALIGNMENT	11	230.00	X		
WHEEL ALIGNMENT	11	130.00	X		
FRAME ALIGNMENT	11	210.00	X		
CRASH BAR	Bent/11	824.04	✓		
CRASH BAR SLIDERS	11	156.96	✓		
REAR TOP BOX	11	353.16	✓		
		2,034.16			

Total Parts 3,223.15

Labour Charges

1	Workmanship to renew damage parts & areas	400.00	280
	\$100 per days X 4 days	400.00	

Total Parts & Labours Concluded 3,623.15

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) for a resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice"
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval

Acknowledged by Repairer
Signature:
Date:

SANFU MOTOR PTE LTD
Company Reg No.: 200612487G
1 Kaki Bukit Ave 6, #02-43, AutoBay@Kaki Bukit, Singapore 417883
Direct Line: 9061 3299 Tel: (65) 6744 7753 Fax: (65) 6744 6010
Email: sanfumotor0243@gmail.com