



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | |
|--|--|-----------------|--|--|
| CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909 ATTN: JENNY LEW | | | Ref: CS/CTI24110035/Unh3m4(N) Date: 01/07/2025 Code: CTI | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | | |
| Insured Veh. | SKZ 9722Z | Veh. Inspected | FBW 7361S | |
| Policy No. | DMHCSNW00006512400 | Coverage (\$) | 0.00 | |
| Claim No. | SNM24D206151 | Excess (\$) | 0.00 | |
| Assign From | LYNN KHONG | Assign Date | 04/11/2024 | |
| 2. Vehicle Particulars & Condition | | | | |
| Make & Model | HONDA ADV750 | c.c | 745 | |
| Engine No. | HIDDEN | Year of Reg. | 2024 | |
| Chassis No. | JH2RH10A6RK308703 | Colour | BLACK | |
| Odometer | 4720 KM | Steering | IN ORDER | |
| Brakes | IN ORDER | Modification | SPORTS RIM | |
| General | GOOD | | | |
| 3. Conditions of Tyres | | | | |
| | Size | Make | Balance | |
| R/H Front Tyre | 120/70 R17 | BRIDGESTONE | 8 mm | |
| L/H Front Tyre | | | mm | |
| R/H Rear Tyre | 160/60 R15 | BRIDGESTONE | 8 mm | |
| L/H Rear Tyre | | | mm | |
| 4. Description of Damages | | | | |
| THE VEHICLE SUSTAINED DAMAGES AT THE N/S AND O/S BODY. DAMAGES SEE DETAILS. | | | | |
| 5. General Information | | | | |
| Accident Date | 28/10/2024 | Inspection Date | 05/11/2024 | |
| Survey held at | SANFU MOTOR PL 1 KAKI BUKIT AVENUE 6 #02-43 AUTOBAY @ KAKI BUKIT SINGAPORE 417883 | | | |
| 5a. Remarks | | | | |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | |
| 5b. Estimate Days of Repair | | | | |
| ESTIMATED NORMAL PERIOD FOR REPAIR: | | | 3 Working Days | |