



BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 197000288K

MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATION | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

CHINA TAIPING INSURANCE (S) PTE LTD

105 CECIL STREET

#18-00 / 19-00

THE OCTAGON

S'PORE 069534

ATTN: CHINA TAIPING INSURANCE (S) PTE LTD

NO. : 48148

- Rev. 1

DATE : 02/11/2024

CLAIM NO. : 12638

POLICY NO. :

FROM : MIGNON

VEHICLE NO. : FBG5666K

MAKE/MODEL : YAM / FZ16

*not actual
du
news
90086608
2/55
3 days
take 2 hrs after ny-*

(Page 1 of 3)

S/N	Description	Action	Qty	Unit Price	Amount
1	BALANCER HANDLE P/N: 80422 - (REPORTED BY MECHANIC)	REPLACE	2.00	\$8.00	16.00
2	BAR FOOTREST FRONT RH P/N: 40315 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$17.00	17.00
3	BAR HANDLE P/N: 44886 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$47.00	47.00
4	BOLT FOOTREST FRONT P/N: 44888 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$10.00	10.00
5	BOX REAR ALUMINIUM 45LITRE (ZEDGE) P/N: 74617 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$373.00	373.00 X
6	CAP END MUFFLER (BLACK) P/N: 43631 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$34.00	34.00
7	EMBLEM P/N: 50204 - (REPORTED BY MECHANIC)	REPLACE	2.00	\$14.00	28.00
8	FOOTREST REAR LH P/N: 53988 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$19.00	19.00 X
9	GRAPHIC 1 - (REPORTED BY MECHANIC)	REPLACE	2.00	\$5.00	10.00



S/N	Description	Action	Qty	Unit Price	Amount
10	GRAPHIC 3 P/N: 45151 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$5.00	5.00
11	GRAPHIC FUEL TANK - (REPORTED BY MECHANIC)	REPLACE	1.00	\$38.00	38.00
12	GRIP HANDLE SET P/N: 77911 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$47.00	47.00
13	GROMMET (TOP PROTECTOR) P/N: 46849 - (REPORTED BY MECHANIC)	REPLACE	6.00	\$8.00	48.00
14	LABOUR P/N: 06766 - LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS.	Supply/Install	10.00	\$85.00	850.00
15	LAMP SIGNAL FRONT RH P/N: 45130 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$27.00	27.00 X
16	LEVER BRAKE P/N: 40317 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$17.00	17.00 X
17	MIRROR ASSY (LH) P/N: 50884 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$31.00	31.00 X
18	MIRROR RH P/N: 40318 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$31.00	31.00 X
19	PROTECTOR MUFFLER (SILVER) P/N: 40320 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$44.00	44.00
20	Rear box bracket alignment - (REPORTED BY MECHANIC)	Repair	1.00	\$94.00	94.00
21	RUBBER - (REPORTED BY MECHANIC)	REPLACE	10.00	\$3.00	30.00
22	SHROUD AIR P/N: 50471 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$40.00	40.00
23	SIDE STAND P/N: 50203 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$27.00	27.00 X
24	Spray painting all cover - (REPORTED BY MECHANIC)	REPLACE	1.00	\$1,008.00	1,008.00



bizSAFE₃



S/N	Description	Action	Qty	Unit Price	Amount
25	STICKER COVER TAIL LH P/N: 63585 - (REPORTED BY MECHANIC)	REPLACE	2.00	\$2.00	4.00
26	SWITCH HANDLE RH P/N: 59575 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$43.00	43.00

SUB TOTAL

\$2,938.00

GST @ 9 %

\$264.42

GRAND TOTAL (SGD)

\$3,202.42

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of

BAN HOCK HIN CO PTE LTD

Acknowledge & Accepted By



MIGNON

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

+ Helmet need to claim

p-418



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

bizSAFE₃