

37 ELRRY3

See Gen

Bifrost Auto Pte Ltd

8 Kaki Bukit Ave 4 #01-49, Premier @ Kaki Bukit Singapore 415875

Tel: 93290237 Email: claims_rar@bifrotauto.com

SJE : _____
 Date of Survey : _____
 Date of ReSurvey: _____
 Contacts : _____

Vehicle Nos : **GBH 6202D**
 Made : Toyota
 Model : Dyna 150 5MT
 Chassis No : JTFAT35Y30K210390

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount: _____

Working Day: _____

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	Front Bumper	1	\$ 683.90	\$ 683.90
2	Front Bumper Reinforcement	1	\$ 301.80	\$ 301.80
3	Front Bumper Bracket RH	1	\$ 232.70	\$ 232.70
4	Front Bumper Bracket LH	1	\$ 232.70	\$ 232.70
5	Front Bumper Foglamp Garnish RH	1	\$ 105.30	\$ 105.30
6	Front Bumper Foglamp Garnish LH	1	\$ 105.30	\$ 105.30
7	Front Grille Assembly	1	\$ 501.20	\$ 501.20
8	Front Grille Emblem	1	\$ 78.40	\$ 78.40
9	Front Panel	1	\$ 1,262.80	\$ 1,262.80
10	Front Wiper Panel	1	\$ 286.20	\$ 286.20
11	Front Windscreen Glass	1	\$ 1,541.00	\$ 1,541.00
12	Front Windscreen Glass Moulding	1	\$ 309.80	\$ 309.80
13	Front Windscreen Pillar RH	1	\$ 390.00	\$ 390.00
14	Front Headlamp Assembly RH	1	\$ 1,195.80	\$ 1,195.80
15	Front Headlamp Assembly LH	1	\$ 1,195.80	\$ 1,195.80
16	Front Headlamp Assembly Lower Rubber RH	1	\$ 38.10	\$ 38.10
17	Front Headlamp Assembly Lower Rubber LH	1	\$ 38.10	\$ 38.10
18	Front Apron Garnish Corner RH	1	\$ 108.50	\$ 108.50
19	Front Apron Garnish Centre	1	\$ 298.60	\$ 298.60
20	Front Corner Panel RH	1	\$ 323.60	\$ 323.60
21	Front Corner Garnish (Upper) RH	1	\$ 110.70	\$ 110.70
22	Front Door Side Mirror RH	1	\$ 345.70	\$ 345.70
23	Front Door RH	1	\$ 1,685.20	\$ 1,685.20
24	Front Door Outer Moulding RH	1	\$ 188.20	\$ 188.20
25	Front Door Upper Hinge RH	1	\$ 89.95	\$ 89.95
26	Front Door Lower Hinge RH	1	\$ 89.95	\$ 89.95
27	Front Door Checker RH	1	\$ 149.70	\$ 149.70

28	Front Door Weatherstrip RH	ut	1	\$	206.50	\$	206.50	✓
29	Front Door Arch Rubber RH	ut	1	\$	75.60	\$	75.60	✓
30	Front Door Glass Channel RH	ond	1	\$	185.70	\$	185.70	✓
31	Front Door Inner Lock RH	ond	1	\$	305.70	\$	305.70	✓
32	Front Door Lock Catch RH	new	1	\$	36.70	\$	36.70	+
33	Front Door Inner Trim Board RH	Delnd	1	\$	672.30	\$	672.30	✓
34	Front Door Glass RH	Shuttered	1	\$	721.10	\$	721.10	-
35	Front Door Power Window Motor RH	new	1	\$	586.30	\$	586.30	+
36	Front Door Regulator RH	ond	1	\$	341.70	\$	341.70	✓
37	Front Door Speaker RH	new	1	\$	245.10	\$	245.10	+
38	Front Door Pillar (Inner) RH	Regr	1	\$	387.40	\$	387.40	+
39	Front Floor Panel Side Garnish RH	new	1	\$	388.60	\$	388.60	+
40	Front Door Pillar (Outer) RH	Regr	1	\$	398.60	\$	398.60	+
41	Front Wheel Arch Panel RH	Disturbed	1	\$	192.10	\$	192.10	✓
42	Front Wheel Arch Rubber RH	ut	1	\$	85.60	\$	85.60	✓
43	Front Step Panel Garnish RH	cut	1	\$	281.70	\$	281.70	✓
44	Front Cabin Rear Panel RH	Regr	1	\$	1,237.60	\$	1,237.60	+
45	Floor Panel	Regr	1	\$	1,228.30	\$	1,228.30	+
46	Floor Panel Carpet	new	1	\$	828.40	\$	828.40	+
47	Front Wiper Arm RH	}	1	\$	122.00	\$	122.00	+
48	Front Wiper Arm LH		1	\$	122.00	\$	122.00	+
49	Front Wiper Blade RH		1	\$	56.00	\$	56.00	+
50	Front Wiper Blade LH		1	\$	56.00	\$	56.00	+
51	Front Wiper Linkage	}	1	\$	420.00	\$	420.00	+
52	Front Wiper Motor		1	\$	760.00	\$	760.00	+
53	Front Shock Absorber RH		1	\$	304.20	\$	304.20	+
54	Front Lower Arm RH		1	\$	590.10	\$	590.10	+
55	Front Lower Arm Ball Joint RH	}	1	\$	184.40	\$	184.40	+
56	Front Upper Arm RH		1	\$	1,185.70	\$	1,185.70	+
57	Mudflap RH	new	1	\$	114.20	\$	114.20	+
58	Rear Side Gate RH	2 of	1	\$	1,945.20	\$	1,945.20	+
59	Rear Side Gate Lower Panel RH	1 of	1	\$	845.20	\$	845.20	+
Parts Sub Total :						\$	26,999.00	
25% Discount						\$	6,749.75	
PARTS TOTAL :						\$	20,249.25	

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$	
1	Front Number Plate	1	\$ 40.00	\$ 40.00	+
2	Front Grille Assembly Clips - Set	1	\$ 50.00	\$ 50.00	+
3	Front Corner Panel Clips - Set	1	\$ 30.00	\$ 30.00	+

4	Front Door Inner Trim Board Clips RH - Set <i>new</i>	1	\$	50.00	\$	50.00	30
5	Front Windscreen Glass Sealant <i>new</i>	1	\$	150.00	\$	150.00	+
6	Front Panel Sealant <i>new</i>	1	\$	150.00	\$	150.00	+
7	Front Wiper Panel Sealant <i>new</i>	1	\$	120.00	\$	120.00	+
8	Front Door RH Sealant <i>new</i>	1	\$	150.00	\$	150.00	+
9	Front Windscreen Panel Sealant <i>new</i>	1	\$	150.00	\$	150.00	+
10	Front Door RH Company Reg Sticker <i>new</i>	1	\$	50.00	\$	50.00	30
11	Front Door Advertisement Sticker <i>new</i>	1	\$	1,200.00	\$	1,200.00	300
12	Rear Side Gate Advertisement Sticker <i>new</i>	1	\$	1,000.00	\$	1,000.00	+
13	Rear Side Gate Top Stainless Steel Railing RH <i>new</i>	1	\$	1,500.00	\$	1,500.00	+
14	Rear Side Gate Aluminium Plate <i>new</i>	1	\$	2,000.00	\$	2,000.00	+
15	Rivets - Set <i>new</i>	1	\$	150.00	\$	150.00	+
16	Front Steel Rim RH <i>new</i>	1	\$	250.00	\$	250.00	20
17	Front Tyre RH <i>new</i>	1	\$	150.00	\$	150.00	+
18	ERP Bracket <i>new</i>	1	\$	50.00	\$	50.00	+
SPECIAL NETT TOTAL :					\$	7,240.00	

Nos.	LABOUR	TOTAL S\$	
1	To Panel Beat, Remove & Refix Parts	\$ 2,400.00	100
2	To Spray Paint Affected Areas	\$ 1,800.00	80
3	Wiring & Bulb Check	\$ 120.00	30
4	To Remove & Refix Front Windscreen Glass	\$ 150.00	120
5	To Transfer Front Door RH Mechanism	\$ 120.00	60
6	To Remove & Refix Front Dashboard Assembly	\$ 500.00	+
7	To Remove & Refix Front Interior Upholstry to facilitate repairs	\$ 150.00	60
8	To Remove & Refix Front Undercarriage	\$ 350.00	+
9	To Remove & Refix Front Tyre and Conduct Wheel Balancing	\$ 150.00	80
10	To Remove & Refix Rear Side Gate Aluminium Plate	\$ 400.00	+
11	To Conduct Four Wheel Alignment	\$ 150.00	80
12	To apply anti rust on affected parts	\$ 150.00	80
13	To Conduct Water Leak Test	\$ 100.00	+
14	To Send Diagnostic & Reset Control Unit. Programming & Calibration	\$ 480.00	+
LABOUR TOTAL :		\$ 7,020.00	

Adrian L

A/s 06/10/24

07 Days

PARTS TOTAL : \$ 20,249.25

SPECIAL NETT TOTAL : \$ 7,240.00

LABOUR TOTAL : \$ 7,020.00

GRAND TOTAL : \$ 34,509.25