

# Lian Her Motors

Blk 5038 #01-405 Ang Mo Kio Industrial Pk 2 Singapore 569541  
Tel : 64817221

Ang Sui Fa  
Blk 454 Yishun Street 41  
# 11 - 27  
Singapore 760454

Vehicle No : SLS 1647 K  
Make : Toyota C-HR  
Year : 2016

Not Withheld  
11 Sep @ 2000h  
Repair After Pains  
3 days

Qty	Description	Unit Price	Amount
-----	-------------	------------	--------

## Estimate Cost Of Repair

1 pc	Rear tail-gate assy		\$1,150.70 X
1 pc	Rear tail-gate emblem - Hybrid		\$48.90 - X
1 pc	Rear tail-gate emblem - C-HR		\$45.80 - X
1 pc	Rear tail-gate emblem		\$62.30 X
1 pc	Rear boot rubber		\$205.60
1 pc	Rear bumper		\$885.70
1 pc	Rear bumper reinforcement		\$483.20
2 pcs	Rear bumper reflector garnish X	\$125.60	\$251.20 X
1 pc	Rear lower bumper		\$485.70 X
2 pcs	Rear bumper side retainer	\$75.10	\$150.20 X
1 pc	Rear end panel		\$725.70 X
1 pc	Rear end panel inner garnish		\$402.10 X
			\$4,897.10
Less 25 %			\$1,224.28
			\$3,672.82

## S Nett

20 pcs	Rear bumper clip	\$2.00	\$40.00
1 pc	Rear reverse sensor	\$200.00	\$200.00

## Labour Charges

Remove/renew the above parts including knocking, welding & cutting.	\$800.00	400
To putty & spray paint on accident affected portion	\$800.00	400
Check and reconnect wiring	\$40.00	15h
To anit- rust proofing	\$100.00	X
Total	\$5,652.82	

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: