

CS/SMR 24110038/K9p3  
REF: K671

ASS. REC. BY:

Kenneth

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s Lian He

of 761N

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.

Bal. or Market Value: \$ 44K

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Date / Time Action / Instruction

1 / Est not ready

13/11 11 Lian & 2000 Coln (Ved & 365282, 657)

Veh No: SLS 1647K Yr Regn: 09.17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or AD

Make: Toy CHR C.C. 1797

Colour: M.P. White A/C: Insured / Std / NI / NA

Sp. Reading: 529926 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: BYX10 2059040

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / SRIm / STD A/RIm or

Tyre Size: F: \_\_\_\_\_

R: 215/60R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Tri Star

Front 8 mm Rear 8 mm

R/Bal. 8 mm R/Bal. 8 mm

L/Bal. 8 mm L/Bal. 8 mm

D.O.A. 29/10/24 D.O.I. 12/11/2024

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to? ☐ : Prel. Report

1) 14/11 Final ☐ : Final Report

Date/Time, File Return to? ☐

2) \_\_\_\_\_

Report Format: TP

Lump Sum / I.B.I. (\$) 2000

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech Invs (\$)

☐ : Weekend (\$)

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

TOTAL

# Lian Her Motors

Blk 5038 #01-405 Ang Mo Kio Industrial Pk 2 Singapore 569541  
Tel : 64817221

Ang Sui Fa  
Blk 454 Yishun Street 41  
# 11 - 27  
Singapore 760454

Vehicle No : SLS 1647 K  
Make : Toyota C-HR  
Year : 2016

Not Withhold  
1/1 Day \$2000h  
Resurvey After Paint  
3 days

| Qty | Description | Unit Price | Amount |
|-----|-------------|------------|--------|
|-----|-------------|------------|--------|

## Estimate Cost Of Repair

|       |                                |  |
|-------|--------------------------------|--|
| 1 pc  | Rear tail-gate assy            |  |
| 1 pc  | Rear tail-gate emblem - Hybrid |  |
| 1 pc  | Rear tail-gate emblem - C-HR   |  |
| 1 pc  | Rear tail-gate emblem          |  |
| 1 pc  | Rear boot rubber               |  |
| 1 pc  | Rear bumper                    |  |
| 1 pc  | Rear bumper reinforcement      |  |
| 2 pcs | Rear bumper reflector garnish  |  |
| 1 pc  | Rear lower bumper              |  |
| 2 pcs | Rear bumper side retainer      |  |
| 1 pc  | Rear end panel                 |  |
| 1 pc  | Rear end panel inner garnish   |  |

photo

|           |            |   |
|-----------|------------|---|
| R         | \$1,150.70 | X |
| na.       | \$48.90    | X |
| na.       | \$45.80    | X |
| na.       | \$62.30    | X |
| na.       | \$205.60   | X |
| Revised   | \$885.70   | X |
| na.       | \$483.20   | X |
| \$125.60  | \$251.20   | X |
| cm        | \$485.70   | X |
| \$75.10   | \$150.20   | X |
| na.       | \$725.70   | X |
| na.       | \$402.10   | X |
|           | \$4,897.10 |   |
| Less 25 % | \$1,224.28 |   |
|           | \$3,672.82 |   |

102.80

## S Nett

|        |                     |  |
|--------|---------------------|--|
| 20 pcs | Rear bumper clip    |  |
| 1 pc   | Rear reverse sensor |  |

photo

|        |    |          |  |
|--------|----|----------|--|
| \$2.00 | mc | \$40.00  |  |
| per 1  |    | \$200.00 |  |

## Labour Charges

Remove/renew the above parts including knocking, welding & cutting.

\$800.00 400l

To putty & spray paint on accident affected portion

\$800.00 400l

Check and reconnect wiring

\$40.00 15h

To anit- rust proofing

na \$100.00 X

Total \$5,652.82

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: