

HUP LIAN HUAT ENGINEERING WORKS

No.38 Defu Lane 9 , Singapore 539278
 TEL: 6282 3336 (3 Lines) FAX: 6289 3336 Email: mahlian@singnet.com.sg
 GST:52832105J RCB NO:201327339E

not Authorised means 5/11/24 1/5 @ 2400/ Total W/o Adminy 2 days.

M/S : MSIG INSURANCE (SINGAPORE) PTE LTD
 4 Shenton Way
 #21-01 SGX Centre 2
 Singapore 068807
 TEL: 6827 7602 FAX: 6827 2708
 ATTN: Motor Claim Department

Estimate No: **ES1602319**
 Date: 27 Oct 2024
 Policy No: 5141680510
 Veh Reg No: **XD7177Y**
 Make/Model: MITSUBISHI FV51JJD4RDEA
 Chassis No: FV51JJA10133
 Engine No: 6M70457033
 Reg. Date: 28/06/2013

Your Ref No: SOON SENG KIM
 Claim Type: Third Party
 Accident Date: 27/10/2024
 TP Veh Reg No: SNB4160T

Estimate Repair Cost to Vehicle No :XD7177Y

Description	U/Price	Quantity	List Price	Amount
			SS	SS
Net Price				
1 Tail Lamp Assy -LH/RH	292 380.00	2 PC	760.00	1 PC
2 Tail Lamp Bracket -LH/RH	380.00	2 PC	760.00	X
3 Rear Mudguard -LH	1,200.00	1 PC	1,200.00	X
4 Rear Mudguard Bracket -LH/RH	580.00	2 PC	1,160.00	X
5 Rear Mudguard Rubber -LH/RH	200.00	2 PC	400.00	X
6 Rear Chassis	2,800.00	2 PC	5,600.00	X
7 Rear Chassis Hook	580.00	1 PC	580.00	X
8 Rear Crossmember	2,000.00	1 SET	2,000.00	1600 S/W
9 Rear License Lamp	180.00	2 PC	360.00	1 PC
10 Rear License Lamp Bracket	150.00	2 PC	300.00	X
11 Rear Spotlight -LH	250.00	1 PC	250.00	✓
12 Rear Number Plate	80.00	1 PC	80.00	15 S/W
			13,450.00	13,450.00
Labour				
13 Labour to remove & renew tail lamp & check wiring & refocus all light .	580.00	1 -	580.00	20
14 Labour to remove & refix rear chassis ,rear crossmember .	1,600.00	1 -	1,600.00	} 500
15 Labour charge to dismantle & cut & welding RH rear mudguard bracket ,rear wheel mudguard ,sideguard & bracket .	1,500.00	1 -	1,500.00	
16 To rust proofing on affected area .	950.00	1 -	950.00	X
17 To spray & painting at accident affected area .	1,500.00	1 -	1,500.00	350
			6,130.00	6,130.00

Total SS 19,580.00

Add GST @ 9% 1,762.20

Total Amount Payable SS 21,342.20

TOTAL: SINGAPORE DOLLAR TWENTY ONE THOUSAND THREE HUNDRED FORTY TWO AND CENTS TWENTY ONLY

LKK Auto Consultants hence notify the Repairer of the following:
 • To resurvey before/after spray painting
 • To display vehicle for 7 days
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

For HUP LIAN HUAT ENGINEERING WORKS

7- 722 257 541.50 1615 870 3026.5