

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
MS	INCOME INSURAN		Ref:	CS/INC24110042/Uqh3m4	
	75 BRAS BASAH R		Date:	13/11/2024	
	INCOME CENTRE	SINGAPORE 189557	Code:	INC	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SMH 6352Z	Veh. Inspected	SNF 3706E	
	Policy No.	-	Coverage	0	
	Claim No.	MT/1301876-002	Excess	\$0.00	
	Assign From	AZHARI AFIDI	Assign Date	04/11/2024	
2. Vehicle Details					
	Make & Model	BMW 318I (A)	C.C	1499	
	Engine No.	39755463B38B15A	Year of Reg.	21/12/2018	
	Chassis No.	WBA8E32020A553422	Colour	BLUE	
	Odometer	84063 KM	Steering	IN ORDER	
	Brakes	IN ORDER	General	GOOD	
	Modification(s)	RIMS: SPORTS RIM			
3.	3. Conditions of Tyres				
		Size	Make	Balance (mm)	
	R/H Front Tyre	225/50R17	MICHELIN	6	
	L/H Front Tyre	225/50R17	MICHELIN	6	
	R/H Rear Tyre	225/50R17	MICHELIN	6	
	L/H Rear Tyre	225/50R17	MICHELIN	6	
4. Description of Damages					
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
DAMAGES SEE DETAILS.					
5.	General Information				
	Accident Date	Accident Date 29/10/2024 Inspection Date 05/11/2024 (11:25)			
	Survey held at	vey held at WE GARAGE - 1 KAKI BUKIT AVENUE 6 #02-11 AUTOBAY @ KAKI BUKIT SINGAPORE 417883			
5a.	Remarks				
A) THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b. Estimate Days of Repair					

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days