

# WE GARAGE

11 Kaki Bukit Avenue 6 #02-11 Autobay @ Kaki Bukit, Singapore 417883

wegarage@consultant.com

Mobile : +65 9009 6622

not Allowed  
4/5 H 5-100/  
whipha Arany  
5/11/24  
4 days

4 November 2024

REG NO. : SNF 3706 E

MAKE/MODEL : BMW 318i

## ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

| QTY | DESCRIPTION                                 | AMT(\$)                       |
|-----|---------------------------------------------|-------------------------------|
|     | <u>LIST ITEMS</u>                           |                               |
| 1   | Rear boot lid                               | \$ 12 1,879.90 X              |
| 2   | Rear boot hinges                            | \$ 17 274.72 X                |
| 2   | Rear boot lamps                             | \$ n/s cre 780.00 12 C 390    |
| 1   | Rear boot lock                              | \$ 50 195.13 X                |
| 1   | Rear boot logo                              | \$ 12 51.84                   |
| 1   | Rear boot rubber                            | \$ 17 142.65 X                |
| 2   | Rear taillamps                              | \$ n/s cre 1,310.00 12 C 655  |
| 2   | Rear taillamp lower brackets                | \$ 17 163.00 X                |
| 1   | Rear end panel                              | \$ 22 992.00                  |
| 1   | Rear end panel inner garnish                | \$ 22 159.00                  |
| 1   | Rear bumper                                 | \$ cre 1,638.90 1255.00       |
| 1   | Rear bumper bracket <del>tom</del> 12 to 12 | \$ cre 225.00                 |
| 1   | Rear bumper lower spoiler                   | \$ 22 485.00 X                |
| 2   | Rear bumper reflectors                      | \$ o/s n/s cre 230.00 12 C 80 |
| 1   | Rear bumper reinforcement                   | \$ 32 589.78                  |
| 2   | Rear bumper PDC sensors                     | \$ n/s cre 403.52 12 C 185    |
| 2   | Rear bumper side retainers                  | \$ 17 276.00 X                |
| 1   | Rear bumper lower moulding                  | \$ 22 254.00 X                |
| 1   | Rear bumper undercover                      | \$ 17 189.30 X                |
| 1   | Open boot sensor                            | \$ cre 445.00 380             |
| 1   | Door keyless sensor                         | \$ 17 395.00 X                |
|     |                                             | \$ 11,079.74                  |
|     | Less 5%                                     | \$ 553.99                     |
|     |                                             | \$ 10,525.75                  |

### SPECIAL NETT ITEMS

|   |                          |                    |
|---|--------------------------|--------------------|
| 1 | Rear bumper clip (1 set) | \$ 22 80.00 30 s/w |
|   |                          | \$ 80.00           |

### LABOUR CHARGES

|   |                                                             |                 |
|---|-------------------------------------------------------------|-----------------|
| 1 | To remove, replaced damaged lamps and check up rear wiring. | \$ 80.00 20     |
| 2 | To remove and refit inner garnishes.                        | \$ 120.00 60    |
| 3 | To remove and refit rear reverse sensor.                    | \$ 150.00 30    |
| 4 | To transfer boot lid mechanism and wiring assembly.         | \$ 47 120.00 2  |
| 5 | To apply undercoating.                                      | \$ 200.00 30    |
| 6 | Panel beating.                                              | \$ 1,600.00 600 |
| 7 | To re-spray painting on the affected areas.                 | \$ 1,500.00 800 |
|   |                                                             | \$ 3,770.00     |

ENK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- To display damaged part(s) to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplemental survey must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

\$ 14,375.75

P-50 62-62  
52  
4809.49  
30  
1540  
6379.49