

IMPERIUM AUTOMOTIVE

25 Kaki Bukit Road 4 # 01-47 Synergy@KB, Singapore 417800

HP : 9748 9940 Shawn Tan

Email : shawn7530@hotmail.com

not Authorized

meras

4/11/24

2/5 \$4000

whphl. All exp

4 days

04 NOVEMBER 2024

Vehicle No: GX72H

Model : NISSAN CABSTAR

QTY	Nett Items	AMOUNT
1	Front Windscreen Glass	one \$1374.00 ✓
1	Front Windscreen Rubber	148.20 one \$197.20 ✓
1	Front Wiper Panel Garnish	2/very 437.20 ✓
1	Front Wiper Motor	600.00 Daye/2m \$712.80 ✓
2	Front Wiper Arm	160x2=320 one/sent \$490.40 ✓
1	Front Body Panel	R \$1583.70 X
2	Front Wiper Arm Cover	m.s \$57.20 ✓
2	Front Wiper Blade	56.10 o/s m.s \$112.20 1/2 C
2	Front Side Mirror	189.50 m/s m o/s 320 \$379.00 1/2 C
2	Front Side Mirror Stay	437.50 m/s m o/s but \$875.00 1/2 C
1	Front Side Mirror Round	Daye \$89.40 ✓
2	Front Side Mirror Stay Cover	one \$454.60 ✓
1	Front Side Mirror Round Stay Cover	m 2 \$109.80 X
		\$6872.50
Less 10%		\$687.25
		\$6185.25

Special Nett Items

1	Front Windscreen Sealant	nn	\$80.00 X
1	Front Grille Clip (1 set)	nn	\$50.00 X
1	Front Sticker "FLAMMABLE GAS"	nn	\$80.00 50 s/w
			\$210.00

Labour Charges

To check Wiring	\$80.00 30
To Remove & Refit Dashboard	\$500.00 200
To Remove & Refit Front Windscreen Glass	\$180.00 60
To Apply undercoating	nn \$150.00 X
Panel Beating	\$1500.00 520
To Respray painting on the affected areas	\$1200.00 400
	\$3610.00

Grand Total \$10,005.25

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P- 4164.5
102
3748.05
50
110
5008.05
226
4006.