



NOT Withheld
C/Pm @ 3850/-
Heavy After Paint
3d91

6457 1931
enquiry@sh-motor.com

WORKSHOP
160 Sin Ming Drive
#07-02 Sin Ming AutoCity
Singapore 575722

S&H Motor Pte Ltd
Co. Reg. No.: 198701322K
GST Reg. No.: M2-0076269-0

M/s Lonpac Insurance Bhd
100 Beach Road
#19-00 Shaw Tower
Singapore 189702

File No :
Date :

SH/2024/0158/TP
11/10/2024

Estimated cost of repair for vehicle no:

SNB7110T
SNB7110T

Toyota Noah

YR2073K

On

11/10/2024

Description

Quantity

List Price

Front bumper *985*
Front bumper center
Front bumper side retainer rh
Front bumper lower grille
Front bumper parking sensor
Front radiator grille assy *1194.90*
Front radiator grille "Toyota Logo" emblem
Headlamp *211* *3384.10*

1	<i>Brd SM</i>	1,381.80	<i>✓</i>
1	<i>S</i>	950.00	<i>X</i>
1	<i>S</i>	137.40	<i>X</i>
1	<i>S</i>	355.90	<i>X</i>
set	<i>S</i>	494.20	<i>X</i>
1	<i>my SM</i>	3,358.30	<i>✓</i>
1	<i>S</i>	91.80	<i>✓</i>
1	<i>my SM</i>	4,287.10	<i>✓</i>
	<i>S</i>	11,056.50	
	<i>S</i>	2,764.13	
	<i>S</i>	8,292.38	

LESS 25%

Special Nett

Front bumper clip
Radiator grille clip

set	<i>S</i>	40.00	<i>✓</i>
set	<i>S</i>	40.00	<i>✓</i>

Labour

To dismantle, replace, cut, weld, knock out dents to straighten accident damaged parts.
Remove & replace front bumper sensor & conduct distance safety setting
Wiring /bulb checking/focusing
To putty & spray paint accident damaged parts and adjacent panels

<i>S</i>	400.00	<i>2001</i>
<i>S</i>	80.00	<i>501</i>
<i>S</i>	40.00	<i>201</i>
<i>S</i>	500.00	<i>2201</i>
<i>S</i>	9,392.38	

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: