

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

TP Budget Direct.

Veron.

TAX INVOICE

KEE CHONG CHING
 BLK 106D PUNGGOL FIELD #08-500
 SINGAPORE 824106

Repair Code : CLM18444

Date in : 03/11/2024

Vehicle Num. : SLJ3560K

Model : HONDA HRV 1.5 DX CVT

Chassis/Eng# : JHMRU1810GX201217/L15B4531218

Contact : 91000582

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
AIR DUCT <i>new</i>	1	127.50	+ 127.50
AIRCON SUCTION HOSE <i>new</i>	1	225.00	+ 225.00
FRONT AIRCON CONDENSER <i>Dented</i>	1	769.00	✓ 769.00
FRONT AIRCON CONDENSER ALUMINIUM PIPE <i>new</i>	1	295.00	+ 295.00
FRONT AIRCON CONDENSER DISCHARGE PIPE <i>new</i>	1	285.00	+ 285.00
FRONT AIRCON FAN BLADE <i>new</i>	1	57.70	+ 57.70
FRONT AIRCON FAN COWLING <i>new</i>	1	125.00	+ 125.00
FRONT AIRCON FAN MOTOR <i>new</i>	1	295.00	+ 295.00
FRONT BONNET <i>Dented</i>	1	892.30	✓ 892.30
FRONT BONNET HINGES L/R <i>new</i>	2	48.50	+ 97.00
FRONT BONNET INNER RUBBER GUIDE STOPPER L/R <i>new</i>	2	23.80	+ 47.60
FRONT BONNET INNER SIDE MOULDING L/R <i>new</i>	2	37.50	+ 75.00
FRONT BONNET INNER TOP MOULDING <i>new</i>	1	33.00	+ 33.00
FRONT BONNET INSULATOR <i>new</i>	1	122.30	+ 122.30
FRONT BONNET MECHANISM LOCK <i>new</i>	1	95.00	+ 95.00
FRONT BUMPER <i>Dented</i>	1	927.50	✓ 927.50
FRONT BUMPER FOGLAMP BRACKET L/R <i>new</i>	2	49.00	✓ 98.00
FRONT BUMPER FOGLAMP GARNISH L/R <i>Dented</i>	2	45.00	✓ 90.00

745

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

KEE CHONG CHING
BLK 106D PUNGGOL FIELD #08-500
SINGAPORE 824106

Contact : 91000582

TAX INVOICE

Repair Code : CLM18444

Date in : 03/11/2024

Vehicle Num. : SLJ3560K

Model : HONDA HRV 1.5 DX CVT

Chassis/Eng# : JHMRU1810GX201217/L15B4531218

FRONT BUMPER FOGLAMP L/R	<i>cracked</i>	2	327.70	✓	655.40
FRONT BUMPER LOWER GRILLE	<i>Deled</i>	1	77.50	✓	77.50
FRONT BUMPER LOWER LID	<i>torn</i>	1	381.00	✓	381.00
FRONT BUMPER REINFORCEMENT	<i>Dented</i>	1	321.00	✓	321.00
FRONT BUMPER SIDE RETAINER L/R	<i>new</i>	2	20.60	+	41.20
FRONT BUMPER TOW HOOK COVER	<i>new</i>	1	17.10	+	17.10
FRONT FENDER ARCH GARNISH L/R	<i>hd cracked</i>	2	165.00	165	330.00
FRONT GRILLE	<i>cracked</i>	1	351.80	✓	351.80
FRONT GRILLE 'LOGO' EMBLEM	<i>me</i>	1	23.40	✓	23.40
FRONT GRILLE CENTER BRACKET	<i>cracked</i>	1	76.00	✓	76.00
FRONT GRILLE CHROME MOULDING	<i>cut</i>	1	130.00	✓	130.00
FRONT GRILLE OUTER COVER	<i>cracked</i>	1	421.00	✓	421.00
FRONT GRILLE TOP GARNISH	<i>cracked</i>	1	85.00	✓	85.00
FRONT HEADLAMP L/R	<i>cracked</i>	2	1784.50	✓	3,569.00
FRONT HEADLAMP LOWER BRACKET L/R	<i>cracked</i>	2	35.00	✓	70.00
FRONT HEADLAMP SIDE BRACKET L/R	<i>cracked</i>	2	35.00	✓	70.00
FRONT HORN	<i>me nec</i>	1	110.50	+	110.50
FRONT SUPPORT PANEL	<i>Buckled</i>	1	576.20	✓	576.20

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

KEE CHONG CHING
BLK 106D PUNGGOL FIELD #08-500
SINGAPORE 824106

Contact : 91000582

TAX INVOICE

Repair Code : CLM18444

Date in : 03/11/2024

Vehicle Num. : SLJ3560K

Model : HONDA HRV 1.5 DX CVT

Chassis/Eng# : JHMRU1810GX201217/L15B4531218

RADIATOR (AUTO) <i>Dented</i>	1	1376.60	✓	1,376.60
RADIATOR BOTTOM MOUNTING L/R <i>new</i>	2	14.50	+	29.00
RADIATOR FAN BLADE	1	57.70	+	57.70
RADIATOR FAN COWLING	1	125.00	+	125.00
RADIATOR FAN MOTOR	1	298.00	+	298.00
RADIATOR LOWER HOSE <i>new</i>	1	42.50	+	42.50
RADIATOR SIDE GUIDE L/R	2	31.60	+	63.20
RADIATOR TOP HOSE	1	32.20	+	32.20
RADIATOR TOP MOUNTING L/R <i>new</i>	2	10.50	+	21.00
REAR BUMPER <i>Dented</i>	1	463.70	✓	463.70
REAR BUMPER LOWER COVER <i>Dented</i>	1	250.00	✓	250.00
REAR BUMPER REFLECTOR L/R <i>cracked</i>	2	141.10	✓	282.20
REAR BUMPER SIDE L/R <i>Dented</i>	2	195.00	✓	390.00
REAR BUMPER SIDE RETAINER L/R <i>new</i>	2	23.00	+	46.00
REAR END PANEL <i>Dented</i>	1	415.60	✓	415.60
REAR END PANEL ANTENNA SENSOR <i>cracked</i>	1	60.10	✓	60.10
REAR END PANEL BUZZLE SENSOR <i>cracked</i>	1	85.20	✓	85.20
REAR END PANEL INNER TOP GARNISH <i>Dented</i>	1	98.00	✓	98.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

KEE CHONG CHING
 BLK 106D PUNGGOL FIELD #08-500
 SINGAPORE 824106

Contact : 91000582

TAX INVOICE

Repair Code : CLM18444

Date in : 03/11/2024

Vehicle Num. : SLJ3560K

Model : HONDA HRV 1.5 DX CVT

Chassis/Eng# : JHMRU1810GX201217/L15B4531218

REAR EXHAUST ALUMINIUM HEAT SHIELD <i>new</i>	1	55.00	+	55.00
REAR EXHAUST RUBBER MOUNTING <i>new</i>	2	16.50	+	33.00
REAR EXHAUST SILENCER BOX <i>Best</i>	1	517.70	✓	517.70
REAR EXHAUST SILENCER BOX GASKET <i>new</i>	1	48.30	+	48.30
REAR FENDER ARCH GARNISH L/R <i>RH cmlnd</i>	2	195.00	<i>195</i>	390.00
REAR FENDER INNER TRIM GARNISH L/R <i>Delnd</i>	2	295.00	✓	590.00
REAR FLOOR EDLC MODULE BATTERY (31719-T7A-003) <i>new</i>	1	1043.00	+	1,043.00
REAR FLOOR JACK PANEL <i>new</i>	1	95.00	+	95.00
REAR FLOOR PANEL <i>Revis</i>	1	662.20	+	662.20
REAR FLOOR PANEL COMPARTMENT SPONGE TRAY <i>cmlnd</i>	1	485.30	✓	485.30 <i>295</i>
REAR FLOOR PANEL INNER TOP BOARD COVER <i>Delnd</i>	1	430.30	✓	430.30 <i>315</i>
REAR TAILGATE <i>Delnd</i>	1	953.30	✓	953.30
REAR TAILGATE 'I-VTEC' EMBLEM <i>new</i>	1	60.00	✓	60.00
REAR TAILGATE 'VEZEL' EMBLEM <i>new</i>	1	56.20	✓	56.20
REAR TAILGATE DAMPER L/R <i>new</i>	2	180.00	+	360.00
REAR TAILGATE HINGES L/R <i>new</i>	2	50.00	+	100.00
REAR TAILGATE INNER PULL GARNISH <i>Delnd</i>	1	153.40	✓	153.40 <i>35</i>
REAR TAILGATE INNER TRIM GARNISH <i>cmlnd</i>	1	180.00	✓	180.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

KEE CHONG CHING
BLK 106D PUNGGOL FIELD #08-500
SINGAPORE 824106

Contact : 91000582

TAX INVOICE

Repair Code : CLM18444

Date in : 03/11/2024

Vehicle Num. : SLJ3560K

Model : HONDA HRV 1.5 DX CVT

Chassis/Eng# : JHMRU1810GX201217/L15B4531218

REAR TAILGATE MECHANISM LOCK <i>Done</i>	1	180.00	✓	180.00
REAR TAILGATE MECHANISM LOCK STRIKER <i>Ren</i>	1	27.50	+	27.50
REAR TAILGATE NUMBER PLATE LAMP L/R <i>Ren</i>	2	38.50	+	77.00
REAR TAILGATE OPENER BUTTON SENSOR <i>Ren</i>	1	175.50	+	175.50
REAR TAILGATE OUTER GARNISH <i>Completed</i>	1	220.00	✓	220.00
REAR TAILGATE OUTER GARNISH 'H' LOGO EMBLEM <i>Ren</i>	1	25.00	✓	25.00
REAR TAILGATE REFLECTOR BACK RUBBER GASKET L/R <i>Ren</i>	2	38.50	+	77.00
REAR TAILGATE REFLECTOR L/R <i>Completed</i>	2	413.20	✓	826.40
REAR TAILGATE RUBBER GUIDE STOPPER L/R <i>Ren</i>	2	18.50	+	37.00
REAR TAILGATE SIDE GARNISH L/R <i>Ren</i>	2	38.20	+	76.40
REAR TAILGATE WEATHER STRIP <i>1st</i>	1	96.80	✓	96.80
REAR TAILGATE WINDSCREEN INNER SEAL <i>Ren</i>	2	50.00	✓	100.00
REAR TAILGATE WINDSCREEN MOULDING <i>Ren</i>	2	50.00	✓	100.00
REAR TAILLAMP L/R <i>Completed</i>	2	474.60	✓	949.20
Subtotal before discount				25,279.50
Percentage discount 20%				5,055.90
Sub-total 1				20,223.60
FRONT ARCH GARNISH CLIPS L/R - SET <i>Ren</i>	2	30.00	20	60.00

18682.60

14946.08

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

KEE CHONG CHING
BLK 106D PUNGGOL FIELD #08-500
SINGAPORE 824106

Contact : 91000582

TAX INVOICE

Repair Code : CLM18444

Date in : 03/11/2024

Vehicle Num. : SLJ3560K

Model : HONDA HRV 1.5 DX CVT

Chassis/Eng# : JHMRU1810GX201217/L15B4531218

FRONT BUMPER CLIPS - SET <i>new</i>	1	50.00	30	50.00
FRONT GRILLE CLIPS - SET <i>new</i>	1	30.00	20	30.00
FRONT NUMBER PLATE <i>for</i>	1	25.00	+	25.00
FRONT NUMBER PLATE HOLDER <i>new</i>	1	50.00	+	50.00
RADIATOR COOLANT <i>new</i>	1	80.00	40	80.00
REAR BUMPER CLIPS - SET <i>new</i>	1	50.00	30	50.00
REAR BUMPER REVERSE SENSOR (4 EYES) - SET <i>new</i>	1	350.00	280	350.00
REAR FENDER ARCH GARNISH CLIPS L/R - SET <i>new</i>	2	30.00	20	60.00
REAR FENDER INNER TRIM GARNISH CLIPS L/R - SET <i>new</i>	2	30.00	✓	60.00
REAR NUMBER PLATE <i>for</i>	1	25.00	+	25.00
REAR NUMBER PLATE HOLDER <i>new</i>	1	50.00	+	50.00
REAR TAILGATE INNER TRIM GARNISH CLIPS - SET <i>new</i>	1	60.00	30	60.00
REAR TAILGATE OUTER GARNISH CLIPS - SET <i>new</i>	1	40.00	20	40.00
REAR TAILGATE WINDSCREEN SEALANT <i>new</i>	1	60.00	✓	60.00
REAR TAILLAMP CLIPS L/R - SET <i>new</i>	2	30.00	+	60.00
Subtotal before discount				1,110.00
Percentage discount 0%				0.00
Sub-total 2				1,110.00
Parts-total				21,333.60

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

KEE CHONG CHING
BLK 106D PUNGGOL FIELD #08-500
SINGAPORE 824106

Contact : 91000582

TAX INVOICE

Repair Code : CLM18444

Date in : 03/11/2024

Vehicle Num. : SLJ3560K

Model : HONDA HRV 1.5 DX CVT

Chassis/Eng# : JHMRU1810GX201217/L15B4531218

LABOUR

To remove, change air con parts, vacuums, refill air con gas.

To remove, reinstall electrical wiring harness, check lighting and resetting headlamp focussing. (to FR)

To reset system after repair works

To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.

To remove, reinstall tailgate windscreen

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

To re-spray painting on the rear bootlid, rear end panel, rear fender (L/R), spare tyre panel and rear bumper.

To re-spray painting on the front bonnet, front support panel, front fender (L/R) and front bumper.

To remove and change exhaust silencer box with pipe, re-align where necessary consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

To remove, reinstall tailgate mechanism and check for function

120 140.00

30 80.00

X 500.00

✓ 80.00

120 150.00

60 100.00

700 1,500.00

800 1,200.00

60 100.00

1400 2,800.00

100 180.00

60 80.00

3530

Labour Total


6,910.00

Parts & Labour Total

28,243.60

*** This is a computer-generated document which requires no signature.***

page 7



Adrian Lj
1/2 04/11/24.

12 Days

Total: 19086.08

1/2: 151K ✓
(Nett Value)