

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/III24110052/RMA3Q2
Date: 28/03/2025

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D23MFL0002582_01
Claimant Vehicle No : SNR5061E Insured Vehicle No : SLQ4872S
Date of Loss: 31/10/2024 Nature of Claim: TP Claim No: MFL2024D0012911

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SNR5061E
Make & Model: SKODA OCTAVIA, 999cc STYLE 1.0 TSI MHEV (A) Engine No: DLAY22569
Reg. Date: 21/06/2024 (Man. Year: 2024) Chassis No: TMBBP8NX9RY156867
Colour: Blue Odometer: 14519 km
Engine Capacity: 999 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R18 Rear Tyre Size: 225/45 R18
Front Left Side: Goodyear 6 mm Rear Left Side: Goodyear 6 mm
Front Right Side: Goodyear 6 mm Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	468.22	212.63	255.59	54.59
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,280.00	1,387.00	893.00	39.17
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,748.22	1,599.63	1,148.59	41.79
+ GST 9.00/9.00% (S\$)	247.34	143.97	103.37	41.79
Nett Amount (S\$)	2,995.56	1,743.60	1,251.96	41.79
+ Loss of Use (1.0 x S\$60.00/day) (S\$)		60.00		
+ Doc/Search Fee (S\$)		27.25		
Nett Liability (S\$)		1,830.85		

INSPECTION

Date of Assignment: 11/11/2024
Date Inspected: 11/11/2024 Inspected At: Volkswagen Group Singapore Pte Ltd (HQ)
247 ALEXANDRA ROAD
Singapore 159934
Estimated Period of Repair: 1.0 days

Adjuster: MOHD RASUL Manager: Daphne Lee Mooi Ngiuk

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 30 Dec 2024)
Parts:	143	SKODA OCTAVIA 999cc STYLE 1.0 TSI MHEV (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNR5061E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TRIM PLATE FOR DOOR HANDI RHR DOOR HANDLE (OUTER)	Cut	212.63 FS	*212.63 FS
2	1		*OUTER DOOR HANDLE WITH SE RHR DOOR HANDLE (INNER BLACK)	Serviceable	127.09 FS	*- FS
3	1		*BOW SUPPORT DOOR HANDLE	Serviceable	128.50 FS	*- FS
Total Parts (S\$)						468.22 212.63

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR	New	798.00	399.00
2	SPRAY PAINT	New	760.00	266.00
3	B&P CHECK SHORT CIRCUIT /HARNESS REPAIR	New	266.00	266.00
4	B&P DIAGNOSIS AND PROGRAMMING	New	456.00	456.00
Gross Labour Cost (\$\$)			2,280.00	1,387.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >