

CHIA AUTO SERVICES PTE LTD

23 Kaki Bukit Avenue 4 #04-01 Vicom Inspection Centre Singapore 415933

Tel: 6243 1373

Reg. No: 201538764H

Email: CA3SERVICES@GMAIL.COM

ATTENTION:	MOTOR CLAIMS DEPARTMENT
DATE:	26-07-24
CLAIM TYPE:	T/P CLAIM
TO:	SOMPO
VEHICLE DETAILS	
VEHICLE NO:	GBC6331R
MAKE & MODEL:	TOYOTA DYNA
CHASSIS NO:	
ACCIDENT DETAILS	
DATE:	21 June, 2024
TIME:	1400HRS
THIRD PARTY REQUESTOR:	JACK LI

CLAIM DETAILS: PARTS

S/N:	DESCRIPTION	QTY:	UNIT LIST PRICE	TOTAL LIST PRICE
1	TAILGATE <i>Dented</i>	1	\$ 1,688.20	\$ 1,688.20
2	TAILGATE HINGE <i>Ken</i>	4	\$ 155.30	\$ 621.20
3	TAILGATE SIDE LOCK <i>Ken</i>	1	\$ 290.00	\$ 290.00
4	TAILGATE STOPPER <i>Ken</i>	1	\$ 68.20	\$ 68.20
5	TAILGATE STOPPER BRACKET <i>Best</i>	1	\$ 198.50	\$ 198.50
6	TAILLAMP <i>cracked</i>	1	\$ 280.00	\$ 280.00
7	TAILLAMP BRACKET <i>Best</i>	1	\$ 170.00	\$ 170.00
8	SIDE PANEL <i>Repair</i>	1	\$ 2,550.00	\$ 2,550.00
9	END PANEL <i>Repair Dented</i>	1	\$ 820.60	\$ 820.60
10	EXHAUST PIPE <i>Ken</i>	1	\$ 910.00	\$ 910.00

TOTAL PRICE \$ 7,596.70

LESS 25% \$ 1,899.18

SUB TOTAL PRICE \$ 5,697.53

SPECIAL NETT ITEMS

S/N:	DESCRIPTION	QTY:	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR NUMBER PLATE <i>Best</i>	1	\$ 50.00	\$ 50.00
2	REAR NUMBER PLATE HOLDER <i>Best</i>	1	\$ 150.00	\$ 150.00
3	TAILGATE 70KM/H <i>NW</i>	1	\$ 30.00	\$ 30.00
4	TAILGATE COMAPNY STICKER <i>NW</i>	1	\$ 250.00	\$ 250.00
5	TAILGATE DYNA STICKER <i>NW</i>	1	\$ 55.00	\$ 55.00

6	REVERSE SENSOR <i>2nd</i>	1	\$ 200.00	\$ 200.00
7	REVERSE SENSOR BRACKET <i>2nd</i>	1	\$ 150.00	\$ 150.00
TOTAL			\$ 885.00	

50
6.8

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	1	\$ 1,200.00	\$ 1,200.00
2	TO SPRAY PAINT AFFECTED AREA	1	\$ 1,200.00	\$ 1,200.00
3	TUFF COAT	1	\$ 200.00	\$ 200.00
4	WIRING CHECK	1	\$ 80.00	\$ 80.00
5	REMOVE AND REFIX TAILGATE ALUMINIUM	1	\$ 150.00	\$ 150.00
6	REMOVE AND REFIX SIDEGATE ALUMINIUM	1	\$ 150.00	\$ 150.00
7	REMOVE AND REFIX REAR EXHAUST PIPE	1	\$ 150.00	\$ 150.00
8	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	1	\$ 100.00	\$ 100.00

500
500
40
30
40
40
40
50

TOTAL \$ 3,230.00

1260

ESTIMATE REPORT

TOTAL PARTS COST	\$	6,582.53
TOTAL LABOUR COST	\$	3,230.00
TOTAL REPAIR COST	\$	9,812.53

APPROVED DETAILS:

SURVEYOR:

CONTACT NO.:

PART BY PART/LUMP SUM

NO. OF DAYS

Adnan C
h/s 26/06/24.

04 Days.

2277.53
+ 615.00
= 2892.53
4152.53
830.00
- 20%
3322.53

Lump sum 8330.00 + 4045.