2/11/25, 11:08 AM Adjuster Report

### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/III24110053/EPA3Q2

Date: 11/02/2025

**REFERENCE** 

Handling Insurer: India International Insurance Pte Ltd Policy No: D24MFL0008848

**Claimant Vehicle** SBS3200X Insured Vehicle No: PD1064Z

No:

Date of Loss: 22/10/2024 Nature of Claim: ΤP Claim No: MFL2024D0012547

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: **SBS3200X** 

VOLVO B9TL, 9.4 D AUTO TURBO ABS (A) Make & Model: Engine No: D9190646

Reg. Date: 30/08/2012 (Man. Year: 2012) Chassis No: YV3S4P920CA157294

Colour: Multi-colour Odometer: 612895 km

**Engine Capacity:** 9364 cc Market Value/New Car N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Pre-accident Condition: Yes Engine Modification: No Handbrake (Serviceable):

**CONDITION OF TYRES** 

Front Tyre Size: 275/70 R22.5 Rear Tyre Size: 275/70 R22.5 Front Left Side: Rear Left Side: Bridgestone 5 mm Bridgestone 5 mm Front Right Side: Bridgestone 5 mm Rear Right Side: Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,582.72	1,725.99	4,856.73	73.78
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,798.00	2,176.00	622.00	22.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$	9,380.72	3,901.99	5,478.73	58.40
Approved Total (Overridden) (S\$	)	3,550.00		
(S\$	9,380.72	3,550.00	5,830.72	62.16
+ GST 9.00/9.00% (S\$	844.26	319.50	524.76	62.16
Nett Amount (S\$	10,224.98	3,869.50	6,355.48	62.16
+ Loss of Use (4.0)	x S\$300.00/day) (S\$)	1,200.00		
+1	Doc/Search Fee (S\$)	2.18		
	Nett Liability (S\$)	5,071.68		

**INSPECTION** 

Date Inspected:

Date of Assignment: 04/11/2024

Strides Premier Automotive Services Pte. Ltd.

(Woodlands) 04/11/2024 Inspected At:

60 Woodlands Industrial Park E4

Singapore 757705

Estimated Period of Repair: 3.0 days

Adjuster: **CHEN TSUE YEE** Manager: CHEW HSIAO TONG NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

### REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 09 Jan 2025)

Parts: N/A VOLVO B9TL 9.4 D AUTO TURBO ABS (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SBS3200X)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

#### **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*DOME FRONT LOWER CLASS 2 FOR VOLVO B9TL	Repair	3,391.95 F	*- FL
2	1		*N/S CORNER DEFLECTOR	Not Necessary	328.33 F	*- FL
3	1		*FRT N/S LIGHT BEZEL	Missing	298.28 F	*298.28 FL
4	1		*PRIMER (SIKA 206 G+P)	Necessary	80.00 FS	*80.00 FS
5	3		*SEALANT SIKAFLEX	Necessary	111.00 FS	*111.00 FS
6	1		*ACTIVATOR	Necessary	80.00 FS	*80.00 FS
7	1		*MILLENN N/S 1/4 GLASS	Broken	165.88 F	*165.88 FL
8	1		*N/S CORNER BUMPER	Repair	974.78 F	*- FL
9	1		*3RD MIRROR BLIND	Missing	232.50 F	*232.50 FL
10	1		*MIRROR VIEW 2 GLASS	Missing	270.00 F	*270.00 FL
11	1		*MIRROR EXTERIOR LONG ARM	Missing	650.00 F	*650.00 FL
F=Fra	inchise	part. S=SpcN	Nett. L=ListItemDisc.	Sub Total (S\$)	6,582.72	1,887.66
			- List Item Discount on L Items	0.00/10.00% (S\$)	0.00	161.67
				Total Parts (S\$)	6,582.72	1,725.99
			Report was unsubmitted during this print-	out.		

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount				
Lab	Labour Items							
1	TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS	New	1,590.00	1,060.00				
2	PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	New	708.00	616.00				
3	TOWING CHARGE	New	500.00	500.00				
	Gross Labour Cost (S\$)		2,798.00	2,176.00				
	Report was unsubmitted during this print-out.							

< END OF ESTIMATES >