


ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: SMM 3302L
 at Workshop m/s PERFORMANCE
 of ALEXANDRA 27
 Insured: 111
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: 81K
 IDAC Accident Rpt: Consistent? : Yes or No
 GIA / PR Seen: Consistent? : Yes or No
 Est. Repairs: days Res.: Yes or No
 Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SMM 3302L Yr Regn: 2019 Jcw
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or

Make: B.M.W 216 I ACTIVE TOURER c.c. 1499
 Colour: BLUE AC: Insured / Std / NI / NA
 Sp. Reading: 61869 T/Radio: Insured / Std / NI / NA
 Eng/No: _____

C/No: WBA 2X92010 7D95464Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: NI / S/Rim / STD A/Rim or

Tyre Size: F: 205/35R17
 R: _____

BS / DUN / EXNOVA / GY / FS / LZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front Rear
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. 29/10/24 D.O.I. 25/11/24

Survey held at ALEXANDRADes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

REPAIR LMTI-43K

Date/Time, File Path to?

☐ : Preli. Report☐ : Final Report

Date/Time, File Path to?

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

S+RS \$

Photos

Others

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$

TOTAL

Report Format:

Lump Sum / L&L (\$

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x
Toll-Free Number (1800-2255269)



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

→ India

ESTIMATE

1 Nov 2024

Estimate No. : b1 71669
Date Estimated : 01/11/2024
Prepared By : Jack Ng Guo Ming

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -
Cheong Yuet Chuen, Mary
5 Phoenix Garden

- ACCOUNT - 40000
Cash Sales - Service
Singapore

Singapore 668273

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMM3302L	WBA2X920107D95464	26/06/2019	216i Active Tourer	59706

DESCRIPTION

To replace front bumper, rear bumper, all damage attachment and make good tailgate

1700 4,250.00

To respray rear bumper, front bumper and tailgate

2076 2,961.00

To check electrical wiring system and lighting at the rear section for proper function.

177.00

To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct check for proper function.

177.00

To replace left headlight.

? 481.00

To replace right headlight.

? 481.00

To supply front emboss number plate.

83.00

Sundries.

150.00

Total Labour 1: 8,760.00

DESCRIPTION	QTY	PRIC	VALUE
FRT CROSSLINK ?	1	182.80	182.80
FRT LH TOP DEFORMATION ELEMENT ?	1	104.15	104.15
FRT RH TOP DEFORMATION ELEMENT ?	1	104.15	104.15
FRT BUMPER TOP CARRIER ?	1	420.15	420.15
LH FINISHER ?	1	55.45	55.45
RH FINISHER ?	1	55.45	55.45
IMPACT ABSORBER TOP	1	64.00	64.00
FRT BUMPER PANEL PRIMED (BASIS) repair	1	987.80	987.80
LH GRID LATERAL (LINES/PDC) ?	1	102.35	102.35
RH GRID LATERAL (LINES/PDC) ?	1	102.35	102.35
RR BUMPER LH SIDE GUIDE	1	172.60	172.60
RR BUMPER RH SIDE GUIDE ?	1	184.95	184.95

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x
Toll-Free Number (1800-2255269)



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Page No. : 2 of 5

Estimate No. : b1 71669
Date Estimated : 01/11/2024
Prepared By : Jack Ng Guo Ming

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMM3302L	WBA2X920107D95464	26/06/2019	216i Active Tourer	59706

DESCRIPTION	QTY	PRIC	VALUE
REAR BUMPER CARRIER ?	1	525.75	525.75
RR BUMPER LH INNER SIDE GUIDE ?	1	172.60	172.60
RR BUMPER RH INNER SIDE GUIDE ?	1	172.60	172.60
REAR BUMPER TRIM STRIP (BLACK) <i>sd</i>	1	108.45	108.45
REAR BUMPER PANEL PRIMED (LINES PDC <i>de</i>	1	1,132.45	1,132.45
FRT LH GRILLE ?	1	125.55	125.55
FRT RH GRILLE ?	1	167.45	167.45
FRONT PANEL V STRUT ?	1	135.90	135.90
AIR DUCT ?	1	562.10	562.10
LH HEADLIGHT LED TECHNOLOGY ?	1	2,503.55	2,503.55
RH HEADLIGHT LED TECHNOLOGY ?	1	2,503.55	2,503.55

Total Parts : 10,646.15

Claims OD / <u>3rd Party</u> / Uninsured losses / Direct Settlement	
Regn No. _____	Claim No. _____
Date & Time <u>25/11/24</u>	Excess S\$ _____
Surveyor's Name <u>Ram</u>	Sign _____
Surveyor's Tel _____	Authorised Yes / No _____
Authorised Date _____	Time _____
RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No	
Surveyor's E-mail _____	
No. of Working Days Recommend <u>5 days</u>	

Reg 68 part

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____



Labour 1	:	8,760.00
Parts	:	10,646.15
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 9%	:	1,746.55
Grand Total	:	21,152.70

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	125F
Vehicle Details	
Vehicle No.:	SMM3302L
Vehicle to be Exported:	No
Intended Deregistration Date:	26 Nov 2024
Vehicle Make:	B.M.W.
Vehicle Model:	216I ACTIVE TOURER
Primary Colour:	Blue
Manufacturing Year:	2019
Engine No.:	39175663B38A15A
Chassis No.:	WBA2X920107D95464
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$29,927.00
Original Registration Date:	26 Jun 2019
First Registration Date:	26 Jun 2019
Transfer Count:	1
Actual ARF Paid:	\$33,898.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	25 Jun 2029
PARF Rebate Amount:	\$23,728.00
Intended COE Rebate Details	
COE Expiry Date:	25 Jun 2029
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$30,009.00
COE Rebate Amount:	\$13,752.00
Total Rebate Amount:	\$37,480.00
Message	
You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.	

The information contained herein is correct as at 26 Nov 2024

OK



BMW 2 Series 216i Active Tourer

\$81,888 Instalment \$1,200/mth

PREMIUM AD

Shortlist

Get Warranty

Loan Calculator



Overview Financial Photo Research

Depreciation	\$14,180 / year
Reg. Date	25-Jun-2019 (4yrs 6mths 29days COE left)
Manufactured	2019
Mileage	91,000 km (16.8k / year)
Transmission	Auto
Engine Cap	1,499 cc
Road Tax	\$684 / year
Power	80.0 kW (107 bhp) View specs of the BMW 2 Series Active Tourer (2014-2021)
Curb Weight	1,380 kg
COE	\$30,009
OMV	\$29,931
ARF	\$33,904
Dereg Value	\$37,471 as of today
No. of Owners	3