

GST REG. NO : M2 - 0020081 - X

→ India

E S T I M A T E

1 Nov 2024

Estimate No. : b1 71669
Date Estimated : 01/11/2024
Prepared By : Jack Ng Guo Ming

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -
Cheong Yuet Chuen, Mary
5 Phoenix Garden

- ACCOUNT - 40000
Cash Sales - Service
Singapore

Singapore 668273

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMM3302L	WBA2X920107D95464	26/06/2019	216i Active Tourer	59706

DESCRIPTION

To replace front bumper, rear bumper, all damage attachment and make good tailgate

2550 1700 4,250.00

To respray rear bumper, front bumper and tailgate

2076 2,961.00

To check electrical wiring system and lighting at the rear section for proper function.

295 177.00

To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct check for proper function.

177.00

To replace left headlight.

X117? 481.00

To replace right headlight.

X117? 481.00

To supply front emboss number plate.

83.00

Sundries.

80 150.00

Total Labour 1: 8,760.00

DESCRIPTION	QTY	PRIC	VALUE
FRT CROSSLINK ? X SUC	1	182.80	182.80
FRT LH TOP DEFORMATION ELEMENT ? X SUC	1	104.15	104.15
FRT RH TOP DEFORMATION ELEMENT ? X SUC	1	104.15	104.15
FRT BUMPER TOP CARRIER ? X SUC	1	420.15	420.15
LH FINISHER ? X SUC	1	55.45	55.45
RH FINISHER ? X SUC	1	55.45	55.45
IMPACT ABSORBER TOP ? X SUC	1	64.00	64.00
FRT BUMPER PANEL PRIMED (BASIS) ? X SUC	1	987.80	987.80
LH GRID LATERAL (LINES/PDC) ? X SUC	1	102.35	102.35
RH GRID LATERAL (LINES/PDC) ? X SUC	1	102.35	102.35
RR BUMPER LH SIDE GUIDE ? X SUC	1	172.60	172.60
RR BUMPER RH SIDE GUIDE ? X SUC	1	184.95	184.95

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 71669
Date Estimated : 01/11/2024
Prepared By : Jack Ng Guo Ming

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMM3302L	WBA2X920107D95464	26/06/2019	216i Active Tourer	59706

DESCRIPTION	QTY	PRIC	VALUE
REAR BUMPER CARRIER <i>? xsa</i>	1	525.75	525.75
RR BUMPER LH INNER SIDE GUIDE <i>? xsa</i>	1	172.60	172.60
RR BUMPER RH INNER SIDE GUIDE <i>? xsa</i>	1	172.60	172.60
REAR BUMPER TRIM STRIP (BLACK) <i>sd</i>	1	108.45	108.45
REAR BUMPER PANEL PRIMED (LINES PDC) <i>de</i>	1	1,132.45	1,132.45
FRT LH GRILLE <i>? xsa</i>	1	125.55	125.55
FRT RH GRILLE <i>? xsa</i>	1	167.45	167.45
FRONT PANEL V STRUT <i>? xsa</i>	1	135.90	135.90
AIR DUCT <i>? ca</i>	1	562.10	562.10
LH HEADLIGHT LED TECHNOLOGY <i>? xsa</i>	1	2,503.55	2,503.55
RH HEADLIGHT LED TECHNOLOGY <i>? xsa</i>	1	2,503.55	2,503.55

Total Parts : 10,646.15

Claims OD / 3rd Party Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time 25/11/24 Excess S\$ _____

Surveyor's Name Ramul Sign _____

Surveyor's Tel _____ Authorised Yes / No _____

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No

Surveyor's E-mail _____

No. of Working Days Recommend 5 days

25/11/24

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____



Labour 1	:	8,760.00
Parts	:	10,646.15
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 9%	:	1,746.55
Grand Total	:	21,152.70

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **
** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **



Supplementary Report

Estimate No. : b1 71669
Date Estimated : 01/11/2024
Prepared By : Jack Ng Guo Ming

Page No. :

- ESTIMATE REPAIR FOR -
Cheong Yuet Chuen, Mary
5 Phoenix Garden

- ACCOUNT - 219
India Int'L Insurance Pte Ltd
64 Cecil Street
#04-05 IOB Building
Singapore 049711

Singapore 668273

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	M LEAGE
SMM3302L	WBA2X920107D95464	26/06/2019	216i Active Tourer	61868

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
** To replace front bumper panel, rear bumper, front air duct, top impact absorber, rear trim strip include carrying out other necessary repairs caused by the accident	2,550.00		2,550.00
* To check electrical wiring system and lightings at the front and rear sections for proper function	295.00		295.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
-------------	------------	-----	---------	------

SUPPLEMENTARY ITEMS

Total Labour : 2,845.00
Total Parts :