

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CD/III24110055/EMA3Q2**Date:** 05/03/2025**REFERENCE**

Handling Insurer: India International Insurance Pte Ltd Policy No: D24MFL0004893  
**Claimant Vehicle No :** SLA2379Y **Insured Vehicle No :** GBH8482Z  
 Date of Loss: 26/10/2024 Nature of Claim: TP Claim No: MFL2024D0013124

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SLA2379Y**  
 Make & Model: AUDI A4, 1.4 TFSI S TRONIC (A) Engine No: CVN001412  
 Reg. Date: 24/02/2016 (Man. Year: 2015) Chassis No: WAUZZZF43GA012639  
 Colour: Grey Odometer: 181842 km  
 Engine Capacity: 1395 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 225/50 R17 Rear Tyre Size: 225/50 R17  
 Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm  
 Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	9,129.00	5,230.30	3,898.70	42.71
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,630.00	2,280.00	3,350.00	59.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>14,759.00</b>	<b>7,510.30</b>	<b>7,248.70</b>	<b>49.11</b>
<b>+ GST 9.00/9.00% (S\$)</b>	1,328.31	675.93	652.38	49.11
<b>Nett Amount (S\$)</b>	<b>16,087.31</b>	<b>8,186.23</b>	<b>7,901.08</b>	<b>49.11</b>
<b>+ Loss of Use (3.0 x S\$60.00/day) (S\$)</b>		180.00		
<b>+ Doc/Search Fee (S\$)</b>		27.25		
<b>Nett Liability (S\$)</b>		<b>8,393.48</b>		

**INSPECTION**

Date of Assignment: 01/11/2024  
 Date Inspected: 01/11/2024 Inspected At: Premium Automobiles Pte Ltd (HQ)  
 55 UBI ROAD 1  
 Singapore 408699  
 Estimated Period of Repair: 3.0 days

**Adjuster:** CHEN TSUE YEE**Manager:** Daphne Lee Mooi Ngiuk

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 Jan 2025)
Parts:	143	AUDI A4 1.4 TFSI S TRONIC (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLA2379Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR RH	Dented	3,647.00 FS	*3,647.00 FS
2	1		*FRONT DOOR OUTER SEAL RH	Necessary	275.00 FS	*275.00 FS
3	1		*FRONT DOOR CATCH RH	Loose	131.00 FS	*130.50 FS
4	1		*FRONT DOOR ATTACHMENT PARTS RH	Not Necessary	1,179.00 FS	*- FS
5	1		*FRONT WING MIRROR MOUNTING RH	Broken	1,113.00 FS	*1,113.00 FS
6	1		*FRONT WING MIRROR CAP -RH	Not Necessary	346.00 FS	*- FS
7	1		*FRONT WING MIRROR GLASS RH	Not Necessary	1,938.00 FS	*- FS
8	1		*SUNDRIES	Necessary	500.00 FS	*64.80 FS
F=Franchise part. S=SpcNett.						
Total Parts (\$\$)					9,129.00	5,230.30

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO DISMANTLE AND RENEW RHS FRONT DOOR.TO REPAIR RHS SILL PANEL RE-ORGANIZE CRASH MANAGEMENT COMPONENTS .REINSTALL ALL PARTS REMOVED	New	2,250.00	900.00
2	TO RESPRAY RHS FRONT DOOR ,RHS SILL PANEL ,RHS WING MIRROR COVER AND RHS FRONT DOOR HANDLE	New	2,900.00	900.00
3	TO CARRY OUT DIAGNOSTIC CHECK	New	480.00	480.00
<b>Gross Labour Cost (\$\$)</b>			<b>5,630.00</b>	<b>2,280.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >