

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0830/2024/KS
DATE : 1-Nov-24
WIP : 36563

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 1/11/2024

YOUR INSURED VEH NO : GBH 8482 Z

India International Insurance Pte Ltd

6 Raffles Quay

#22-00

Singapore 048580

Attn: Motor Claims Dept

OWNER'S NAME : MR MAXIMUS TJOA @CHUA XIAN KANG
ADDRESS : 108 LORONG H TELOK KURAU
SINGAPORE 426134

TELEPHONE : HP +65 92986522
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 7240045346
VEHICLE NO : **SLA 2379 Y**
MODEL CODE : AUDI A4 SEDAN 1.4 TFSI S
MODEL YEAR : 24/2/2016
ENGINE NO : CVN 001412
CHASSIS NO : WAUZZZF43GA012639
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 26-Oct-24
PLACE OF ACCIDENT : 6 MARINE VISTA, SINGAPORE 449030
NEPTUNE COURT 6 MARINE VISTA

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLA 2379 Y

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO DISMANTLE AND RENEW RHS FRONT DOOR. TO REPAIR RHS SILL PANEL. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 2,250.00	
2	TO RESPRAY RHS FRONT DOOR, RHS SILL PANEL, RHS WING MIRROR COVER AND RHS FRONT DOOR HANDLE.	\$ 2,900.00	
3	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 480.00	
TOTAL LABOUR CHARGES		: \$ 5,630.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLA 2379 Y

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT DOOR - RH	1	\$ 3,647.00	
2	FRONT DOOR OUTER SEAL - RH	1	\$ 275.00	
3	FRONT DOOR CATCH - RH	1	\$ 131.00	
4	FRONT DOOR ATTACHMENT PARTS - RH	1	\$ 1,179.00	
5	FRONT WING MIRROR MOUNTING - RH	1	\$ 1,113.00	
6	FRONT WING MIRROR CAP - RH	1	\$ 346.00	
7	FRONT WING MIRROR GLASS - RH	1	\$ 1,938.00	
8	SUNDRIES		\$ 500.00	
TOTAL SPARE PARTS		:	\$ 9,129.00	
TOTAL LABOUR CHARGES		:	\$ 5,630.00	
GRAND TOTAL		:	\$ 14,759.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT