

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/III24110056/TMA3Q2  
Date: 18/06/2025

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D23MFL0002582\_01  
Claimant Vehicle No : SGL8569C Insured Vehicle No : SLP1251J  
Date of Loss: 28/10/2024 Nature of Claim: TP Claim No: MFL2024D0012965

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SGL8569C  
Make & Model: PEUGEOT E-2008GT, (A) Engine No: HIDDEN  
Reg. Date: 18/08/2023 (Man. Year: 2023) Chassis No: VR3UKZKSZPJ607905  
Colour: Red Odometer: 16580 km  
Engine Capacity: 0 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/55 R18 Rear Tyre Size: 215/55 R18  
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm  
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,940.50	785.00	1,155.50	59.55
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,200.00	1,375.00	825.00	37.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,140.50	2,160.00	1,980.50	47.83
+ GST 9.00/9.00% (S\$)	372.65	194.40	178.25	47.83
Nett Amount (S\$)	4,513.15	2,354.40	2,158.75	47.83
+ Car Rental (3.0 x S\$100.00/day + 9.00% GST) (S\$)		327.00		
+ Doc/Search Fee (S\$)		27.25		
Nett Liability (S\$)		2,708.65		

INSPECTION

Date of Assignment: 09/12/2024  
Date Inspected: 09/12/2024 Inspected At: Vantage Automotive Limited (Alexandra)  
305 Alexandra Road #02-01, Vantage Automotive Centre  
Singapore 159942  
Estimated Period of Repair: 3.0 days

Adjuster: MOHD TAUFIKH BIN HAMID Manager: Daphne Lee Mooi Ngiuk

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 May 2025)
Parts:	M1-SUV	PEUGEOT E-2008GT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGL8569C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	100.00 FS	*20.00 FS
2	1		*REAR BUMPER	Deformed	594.00 FS	*594.00 FS
3	1		*REAR BUMPER SKIRT	Not Necessary	234.00 FS	*- FS
4	1		*RR BUMPER MOULDING	Cut	171.00 FS	*171.00 FS
5	1		*RR BUMPER BRACKET CENTRAL	Not Necessary	121.50 FS	*- FS
6	1		*RR BUMPER REINFORCEMENT	Not Necessary	720.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	1,940.50	785.00
-------------------	----------	--------

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE & REPLACE REAR BUMPER ,REAR REINFORCEMENT	New	1,250.00	600.00
2	TO REMOVE & REFIT PARTS FOR REAR BUMPER REPLACEMENT	New	350.00	175.00
3	TO CONDUCT ECU RE-PROGRAMMING AND CLEAR OF FAULT CODES TO ENSURE PROPER FUNCTION	New	600.00	600.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,200.00</b>	<b>1,375.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >