

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/III24110057/APA3Q2**Date:** 06/01/2025**REFERENCE**

Handling Insurer: India International Insurance Pte Ltd Policy No: D20MFL0006372_03
Claimant Vehicle No : SMQ1282C **Insured Vehicle No :** SHD2598M
Date of Loss: 25/10/2024 Nature of Claim: TP Claim No: MFL2024D0012690

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMQ1282C**
Make & Model: TOYOTA C-HR HYBRID, 1.8 S CVT (A) Engine No: 2ZR2D34790
Reg. Date: 30/10/2019 (Man. Year: 2019) Chassis No: ZYX102172899
Colour: Green Odometer: 130139 km
Engine Capacity: 1797 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R17 Rear Tyre Size: 215/60 R17
Front Left Side: AutoGreen 6 mm Rear Left Side: AutoGreen 6 mm
Front Right Side: AutoGreen 6 mm Rear Right Side: AutoGreen 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,583.47	1,555.95	6,027.52	79.48
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,360.00	460.00	1,900.00	80.51
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,943.47	2,015.95	7,927.52	79.73
Approved Total (Overridden) (S\$)		1,600.00		
Nett Amount (S\$)	9,943.47	1,600.00	8,343.47	83.91
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 01/11/2024
Date Inspected: 01/11/2024 Inspected At: SM SPRAY PAINTING (HQ)
NO. 25 KAKI BUKIT ROAD 4 #08-30 SYNERGY @ KAKI BUKIT
Singapore 417800
Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 06 Jan 2025)
Parts:	M1-SUV	TOYOTA C-HR HYBRID 1.8 S CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMQ1282C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR LH	Dented	1,928.60 FL	*1,928.60 FL
2	1		*REAR DOOR LOWER GARNISH LH	Not Necessary	290.40 FL	*- FL
3	1		*REAR DOOR WEATHERSTRIP LH	Not Necessary	210.90 FL	*- FL
4	1		*REAR DOOR TRIM LH	Not Necessary	1,852.20 FL	*- FL
5	1		*REAR WINDOW LOWER MOULDING LH	Not Necessary	128.40 FL	*- FL
6	2		*REAR DOOR BLACK TAPE LH	Necessary	106.00 FL	*106.00 FL
7	1		*REAR DOOR LOCK LH	Not Necessary	727.30 FL	*- FL
8	1		*REAR LH DOOR HINGE TOP	*Check	137.10 FL	*- FL
9	1		*REAR LH DOOR HINGE BOTTOM	*Check	137.10 FL	*- FL
10	1		*REAR FENDER LH	Not Necessary	1,592.70 FL	*- FL
11	1		*REAR WHEEL ARCH LH	Not Necessary	203.30 FL	*- FL
12	1		*FRONT DOOR LH	Not Necessary	2,071.20 FL	*- FL
13	1		*FRONT LH DOOR HINGE TOP	Not Necessary	135.40 FL	*- FL
14	1		*FRONT LH DOOR HINGE BOTTOM	Not Necessary	135.40 FL	*- FL
15	1		*FRONT DOOR BLACK TAPE LH NO.1	Not Necessary	60.40 FL	*- FL
16	1		*FRONT DOOR BLACK TAPE LH NO.2	Not Necessary	30.40 FL	*- FL
17	1		*FRONT DOOR BLACK TAPE LH NO.3	Not Necessary	124.50 FL	*- FL
18	1		*SET DOOR RUBBER RIVET	*Check	90.00 FS	*- FS
19	1		*SET DOOR TRIM CLIPS	Necessary	90.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,051.30	2,064.60
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,467.83	508.65
Total Parts (\$\$)	7,583.47	1,555.95

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE REPAIR AND REPLACE PARTS FOR THE AFFECTED AREAS	New	1,000.00	200.00
2	PUTTY BLEND AND SPRAY PAINT	New	900.00	200.00
3	REMOVE AND REINSTALL DOOR WINDOW GLASS TO FACILITATE REPAIR	New	100.00	60.00
4	DISMANTLE AND TRANSFER DOOR	New	360.00	0.00
Gross Labour Cost (\$\$)			2,360.00	460.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >