

ASSIGNMENT

From: _____ Date: _____
 Estn: _____
 OD / TP RES / OD RES / EVA / INV / MV
 To in _____ Vehicle NO: _____
 at _____
 of _____
 Insured: _____
 Policy No: _____
 Claim No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Vehicle: _____
 (Policy Condition)

Remark: Vehicle had commenced its
 repair at the time of inspection.

Bal. or Market Value: _____
 IDAC Accident Report: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SMQ1282C Yr Regn: 2019, Oct.
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota CHR C.D. 1797

Colour: Green A/C: Insured / Std / NI / NA

Sp. Reading: 130139 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: 27X102172899

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / SRim / STD A/Rim or

Tyre Size: F: 215/60R17

R: 215/60R17

ES / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Auto Green

Front

Rear

R/Bal. 06 mm

R/Bal. 06 mm

L/Bal. 06 mm

L/Bal. 06 mm

D.O.A.

D.O.A. 01/11/24

Survey held at

SM Spmy Paints

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction
7 PM (PRS)

COE Expiry: _____

Estimate given during: Yes ()
 1st Survey: No ()

MV:

PV:

Nett:

Date/Time, File Pass to?

☐ : Prel. Report

1) _____
 Date/Time, File Return to?

☐ : Final Report

2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Addl Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invt (\$)

Photos

Others

Report Format: _____

Report Form: _____

ESTIMATE REPORT

ATTN: MOTOR CLAIMS DEPT

VRN
MODEL

SMQ1282C
TOYOTA CHR

PARTS REPLACEMENT	Qty	S\$ Unit	S\$ Amt
1 REAR DOOR LH <i>Dented</i>	1	\$ 1,928.60	\$ 1,928.60 <i>✓</i>
2 REAR DOOR LOWER GARNISH LH <i>new</i>	1	\$ 290.40	\$ 290.40 <i>+</i>
3 REAR DOOR WEATHERSTRIP LH <i>new</i>	1	\$ 210.90	\$ 210.90 <i>+</i>
4 REAR DOOR TRIM LH <i>new</i>	1	\$ 1,852.20	\$ 1,852.20 <i>+</i>
5 REAR WINDOW LOWER MOULDING LH <i>new</i>	1	\$ 128.40	\$ 128.40 <i>+</i>
6 REAR DOOR BLACK TAPE LH <i>new</i>	2	\$ 53.00	\$ 106.00 <i>✓</i>
7 REAR DOOR LOCK LH <i>new</i>	1	\$ 727.30	\$ 727.30 <i>+</i>
8 REAR LH DOOR HINGE TOP <i>?</i>	1	\$ 137.10	\$ 137.10 <i>?</i>
9 REAR LH DOOR HINGE BOTTOM <i>?</i>	1	\$ 137.10	\$ 137.10 <i>?</i>
10 REAR FENDER LH <i>new</i>	1	\$ 1,592.70	\$ 1,592.70 <i>+</i>
11 REAR WHEEL ARCH LH <i>new</i>	1	\$ 203.30	\$ 203.30 <i>+</i>
12 FRONT DOOR LH <i>?</i>	1	\$ 2,071.20	\$ 2,071.20 <i>+</i>
13 FRONT LH DOOR HINGE TOP <i>?</i>	1	\$ 135.40	\$ 135.40 <i>+</i>
14 FRONT LH DOOR HINGE BOTTOM <i>?</i>	1	\$ 135.40	\$ 135.40 <i>+</i>
15 FRONT DOOR BLACK TAPE LH NO.1 <i>new</i>	1	\$ 60.40	\$ 60.40 <i>+</i>
16 FRONT DOOR BLACK TAPE LH NO.2	1	\$ 30.40	\$ 30.40 <i>+</i>
17 FRONT DOOR BLACK TAPE LH NO.3	1	\$ 124.50	\$ 124.50 <i>+</i>

\$ 9,871.30

All List -25%

\$ 2,467.83

\$ 7,403.48

Special Nett

1 DOOR RUBBER RIVET (SET) <i>?</i>	1	\$ 90.00	\$ 90.00 <i>?</i>
2 DOOR TRIM CLIPS (SET) <i>new</i>	1	\$ 90.00	\$ 90.00 <i>30</i>

\$ 180.00

PARTS TOTAL \$ 7,583.48

Labour Charges

1 Remove, repair and replace parts for the effected areas.	\$ 1,000.00 <i>200</i>
2 Putty, Blend And Spray Paint.	\$ 900.00 <i>200</i>
3 Remove and reinstall Door window glass to facilitate repair.	\$ 100.00 <i>60</i>
4 Dismantle and transfer Door.	\$ 360.00 <i>+</i>

LABOURS TOTAL \$ 2,360.00

Grand Total : \$ 9,943.48
Add 9% GST : \$ 894.91
Nett Total : \$ 10,838.39

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

No. of repair days: 6

Acknowledged by Repairer

Signature:

Date:

Adrian Wong.
H/S 01/11/24.
03 Days
#96893735.