



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no : 6631 1188



TOYOTA

Ulc

ESTIMATE

Account Details			Account No.		Customer Details		
India International Insurance P L 64 Cecil Street #06-02 IOB Building Singapore 049711 Attn: Motor Claims Dept			S1000006 / ICIII		Mr Ho Wee How (He Weihao) 1037 Serangoon Road #07-10 Singapore 328170 Mobile: 97334926		
			Document No. 0				
			Document Date 04/11/2024				
Year	Model	Variant	Reg Date	Reg No.	Kilometers	Wip No.	Order No. / Remarks
2022	MXPJ10R	BHXNBQ A2	27/07/2023	SNL6750A	0	34493	72/DS/SNL6750A
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
JTDKBB3601002586		M15AY491610	60	Thomas Pang W T	--/--/----		0.00 --/--/---- 0.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
1	Z	BP-SUNDRY-AI TP INS INDIA INTERNATIONAL PTE LTD TP VEH GBA5368C DATE OF ACC 04 11 2024				50	100.00
2	Z	BP-SLANT SUPPLY SEALANT (NETT)					✓ 100.00
3	B	BP-LAB2 DRILL HOLE AND INSTALL REVERSE SENSOR					✓ 198.00
4	B	BP-LAB2 CHECK WIRING SYSTEM					✓ 134.64
5	B	BP-LAB2 REMOVE AND TRANSFER TAILGATE COMPONENTS ONTO NEW TAILGATE R/R REAR REVERSE CAMERA TO FAC REPAIR.					✓ 594.00
6	B	BP-WS2 REPLACE REAR TAILGATE GLASS					✓ 594.00
7	S	BP-SUBLET SUPPLY SOLAR FILM					✓ 480.00
8	B	BP-LAB2 REMOVE INTERIOR UPHOLSTERY TO FAC REPAIR					? 792.00
9	B	BP-ECU2 TO RESET ECU AND REPROGRAMME					✓ 198.00
10	B	BP-MECH2 TO CONDUCT ADJUSTMENT ON BLIND SPOT SENS OR					✓ 198.00
11	B	BP-LAB2 REPLACE ACC DAMAGED PARTS					1584 2376.00
12	B	BP-RES2 RESPRAY ACC AFFECTED AREAS					1312 1968.00
13	S	PSP PER PANE LABOUR FOR PLATINUM SHINEPRO & SHINE PER PANEL APPLICATION					✓ 183.18

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- Legal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Stipulated by Repairer

For & on behalf of Borneo Motors (Singapore) Pte Ltd	Customer's Signature	Charge Summary	Total Tayfikh 97495749 WP' 09/12/24 @ 230pm R/P Resurvey before paint Tayfikh e lkhanto.com Less 05 days. Amount Due
	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details			Account No.		Customer Details			
India International Insurance P L 64 Cecil Street #06-02 IOB Building Singapore 049711 Attn: Motor Claims Dept			S1000006 / ICIII1		Mr Ho Wee How (He Weihao) 1037 Serangoon Road #07-10 Singapore 328170 Mobile: 97334926			
			Document No. 0					
			Document Date 04/11/2024					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2022	MXPJ10R	BHXNBQ A2	27/07/2023	SNL6750A	0	34493	72/DS/SNL6750A	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
JTDKBB3601002586		M15AY491610	60	Thomas Pang W T	--/--/----		0.00 --/--/---- 0.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
14	1	T52159-5C906 COVER, RR BUMPER			1.00	444.00		unt / 444.00
15	2	T52453-52902 GUARD, RR BUMPER,			1.00	766.70		bt / 766.70
16	3	T67005-52E03 PANEL SUB-ASSY, BACK			1.00	2175.40		bt / 2175.40
17	4	T68105-52770 GLASS SUB-ASSY, BACK			1.00	1644.20	photo	rel / 1644.20
18	5	T64813-K2020 DAM, BACK WINDOW			1.00	28.30		rel / 28.30
19	6	T21000-20 SIKA 182010 SIKA TACK GO! (BLA			2.00	108.00		rel / 216.00
20	7	T21000-22 SIKA 207. G+P ADHESIVE PRIMER			1.00	200.00		rel / 200.00
21	8	T75442-52550 PLATE, BACK DOOR			1.00	56.70		rel / 56.70
22	9	T75442-52560 PLATE, LUGGAGE COMPT			1.00	56.70		rel / 56.70
23	0	T75441-52270 PLATE, LUGGAGE COMPT			1.00	63.20		rel / 63.20
24	1	T89348-K0231 RETAINER, ULTRASONIC			4.00	55.20		? 220.80
25	2	L89348-58130 CLIP, ULTRASONIC			2.00	16.60		? 33.20
26	3	T89341-K0060 CO SENSOR, ULTRASONIC,			2.00	503.90		? 1007.80
27	4	T89997-30100 ANTENNA, ELECTRICAL			1.00	100.00		? 100.00
28	5	S52161-0K040 PIECE, RR BUMPER			10.00	5.80		rel / 58.00
For & on behalf of			Customer's Signature		Charge Summary		Total	
Borneo Motors (Singapore) Pte Ltd							14,986.82	
			Please acknowledge receipt of vehicle				GST 9.00%	
					Parts 7,071.00		1,348.81	
					Labour 7,252.64			
					Sublet 663.18			
					Lubrication/Fluid 0.00		Less 0.00	
					Others 0.00		Amount Due 16,335.63	

Customer Copy