



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details			Account No.		Customer Details		
India International Insurance P L 64 Cecil Street #06-02 IOB Building Singapore 049711 Attn: Motor Claims Dept			S1000006 / ICIII1		Mr Ho Wee How (He Weihao) 1037 Serangoon Road #07-10 Singapore 328170 Mobile: 97334926		
			Document No.				
			0				
			Document Date				
			04/11/2024				

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2022	MXPJ10R	BHXNBQ A2	27/07/2023	SNL6750A	0	34493	72/DS/SNL6750A

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTDKBAB3601002586	M15AY491610	60	Thomas Pang W T	--/--/----	0.00 --/--/----

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY-AI TP INS:INDIA INTERNATIONAL PTE LTD TP VEH:GBA5368C DATE OF ACC:04.11.2024				100.00
2	Z	BP-SLANT SUPPLY SEALANT (NETT)				100.00
3	B	BP-LAB2 DRILL HOLE AND INSTALL REVERSE SENSOR				198.00
4	B	BP-LAB2 CHECK WIRING SYSTEM				134.64
5	B	BP-LAB2 REMOVE AND TRANSFER TAILGATE COMPONENTS ONTO NEW TAILGATE. R/I REAR REVERSE CAMERA TO FAC REPAIR.				594.00
6	B	BP-WS2 REPLACE REAR TAILGATE GLASS				594.00
7	S	BP-SUBLET SUPPLY SOLAR FILM				480.00
8	B	BP-LAB2 REMOVE INTERIOR UPHOLSTERY TO FAC REPAIR				792.00
9	B	BP-ECU2 TO RESET ECU AND REPROGRAMME				198.00
10	B	BP-MECH2 TO CONDUCT ADJUSTMENT ON BLIND SPOT SENS OR				198.00
11	B	BP-LAB2 REPLACE ACC DAMAGED PARTS				2376.00
12	B	BP-RES2 RESPRAY ACC AFFECTED AREAS				1968.00
13	S	PSP PER PANE LABOUR FOR PLATINUM SHINEPRO & SHINE PER PANEL APPLICATION				183.18

For & on behalf of Borneo Motors (Singapore) Pte Ltd	Customer's Signature	Charge Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less Amount Due

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details	Account No.	Customer Details
India International Insurance P L 64 Cecil Street #06-02 IOB Building Singapore 049711 Attn: Motor Claims Dept	S1000006 / ICIII1	Mr Ho Wee How (He Weihao) 1037 Serangoon Road #07-10 Singapore 328170 Mobile: 97334926
	Document No. 0	
	Document Date 04/11/2024	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2022	MXPJ10R	BHXNBQ A2	27/07/2023	SNL6750A	0	34493	72/DS/SNL6750A

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTDKBAB3601002586	M15AY491610	60	Thomas Pang W T	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
14	1	T52159-5C906 COVER, RR BUMPER	1.00	444.00		444.00
15	2	T52453-52902 GUARD, RR BUMPER,	1.00	766.70		766.70
16	3	T67005-52E03 PANEL SUB-ASSY, BACK	1.00	2175.40		2175.40
17	4	T68105-52770 GLASS SUB-ASSY, BACK	1.00	1644.20		1644.20
18	5	T64813-K2020 DAM, BACK WINDOW	1.00	28.30		28.30
19	6	T21000-20 SIKA 182010 SIKA TACK GO! (BLA	2.00	108.00		216.00
20	7	T21000-22 SIKA 207. G+P ADHESIVE PRIMER	1.00	200.00		200.00
21	8	T75442-52550 PLATE, BACK DOOR	1.00	56.70		56.70
22	9	T75442-52560 PLATE, LUGGAGE COMPT	1.00	56.70		56.70
23	0	T75441-52270 PLATE, LUGGAGE COMPT	1.00	63.20		63.20
24	1	T89348-K0231 RETAINER, ULTRASONIC	4.00	55.20		220.80
25	2	L89348-58130 CLIP, ULTRASONIC	2.00	16.60		33.20
26	3	T89341-K0060 C0 SENSOR, ULTRASONIC,	2.00	503.90		1007.80
27	4	T89997-30100 ANTENNA, ELECTRICAL	1.00	100.00		100.00
28	5	S52161-0K040 PIECE, RR BUMPER	10.00	5.80		58.00

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd			14,986.82
	Please acknowledge receipt of vehicle		GST 9.00% 1,348.81
		Parts 7,071.00	
		Labour 7,252.64	
		Sublet 663.18	
		Lubrication/Fluid 0.00	Less 0.00
		Others 0.00	Amount Due 16,335.63

Customer Copy