

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

GBF4070R
TP/LONPAC

M/S : LONPAC INSURANCE BERHAD
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

TEL: 62507388

ATTN: Motor Claim Department

FAX: 62963767

WS Ref: TP/LONPAC

Claim Type: Third Party

Accident Date: 24/10/2024

TP Veh Reg No: GBE1107U

Estimate No:

Date:

Policy No:

Veh Reg No:

Make/Model:

ES2401013/YISHUN

06 Dec 2024

8-V0014278-MVA-R007

GBF4070R

TOYOTA TOYOTA DYNA
150 M

Chassis No:

Engine No:

Reg. Date:

JTFAT35Y20K206895

1KD2643384

18/10/2016

Estimate Repair Cost to Vehicle No :GBF4070R

PAGE:1/1

Description	U/Price	Quantity	List Price S\$	Amount S\$
List Price				
1 REAR TAILGATE	1,703.60	1 PC	1,703.60	✓
2 TAILGATE STICKER - TOYOTA	330.10	1 PC	330.10	✓
3 TAILGATE LH SIDE LOCK HANDLE	160.50	1 PC	160.50	✓
4 TAILGATE STICKER 'DYNA'	39.10	1 PC	39.10	✓
5 TAILGATE LH HINGE	49.90	1 PC	49.90	✓
6 LH TAILLAMP	357.10	1 PC	357.10	✓
7 LH TAILLAMP PANEL	61.70	1 PC	61.70	✓
			2,702.00	
		Less 25%	675.50	2,026.50
Special Net				
8 STICKER 70KM/HR	10.00	1 PC	10.00	✓
9 STICKER 13 PAX	10.00	1 PC	10.00	✓
10 REAR LH CORNAL STOPPER	18.00	1 PC	18.00	✓
11 TAILGATE INNER PROTECTOR	340.00	1 PC	340.00	✓
12 REAR CENTRE STEP TRAY	200.00	1 PC	200.00	✓
13 REVERSE SENSOR	200.00	1 SET	200.00	✓
			778.00	778.00
Labour				
14 TO REMOVE & REFIX TAILGATE, TAILLAMPS, TO KNOCKING & REPAIR TAILGATE LOWER MEMBER, LH SIDE GATE LOWER PANEL, CABIN REAR LH PILLAR, REAR FLOORBOARD & REALIGN REAR TRUCK POSITION	1,200.00	1 LA	1,200.00	900
15 PUTTY & RESPRAY ON TAILGATE, LH SIDE GATE, LH SIDE LOWER MEMBER, TAILGATE LOWER MEMBER, REAR TRUCK LH CORNAL PILLAR & CABIN REAR LH PILLAR & ALL AFFECTED AREAS	1,100.00	1 LA	1,100.00	800
16 TO REWRITE ADVERTISEMENT	200.00	1 LA	200.00	100
			2,500.00	2,500.00
			Total	S\$ 5,304.50
			Add GST @ 9%	477.41
			Total Amount Payable	S\$ 5,781.91

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE