

WHEELZ 4 YOU

Not Auland
me
Mora
11/06/24

2/5 \$ 4300
Abg hie the rpg
5 days.

To: Motor Claims Department

Date: 16/04/2024

Vehicle No: GBG3144M

Model: NISSAN NV200

Estimated Repair Cost For GBG3144M NISSAN NV200

QTY	Parts	Amount
1	Rear bumper	698.20 \$ 787.55 ✓
2	Rear bumper side retainer @ \$48.50	\$ 97.00 X
2	Rear bumper reflector @ \$85	\$ 170.00 X
1	Rear bumper sponge	103.20 \$ 155.00 ✓
1	Tailgate	\$ 1,991.00 ✓
1	Tailgate lock	\$ 375.10 X
1	Tailgate rubber	198.40 \$ 263.10 ✓
1	Tailgate logo	\$ 94.00 X
1	Tailgate NV200 emblem	\$ 94.00 ✓
1	Tailgate vanette emblem	\$ 94.00 ✓
1	Tailgate outer garnish	\$ 260.90 X
1	Tailgate trimboard	\$ 285.05 ✓
2	tailgate hinge @\$95	\$ 190.00 X
2	Rear number plate lamp @\$48.15	\$ 96.30 X
2	Taillamp @\$787.55	\$ 1,575.10 X
1	Rear end panel garnish	\$ 133.92 X
1	Rear end panel inner	\$ 1,685.00 X
1	Rear end panel outer	282.40 \$ 654.50 ✓
1	Rear floor panel	\$ 1,216.34 X
Parts Sum:		\$ 10,217.86
Parts Less 10% :		\$ 1,021.79
Parts Total:		\$ 9,196.07

Special Nett Items

1	Tailgate glass sealant	1.00 \$ 60.00 40
1	Tailgate glass inner seal	\$ 60.00 X
1	Tailgate sealant	\$ 100.00 X
1	Rear floor panel board	\$ 600.00 X
1	Reverse sensor	\$ 280.00 200
1	Reverse camera	\$ 450.00 300
1	Rear storage cabinet	\$ 2,800.00 X
1	70km sticker	\$ 25.00 10
1	3pax sticker	\$ 25.00 10
1	Tailgate sticker	\$ 120.00 X
1	Rear number plate	\$ 80.00 X
1	Rear bumper clips	\$ 50.00 30
1	Rear bumper rivets	\$ 50.00 X
1	Tailgate trim board clip	\$ 80.00 30
Special Nett Items Total:		\$ 4,780.00

Labour & Misc Charges

Description	Amount
To Check Wiring	\$ 50.00 20
To Install Reverse Sensor	\$ 80.00 30
To dismantle cabinet, remove/refit trims and garnishes	\$ 380.00 50
To transfer tailgate parts	\$ 150.00 50
To transfer tailgate glass	\$ 150.00 120
To repair exhaust	\$ 180.00 X
To install reverse camera	\$ 150.00 30
To apply Body Sealant On Body Joints	\$ 120.00 X
Anti-rust	\$ 120.00 30
Labour to remove necc parts, cut and reweld panel, repair chasiss	\$ 1,200.00 600
Spray painting	\$ 1,200.00 500
Labour Charges Total:	\$ 3,780.00

Parts Total:	\$ 9,196.07
Special Nett Items Total:	\$ 4,780.00
Labour Charges Total:	\$ 3,780.00
Total Cost Of Repair:	\$ 17,756.07
(Non-Inclusive of GST)	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

P-3746.25
102
3371.63
620
1430
5471.63
202
4337