

# WHEELZ 4 YOU

Nof Holland  
nr  
Mora  
11/06/24

2/5 \$ 4300  
de 2 hte 1 hte 1 hte  
4 days.

To: Motor Claims Department

Date: 16/04/2024

Vehicle No: GBG3144M

Model: NISSAN NV200

## Estimated Repair Cost For GBG3144M NISSAN NV200

| QTY                 | Parts                                         | Amount             |
|---------------------|-----------------------------------------------|--------------------|
| 1                   | Rear bumper <i>to 120</i>                     | \$ 787.55 ✓        |
| 2                   | Rear bumper side retainer @ \$48.50 <i>11</i> | \$ 97.00 X         |
| 2                   | Rear bumper reflector @ \$85 <i>NF</i>        | \$ 170.00 X        |
| 1                   | Rear bumper sponge <i>to 120</i>              | \$ 155.00 ✓        |
| 1                   | Tailgate <i>to 120</i>                        | \$ 1,991.00 ✓      |
| 1                   | Tailgate lock <i>su</i>                       | \$ 375.10 X        |
| 1                   | Tailgate rubber <i>1W1</i>                    | \$ 263.10 ✓        |
| 1                   | Tailgate logo <i>su</i>                       | \$ 94.00 X         |
| 1                   | Tailgate NV200 emblem <i>nu</i>               | \$ 94.00 ✓         |
| 1                   | Tailgate vanette emblem <i>nu</i>             | \$ 94.00 ✓         |
| 1                   | Tailgate outer garnish <i>11</i>              | \$ 260.90 X        |
| 1                   | Tailgate trimboard <i>11</i>                  | \$ 285.05 ✓        |
| 2                   | tailgate hinge @\$95 <i>11</i>                | \$ 190.00 X        |
| 2                   | Rear number plate lamp @\$48.15 <i>11</i>     | \$ 96.30 X         |
| 2                   | Taillamp @\$787.55 <i>11</i>                  | \$ 1,575.10 X      |
| 1                   | Rear end panel garnish <i>su</i>              | \$ 133.92 X        |
| 1                   | Rear end panel inner <i>11</i>                | \$ 1,685.00 X      |
| 1                   | Rear end panel outer <i>to 120</i>            | \$ 654.50 ✓        |
| 1                   | Rear floor panel <i>11</i>                    | \$ 1,216.34 X      |
| Parts Sum:          |                                               | \$ 10,217.86       |
| Parts Less 10% :    |                                               | \$ 1,021.79        |
| <b>Parts Total:</b> |                                               | <b>\$ 9,196.07</b> |

### Special Nett Items

|                                  |                                         |                    |
|----------------------------------|-----------------------------------------|--------------------|
| 1                                | Tailgate glass sealant <i>11</i>        | \$ 60.00 40        |
| 1                                | Tailgate glass inner seal <i>11</i>     | \$ 60.00 X         |
| 1                                | Tailgate sealant <i>11</i>              | \$ 100.00 X        |
| 1                                | Rear floor panel board <i>11</i>        | \$ 600.00 X        |
| 1                                | Reverse sensor <i>malfunction / 120</i> | \$ 280.00 200      |
| 1                                | Reverse camera <i>malfunction</i>       | \$ 450.00 300      |
| 1                                | Rear storage cabinet <i>11</i>          | \$ 2,800.00 X      |
| 1                                | 70km sticker <i>11</i>                  | \$ 25.00 10        |
| 1                                | 3pax sticker <i>11</i>                  | \$ 25.00 10        |
| 1                                | Tailgate sticker <i>11</i>              | \$ 120.00 X        |
| 1                                | Rear number plate <i>su</i>             | \$ 80.00 X         |
| 1                                | Rear bumper clips <i>11</i>             | \$ 50.00 30        |
| 1                                | Rear bumper rivets <i>11</i>            | \$ 50.00 X         |
| 1                                | Tailgate trim board clip <i>11</i>      | \$ 80.00 30        |
| <b>Special Nett Items Total:</b> |                                         | <b>\$ 4,780.00</b> |

### Labour & Misc Charges

| Description                                                       | Amount             |
|-------------------------------------------------------------------|--------------------|
| To Check Wiring                                                   | \$ 50.00 20        |
| To Install Reverse Sensor                                         | \$ 80.00 30        |
| To dismantle cabinet, remove/refit trims and garnishes            | \$ 380.00 50       |
| To transfer tailgate parts                                        | \$ 150.00 50       |
| To transfer tailgate glass                                        | \$ 150.00 120      |
| To repair exhaust                                                 | \$ 180.00 X        |
| To install reverse camera                                         | \$ 150.00 30       |
| To apply Body Sealant On Body Joints                              | \$ 120.00 X        |
| Anti-rust                                                         | \$ 120.00 30       |
| Labour to remove necc parts, cut and reweld panel, repair chasiss | \$ 1,200.00 600    |
| Spray painting                                                    | \$ 1,200.00 500    |
| <b>Labour Charges Total:</b>                                      | <b>\$ 3,780.00</b> |

|                                  |                     |
|----------------------------------|---------------------|
| <b>Parts Total:</b>              | <b>\$ 9,196.07</b>  |
| <b>Special Nett Items Total:</b> | <b>\$ 4,780.00</b>  |
| <b>Labour Charges Total:</b>     | <b>\$ 3,780.00</b>  |
| <b>Total Cost Of Repair:</b>     | <b>\$ 17,756.07</b> |
| <b>(Non-Inclusive of GST)</b>    |                     |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

P-3746.28  
02  
3371.63  
620  
1430  
5471.63  
202  
4337