

WHEELZ 4 YOU

Not Aired
 ne
 Mount
 11/06/24
 2/5 # 4300
 1 day weather upon
 5 days.

To: Motor Claims Department

Date: 16/04/2024

Vehicle No: GBG3144M

Model: NISSAN NV200

Estimated Repair Cost For GBG3144M NISSAN NV200

QTY	Parts	Amount	Nett Item
1	Rear bumper	698.20	\$ 787.55 ✓
2	Rear bumper side retainer @ \$48.50		\$ 97.00 X
2	Rear bumper reflector @ \$85		\$ 170.00 X
1	Rear bumper sponge		\$ 155.00 ✓
1	Tailgate	103.20	\$ 1,991.00 ✓
1	Tailgate lock		\$ 375.10 X
1	Tailgate rubber	198.40	\$ 263.10 ✓
1	Tailgate logo		\$ 94.00 X
1	Tailgate NV200 emblem		\$ 94.00 ✓
1	Tailgate vanette emblem		\$ 94.00 ✓
1	Tailgate outer garnish		\$ 260.90 X
1	Tailgate trimboard		\$ 285.05 ✓
2	tailgate hinge @\$95		\$ 190.00 X
2	Rear number plate lamp @\$48.15		\$ 96.30 X
2	Taillamp @\$787.55		\$ 1,575.10 X
1	Rear end panel garnish		\$ 133.92 X
1	Rear end panel inner		\$ 1,685.00 X
1	Rear end panel outer	282.40	\$ 654.50 ✓
1	Rear floor panel		\$ 1,216.34 X
Parts Sum:		\$	10,217.86
Parts Less 10% :		\$	1,021.79
Parts Total:		\$	9,196.07

Special Nett Items

1	Tailgate glass sealant	1.11	\$ 60.00 40
1	Tailgate glass inner seal	1.11	\$ 60.00 X
1	Tailgate sealant	1.11	\$ 100.00 X
1	Rear floor panel board	1.11	\$ 600.00 X
1	Reverse sensor	malfunction / torn	\$ 280.00 200
1	Reverse camera	malfunction	\$ 450.00 300
1	Rear storage cabinet	1.11	\$ 2,800.00 X
1	70km sticker	1.11	\$ 25.00 10
1	3pax sticker	1.11	\$ 25.00 10
1	Tailgate sticker	1.11	\$ 120.00 X
1	Rear number plate	1.11	\$ 80.00 X
1	Rear bumper clips	1.11	\$ 50.00 30
1	Rear bumper rivets	1.11	\$ 50.00 X
1	Tailgate trim board clip	1.11	\$ 80.00 30
Special Nett Items Total:		\$	4,780.00

Labour & Misc Charges

Description	Amount
To Check Wiring	\$ 50.00 20
To Install Reverse Sensor	\$ 80.00 30
To dismantle cabinet, remove/refit trims and garnishes	\$ 380.00 50
To transfer tailgate parts	\$ 150.00 50
To transfer tailgate glass	\$ 150.00 120
To repair exhaust	\$ 180.00 X
To install reverse camera	\$ 150.00 30
To apply Body Sealant On Body Joints	\$ 120.00 X
Anti-rust	\$ 120.00 30
Labour to remove necc parts, cut and reweld panel, repair chasiss	\$ 1,200.00 600
Spray painting	\$ 1,200.00 500
Labour Charges Total:	\$ 3,780.00

Parts Total: \$ 9,196.07
Special Nett Items Total: \$ 4,780.00
Labour Charges Total: \$ 3,780.00
Total Cost Of Repair: \$ 17,756.07
(Non-Inclusive of GST)

LKK Auto Consultants hence notify
 the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

P-3746.25
 102
 3371.63
 620
 1430
 5471.63
 202
 4351