

CS/SMO24060250/Aqh3

ASSIGNMENT

From: _____ Date: _____

Estim: _____

OD / TP / TP RES / OD RES / EVA / INV / MVTo in Vehicle No: _____at W/O in/s _____

of _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Vek: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repair: 3 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: Smu874E Yr Regn: 2020 JulyType: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Lexus ES250 C.D. 2487Colour: White A/C: Insured / Std / NI / NASp. Reading: 51803 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTHB11B1802026396Gen. Cond: Good / Fair / Poor / BurntSteering: Order / Jammed / Leaked / Burnt orBrake: Order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 235/45R18R: 235/45R18BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front _____ Rear _____

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 26/06/24Survey held at Chia AutoDes. of Damages: Frt / Rear O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time _____ Action / Instruction _____

TP Sampo

COE Expiry: _____

finalised with Ms Hong LS \$2700, 3 days (Red \$9735.88, 78%)

Estimate given during: Yes (✓)

1st Survey: No ()

MV: 155KPV: 574KNett: 976K

Date/Time, File Pass to?

1) 15/08 Typist

Date/Time, File Return to?

2) _____

Report Format:

TPDays Of Repair: 3Resurvey No. of Trip: 2

Addl Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Inve (\$

Survey Fee:

Transportation:

3 + PS \$1

Photos

Others

CHIA AUTO SERVICES PTE LTD

23 Kaki Bukit Avenue 4 #04-01 Vicom Inspection Centre Singapore 415933

Tel: 6744 4986

Reg. No: 201538764H

Email: CA3SERVICES@GMAIL.COM

ATTENTION:	MOTOR CLAIMS DEPARTMENT
DATE:	25-06-26
CLAIM TYPE:	T/P CLAIM
TO:	SOMPO
VEHICLE DETAILS	
VEHICLE NO:	SMU874E
MAKE & MODEL:	TOYOTA LEXUS ES250
CHASSIS NO:	
ACCIDENT DETAILS	
DATE:	25 June, 2024
TIME:	0910HRS
THIRD PARTY REQUESTOR:	JACK LI

CLAIM DETAILS: PARTS

S/N:	DESCRIPTION	QTY:	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR DOOR RH <i>Repair</i>	1	\$ 1,688.50	\$ 1,688.50
2	REAR FENDER <i>Repair</i>	1	\$ 1,655.80	\$ 1,655.80
3	REAR FENDER INNER COWLING <i>3/4</i>	1	\$ 280.00	\$ 280.00
4	REAR WINDSCREEN MOULDING <i>1/2</i>	1	\$ 190.00	\$ 190.00
5	REAR BUMPER <i>Repair</i>	1	\$ 1,620.20	\$ 1,620.20
6	REAR BUMPER SIDE RETAINER <i>new</i>	1	\$ 120.00	\$ 120.00
7	REAR SHOCK ABSORBER <i>new</i>	1	\$ 320.00	\$ 320.00
8	REAR KNUCKLE ARM <i>new</i>	1	\$ 620.00	\$ 620.00
9	REAR UPPER ARM <i>Not a Best</i>	1	\$ 450.00	\$ 450.00
10	REAR LOWER ARM <i>Best</i>	1	\$ 410.00	\$ 410.00
11	REAR TRAILING ARM <i>new</i>	1	\$ 520.00	\$ 520.00
12	REAR WHEEL BEARING <i>Regrd</i>	1	\$ 720.00	\$ 720.00

TOTAL PRICE \$ 8,594.50

LESS 25% \$ 2,148.63

SUB TOTAL PRICE \$ 6,445.88

SPECIAL NETT ITEMS

S/N:	DESCRIPTION	QTY:	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER CLIPS(SET) <i>new</i>	1	\$ 20.00	\$ 20.00
2	REAR FENDER INNER COWLING CLIPS(SET) <i>new</i>	1	\$ 20.00	\$ 20.00
3	REAR WINDSCREEN SEALANT <i>new</i>	1	\$ 120.00	\$ 120.00

4	WHEEL RIM <i>cut</i>	1	\$ 1,200.00	\$ 1,200.00	680
5	WHEEL RIM GAS PIN <i>Best</i>	1	\$ 100.00	\$ 100.00	50
6	CERMAIC COATING	1	\$ 1,000.00	\$ 1,000.00	600
			TOTAL	\$ 2,460.00	

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	1	\$ 1,400.00	\$ 1,400.00	300
2	TO SPRAY PAINT AFFECTED AREA	1	\$ 1,000.00	\$ 1,000.00	600
3	TUFF COAT	1	\$ 200.00	\$ 200.00	30
4	WIRING CHECK	1	\$ 80.00	\$ 80.00	+
5	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	1	\$ 280.00	\$ 280.00	+
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	1	\$ 100.00	\$ 100.00	+
7	REMOVE AND REFIX REVERSE REAR UNDERCARRIAGE	1	\$ 350.00	\$ 350.00	180
8	FOUR WHEEL ALIGNMENT	1	\$ 120.00	\$ 120.00	80
			TOTAL	\$ 3,530.00	

ESTIMATE REPORT

TOTAL PARTS COST	\$	8,905.88
TOTAL LABOUR COST	\$	3,530.00
TOTAL REPAIR COST	\$	12,435.88

APPROVED DETAILS:

SURVEYOR:
CONTACT NO.:
PART BY PART/LUMP SUM
NO. OF DAYS

Adrian G
1/s. 26/06/24.
03 days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

TEO HIN TYRES

11 KAKI BUKIT ROAD 1
#01-01 EUNOS TECHNOLINK
SINGAPORE 415939
TEL:67455711

Work Order: R007018
Company: CHIA AUTO SERVICES PTE LTD
License: SMU 874 E
Date: 25.6.24 12:05

Lexus : ES (200/240/250/350) : 2020.01- (ASZ10 AXZA10 GSZ10 MXZA10) : AXZA10L-(AEZGBC, AEZGBW, AEZGBV),
AXZA10R-(AEZGBQ, AEZGB) : with 235/45R18 Tire

Front : Left

Actual	Before	Specified Range
-0°25'		-1°07' 0°23'
5°15'		4°21' 5°51'
-0°10'		-0°04' 0°07'
10°20'		
9°55'		

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
-0°36'		-1°07' 0°23'
5°27'		4°21' 5°51'
-0°06'		-0°04' 0°07'
10°29'		
9°53'		

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	Before	Specified Range
0°11'		-0°45' 0°45'
-0°12'		-0°45' 0°45'
-0°10'		
-0°16'		-0°07' 0°13'

Rear : Left

Actual	Before	Specified Range
-1°49'		-1°50' -0°20'
0°08'		0°00' 0°11'

Camber
Toe

Rear : Right

Actual	Before	Specified Range
-2°25'		-1°50' -0°20'
-0°10'		0°00' 0°11'

Rear

Cross Camber
Total Toe
Thrust Angle

Actual	Before	Specified Range
0°36'		-0°45' 0°45'
-0°02'		0°01' 0°21'
0°09'		