

CHIA AUTO SERVICES PTE LTD

23 Kaki Bukit Avenue 4 #04-01 Vicom Inspection Centre Singapore 415933

Tel: 6744 4986

Reg. No: 201538764H

Email: CA3SERVICES@GMAIL.COM

ATTENTION:	MOTOR CLAIMS DEPARTMENT
DATE:	25-06-26
CLAIM TYPE:	T/P CLAIM
TO:	SOMPO
VEHICLE DETAILS	
VEHICLE NO:	SMU874E
MAKE & MODEL:	TOYOTA LEXUS ES250
CHASSIS NO:	
ACCIDENT DETAILS	
DATE:	25 June, 2024
TIME:	0910HRS
THIRD PARTY REQUESTOR:	JACK LI

CLAIM DETAILS: PARTS

S/N:	DESCRIPTION	QTY:	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR DOOR RH <i>Repair</i>	1	\$ 1,688.50	\$ 1,688.50
2	REAR FENDER <i>Repair</i>	1	\$ 1,655.80	\$ 1,655.80
3	REAR FENDER INNER COWLING <i>34</i>	1	\$ 280.00	\$ 280.00
4	REAR WINDSCREEN MOULDING <i>in</i>	1	\$ 190.00	\$ 190.00
5	REAR BUMPER <i>Repair</i>	1	\$ 1,620.20	\$ 1,620.20
6	REAR BUMPER SIDE RETAINER <i>new</i>	1	\$ 120.00	\$ 120.00
7	REAR SHOCK ABSORBER <i>new</i>	1	\$ 320.00	\$ 320.00
8	REAR KNUCKLE ARM <i>new</i>	1	\$ 620.00	\$ 620.00
9	REAR UPPER ARM <i>Not a Best</i>	1	\$ 450.00	\$ 450.00
10	REAR LOWER ARM <i>Best</i>	1	\$ 410.00	\$ 410.00
11	REAR TRAILING ARM <i>new</i>	1	\$ 520.00	\$ 520.00
12	REAR WHEEL BEARING <i>new</i>	1	\$ 720.00	\$ 720.00

TOTAL PRICE \$ 8,594.50

LESS 25% \$ 2,148.63

SUB TOTAL PRICE \$ 6,445.88

SPECIAL NETT ITEMS

S/N:	DESCRIPTION	QTY:	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER CLIPS(SET) <i>new</i>	1	\$ 20.00	\$ 20.00
2	REAR FENDER INNER COWLING CLIPS(SET) <i>new</i>	1	\$ 20.00	\$ 20.00
3	REAR WINDSCREEN SEALANT <i>new</i>	1	\$ 120.00	\$ 120.00

4	WHEEL RIM <i>Ct</i>	1	\$ 1,200.00	\$ 1,200.00	<i>680</i>
5	WHEEL RIM GAS PIN <i>Best</i>	1	\$ 100.00	\$ 100.00	<i>50</i>
6	CERMAIC COATING	1	\$ 1,000.00	\$ 1,000.00	<i>600</i>
			TOTAL	\$ 2,460.00	

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	1	\$ 1,400.00	\$ 1,400.00	<i>200</i>
2	TO SPRAY PAINT AFFECTED AREA	1	\$ 1,000.00	\$ 1,000.00	<i>600</i>
3	TUFF COAT	1	\$ 200.00	\$ 200.00	<i>30</i>
4	WIRING CHECK	1	\$ 80.00	\$ 80.00	<i>+</i>
5	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	1	\$ 280.00	\$ 280.00	<i>+</i>
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	1	\$ 100.00	\$ 100.00	<i>+</i>
7	REMOVE AND REFIX REVERSE REAR UNDERCARRIAGE	1	\$ 350.00	\$ 350.00	<i>180</i>
8	FOUR WHEEL ALIGNMENT	1	\$ 120.00	\$ 120.00	<i>80</i>
			TOTAL	\$ 3,530.00	

ESTIMATE REPORT

TOTAL PARTS COST	\$	8,905.88
TOTAL LABOUR COST	\$	3,530.00
TOTAL REPAIR COST	\$	12,435.88

APPROVED DETAILS:

SURVEYOR:
CONTACT NO.:
PART BY PART/LUMP SUM
NO. OF DAYS

Adrian G
L/S. 26/06/24.
03 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: