



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS INCOME INSURANCE LTD	Ref:	CS/INC24110063/Uvp3e2
75 BRAS BASAH ROAD	Date:	15/11/2024
INCOME CENTRE SINGAPORE 189557	Code:	INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GN 7667Z	Veh. Inspected	GBD 8758A
Policy No.	-	Coverage	0
Claim No.	MT/1300476-002	Excess	\$0.00
Assign From	JULIET KOH	Assign Date	05/11/2024

2. Vehicle Details

Make & Model	TOYOTA DYNA (M)	C.C	2982
Engine No.	1KD2490830	Year of Reg.	06/07/2015
Chassis No.	JTFAT35Y80K204472	Colour	SILVER
Odometer	270445 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: NIL		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	195R15	AGILIS	6
L/H Front Tyre	195R15	AGILIS	6
R/H Rear Tyre	155R12 (D)	YOKOHAMA	6/6
L/H Rear Tyre	155R12 (D)	YOKOHAMA	6/6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	19/10/2024	Inspection Date	05/11/2024 (13:01)
Survey held at	CARSMITH PTE LTD - 8 KAKI BUKIT AVE 4 #04-35 SINGAPORE 415875		

5a. Remarks

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days