

HD Perfect Autowork Pte Ltd

Company Reg No: 202136904Z

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail: hdperfectautowork@gmail.com



HD PERFECT
AUTOWORK PTE LTD

DATE : 04.11.2024

TO : **INCOME** MOTOR CLAIMS DEPTS
VEHICLE NO : **SMU8769Z**
MODEL : **VOLKSWAGEN GOLF**
DATE OF ACCIDENT : 03.11.2024
TIME OF ACCIDENT : 00:18 HOURS

Vern.

2015

WVWZZZA4ZF W193527

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	TAILGATE <i>Regis</i>	1	\$ 1,999.60	\$ 1,999.60
2	TAILGATE STOPPER	2	\$ 38.00	\$ 76.00
3	TAILGATE INNER TRIM	1	\$ 438.96	\$ 438.96
4	TAILGATE TOP LOCK	1	\$ 89.60	\$ 89.60
5	TAILGATE LOWER LOCK	1	\$ 568.75	\$ 568.75
6	TAILGATE WINDSCREEN MOULDING C/W GLASS <i>off</i>	1	\$ 1,511.60	\$ 1,511.60
7	TAILGATE WEATHESTRIP <i>new</i>	1	\$ 635.60	\$ 635.60
8	TAILGATE LAMP <i>new</i>	2	\$ 747.65	\$ 1,495.30
9	TAIL LAMP <i>combined LH</i>	2	\$ 833.51	\$ 1,667.02
10	TAIL LAMP PANEL LH <i>new</i>	1	\$ 482.70	\$ 482.70
11	TAIL LAMP INNER PANEL LH <i>new</i>	1	\$ 446.50	\$ 446.50
12	TAIL LAMP LOWER BRACKET LH <i>new</i>	1	\$ 188.96	\$ 188.96
13	REAR BUMPER <i>Rehnd</i>	1	\$ 1,588.40	\$ 1,588.40
14	REAR BUMPER DIFFUSER <i>Rehnd</i>	1	\$ 498.50	\$ 498.50
15	REAR BUMPER SIDE GARNISH LH <i>new</i>	1	\$ 155.35	\$ 155.35
16	REAR BUMPER CENTER BEAM <i>combined</i>	1	\$ 41.60	\$ 41.60
17	REAR BUMPER SIDE BRACKET <i>new</i>	2	\$ 198.50	\$ 397.00
18	REAR BUMPER REINFORCEMENT <i>Defnd</i>	1	\$ 659.46	\$ 659.46
19	REAR BUMPER TOWING COVER <i>new</i>	1	\$ 85.40	\$ 85.40
20	REAR BUMPER REFLECTOR <i>new</i>	2	\$ 132.60	\$ 265.20
21	REAR FENDER LH <i>new</i>	1	\$ 2,183.44	\$ 2,183.44

+

+

+

+

+

+

+

+

+

+

+

+

+

+

+

+

+

+

+

+

+

+

+

+

+

+

+

+

TO : **INCOME** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SMU8769Z**
 MODEL : **VOLKSWAGEN GOLF**
 DATE OF ACCIDENT : 03.11.2024
 TIME OF ACCIDENT : 00:18 HOURS

22	REAR FENDER COWLING	2	\$ 388.22	\$ 776.44	+
23	REAR FENDER INNER TRIM	2	\$ 535.60	\$ 1,071.20	+
24	REAR FENDER INNER PANEL LH	1	\$ 685.30	\$ 685.30	+
25	REAR FENDER AIR VENT LH	1	\$ 98.45	\$ 98.45	+
26	REAR END PANEL <i>Deted</i>	1	\$ 1,599.60	\$ 1,599.60	1180
27	REAR END PANEL TOP GARNISH <i>Deted</i>	1	\$ 346.67	\$ 346.67	✓
28	REAR FLOOR PANEL TOP BOARD <i>new</i>	1	\$ 698.75	\$ 698.75	+
29	REAR CHASSIS EXTEND PANEL LH <i>new</i>	1	\$ 967.50	\$ 967.50	+
30	REAR EXHAUST PIPE <i>Best</i>	1	\$ 1,588.18	\$ 1,588.18	1480
31	REAR EXHAUST MOUNTING <i>new</i>	2	\$ 90.97	\$ 181.94	+
32	REAR EXHAUST INSULATOR <i>new</i>	1	\$ 299.96	\$ 299.96	+
33	REAR EXHAUST MOUNTING BRACKET <i>new</i>	2	\$ 135.60	\$ 271.20	+

58643474
 5579126

TOTAL PRICE \$ 24,060.13
 LESS 10% \$ 2,406.01
SUB TOTAL PRICE \$ 21,654.12

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	REAR NUMBER PLATE <i>new</i>	1	\$ 50.00	\$ 50.00	+
2	REAR BUMPER CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	30
3	REAR BUMPER NUMBER PLATE LAMP	2	\$ 99.87	\$ 199.74	+
4	REAR FENDER SEALANT	1	\$ 80.00	\$ 80.00	+
5	REAR FENDER INNER TRIM CLIPS (SET)	1	\$ 80.00	\$ 80.00	+
6	REAR FENDER COWLING CLIP	1	\$ 40.00	\$ 40.00	+
7	TAILGATE SEALANT	1	\$ 150.00	\$ 150.00	+
8	TAILGATE STICKER (BLACK)	1	\$ 120.00	\$ 120.00	+
9	TAIL GATE INNER TRIM CLIP (SET)	1	\$ 80.00	\$ 80.00	+
10	TAILGATE WINDSCREEN SEALANT <i>new</i>	1	\$ 80.00	\$ 80.00	+
11	TAILGATE WINDSCREEN INNER SEAL	1	\$ 60.00	\$ 60.00	+
12	TAILGATE WINDSCREEN SOLAR FILM	1	\$ 150.00	\$ 150.00	+
13	TAILLAMP CLIP (SET)	1	\$ 50.00	\$ 50.00	+
14	REAR END PANEL TOP GARNISH CLIPS (SET) <i>new</i>	1	\$ 30.00	\$ 30.00	20
15	REAR END PANEL INSULATION SEAL <i>new</i>	1	\$ 150.00	\$ 150.00	60
16	REVERSE SENSOR <i>new</i>	1	\$ 220.00	\$ 220.00	200

TOTAL \$ 1,619.74

310

TO : **INCOME** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SMU8769Z**
 MODEL : **VOLKSWAGEN GOLF**
 DATE OF ACCIDENT : 03.11.2024
 TIME OF ACCIDENT : 00:18 HOURS

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
	TO PANEL BEAT, REMOVE AND REPLACE PARTS	\$ 2,000.00	800
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,600.00	800
3	TUFF COAT	\$ 250.00	60
4	WIRING AND BULB CHECK	\$ 180.00	30
5	REMOVE AND REFIX CUSHION SEAT/UPHOLSTRY & ROOF LINING TO FACILITATE REPAIR	\$ 350.00	60
6	TRANSFER TAILGATE MECHANISM	\$ 80.00	x
7	CONDUCT WATER LEAKAGE TEST	\$ 80.00	x
8	REMOVE AND REFIX FUEL TANK	\$ 100.00	x
9	REMOVE AND REFIX REAR EXHAUST PIPE	\$ 180.00	60
10	REMOVE AND REFIX TAILGATE WINDSCREEN	\$ 120.00	x
11	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 120.00	50
12	REMOVE AND REFIX REAR REVERSE CAMERA	\$ 120.00	x
13	REMOVE AND REFIX VIDEO CAMERA	\$ 80.00	x

TO : **INCOME** MOTOR CLAIMS DEPTS
VEHICLE NO : **SMU8769Z**
MODEL : **VOLKSWAGEN GOLF**
DATE OF ACCIDENT : 03.11.2024
TIME OF ACCIDENT : 00:18 HOURS

14	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 380.00	X 180.
----	--	-----------	--------

2040

TOTAL \$ **5,640.00**

ESTIMATE REPORT

TOTAL PARTS COST : \$ 23,273.86
TOTAL LABOUR COST : \$ 5,640.00
TOTAL REPAIR COST : \$ 28,913.86

Adrian
2/s 05/11/24.
05 Days

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE
CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED
ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
IRENE
HP : 8297 9787

Total: 8141.26
H/s: 6.5K

6.5K

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: