



辉皇鸿寶

HHHB PTE LTD

2 Kaki Bukit Ave 2 | #02-11 Kaki Bukit @ Autohub | Singapore 417921
Office: 6844 7414 | Fax: 6844 7401 | Email: claims@hhb.com.sg
Company Reg. No. 202341776E

TP INC

Veron.

Vehicle No.: SNM290U
Make/Model : Suzuki Swift 1.2
Chassis no.: JSAAZCA3S00599502
Year of Manufacture : 2023

Date of survey:
Surveyor:
Company :
Ins Company : Income
TP vehicle No.: GBK8288C

Accident Date : 30 Oct 2024

Type of repair: Lump Sump

Estimate cost of repairs

Qty	Part Description	Unit Price	Total Price	
1 pc	Front bumper <i>Deh</i>	\$ 987.00	\$ 987.00	<i>695</i>
1 pc	Front bumper retainer RH <i>new</i>	\$ 63.00	\$ 63.00	<i>+</i>
1 pc	Front fender RH <i>Buckled</i>	\$ 945.00	\$ 945.00	<i>649</i>
1 pc	Front fenfer inner shield RH <i>new</i>	\$ 155.00	\$ 155.00	<i>+</i>
1 pc	Headlamp RH <i>new</i>	\$ 1,655.00	\$ 1,655.00	<i>+</i>
			\$ 3,805.00	<i>1344</i>
			\$ (570.75)	<i>1142.40</i>
			\$ 3,234.25	
	Less 15%			
1 set	Front bumper clips <i>new</i>	\$ 50.00	\$ 50.00	<i>SN 30</i>
1 set	Front fender inner shield clips <i>new</i>	\$ 50.00	\$ 50.00	<i>SN +</i>
			\$ 100.00	
1 job	To putty and spray painting	\$ 600.00	\$ 600.00	<i>400</i>
1 job	Wiring Charges	\$ 60.00	\$ 60.00	<i>30</i>
1 job	To rewire front portion and refocus headlamp beam	\$ 60.00	\$ 60.00	<i>+</i>
1 job	Labour to remove rear accident damaged parts in order to repairs including panel beat and replace above parts.	\$ 600.00	\$ 600.00	<i>400</i>
			\$ 1,320.00	<i>830</i>
			\$ 4,654.25	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Grand-total

Total: 2002.40
H/S: 1.6K ✓

Adrian C
H/S 08/11/24
03 Days