

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT						
	INCOME INSURAN		Ref:	CS/INC24110066/Avp3e2(N)		
	75 BRAS BASAH R INCOME CENTRES		Date:	22/01/2025		
	ATTN: LIM SEREN	E		Code:	INC	
1. Policy Particulars :- THIRD PARTY CLAIM						
	Insured Veh.	SLA 9541Z	Veh. Inspected	t	SDR 2929R	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	MT/1302352-002	Excess (\$)		0.00	
	Assign From	JULIET KOH	Assign Date		05/11/2024	
2. Vehicle Particulars & Condition						
	Make & Model	TOYOTA NOAH HYBRID	c.c		1797	
	Engine No.	HIDDEN	Year of Reg.		2018	
	Chassis No.	ZWR800337166	Colour		BLACK	
	Odometer	184290 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	215/50 R17	GITI		6 mm	
	L/H Front Tyre	215/50 R17	GITI		6 mm	
	R/H Rear Tyre	215/50 R17	GITI		6 mm	
	L/H Rear Tyre	215/50 R17	GITI		6 mm	
4. Description of Damages						
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
					3."	
5.	General Information					
	Accident Date	30/10/2024	Inspect Date /	Time	05/11/2024 ( 03:14 PM )	
	Survey held at					
	8 KAKI BUKIT AVENUE 4, #08-09, PREMIER @ KAKI BUKIT, SINGAPORE 415875					
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORM	MAL PERIOD FOR REPAIR:		5 Workir	ng Days	
	•					