

PLEASE ARRANGE TO SURVEY
VEHICLE AT 30 BUKIT BATOK
CRESCENT (S 658075)

Selamatshahh
CLAIM DEPARTMENT
DID : 66547727
FAX :

Date : 05/11/2024

To : INDIA INTERNATIONAL INSURANCE PTE LTD
ESTIMATION

Attn : Motor Claim Department FAX :

Owner : ETHOZ Group Ltd
SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : 1 Accident Date : 28/10/2024

Vehicle No : GBL-5477-M Make & Model : TOYOTA HIACE 3.0 TURBO VAN G (M) EURO

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
List Item			
1	REAR BUMPER <i>de</i>	422.50	/
10	REAR BUMPER CLIPS <i>re</i>	50.00	/
1	TAILGATE <i>bl</i>	2,156.00	/
1	TAILGATE LOGO <i>re</i>	86.10	/
1	EMBLEM - TOYOTA HIACE <i>re</i>	75.00	/
1	TAILGATE LOCK <i>Xnn</i>	289.60	
1	TAILGATE WEATHERSTRIPE <i>Xnn</i>	311.20	
1	END PANEL	RESTORE	

Date : 05/11/2024

To : INDIA INTERNATIONAL INSURANCE PTE LTD
ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : 1

Accident Date : 28/10/2024

Vehicle No : GBL-5477-M

Make & Model : TOYOTA HIACE 3.0 TURBO VAN G (M) EURO

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
	Sub Total	2092.20 3390.40	
	Discount 25% On Parts	(847.60)	
	<u>Special Nett Item</u>		
1	REVERSE SENSOR Xnn	200.00	
1	SEALANT m/	30 50.00	
1	ADVERTISEMENT STICKER m/	150 100 200.00	
1	70KM/H STICKER m/	15.00	
1	8 PAX STICKER m/	15.00	

Date : 05/11/2024

To : INDIA INTERNATIONAL INSURANCE PTE LTD
ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : 1

Accident Date : 28/10/2024

Vehicle No : GBL-5477-M

Make & Model : TOYOTA HIACE 3.0 TURBO VAN G (M) EURO

ESTIMATED REPAIR COST DETAILS

Excess : 0.00

Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
	Sub Total	480.00	
Labour & Misc			
	LABOUR TO FACILITATE REPAIR	600.00	400 ✓
	TO RESPRAY AFFECTED AREAS	700.00	500 ✓
	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	30.00	X 1 ✓
	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	150.00	120 ✓
	RUST PROOFING	50.00	30 ✓

Date : 05/11/2024
 To : INDIA INTERNATIONAL INSURANCE PTE LTD
ESTIMATION
 Attn : Motor Claim Department FAX :

Owner : ETHOZ Group Ltd
 : SOMPO INSURANCE SINGAPORE PTE. LTD.
 Certificate No : 1 Accident Date : 28/10/2024
 Vehicle No : GBL-5477-M Make & Model : TOYOTA HIACE 3.0 TURBO VAN G (M) EURO
ESTIMATED REPAIR COST DETAILS Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
	Sub Total	1530.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Remarks:

4 days / Res after repair
 4/5

4,552.80
SUB TOTAL
GST 9.0 % 409.75
TOTAL 4,962.55

Surveyor's name: Rame - Hg 900 10068

Principal's name: ETHOZ Group Ltd

Survey Date & Time: 06/11/24

PAGE : 4