

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS	INCOME INSURAN	ICE LTD	Ref:	CS/INC24110070/Unp3m4
	75 BRAS BASAH F		Date:	12/11/2024
	INCOME CENTRE	SINGAPORE 189557	Code:	INC
1.	Policy Particulars :- THIRD PARTY CLAIM			
	Insured Veh.	SMU 4395U	Veh. Inspected	SNH 24Z
	Policy No.	-	Coverage	0
	Claim No.	MT/1302460-001	Excess	\$0.00
	Assign From	JULIE MANGUBAT	Assign Date	05/11/2024
2.	Vehicle Details			
	Make & Model	MERCEDES BENZ GLB 180 AMG LINE	c.c	1332
	Engine No.	28291480473173	Year of Reg.	13/04/2021
	Chassis No.	W1N2476842W093210	Colour	BLACK
	Odometer	117031 KM	Steering	IN ORDER
	Brakes	IN ORDER	General	GOOD
	Modification(s)	RIMS: SPORTS RIM		
3. Conditions of Tyres				
		Size	Make	Balance (mm)
	R/H Front Tyre	235/50R19	CONTINENTAL	8
	L/H Front Tyre	235/50R19	CONTINENTAL	8
	R/H Rear Tyre	235/50R19	CONTINENTAL	8
	L/H Rear Tyre	235/50R19	CONTINENTAL	8
4.	Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
	Accident Date	31/10/2024	Inspection Date	05/11/2024 (14:33)
	Survey held at	IMPERIUM AUTOMOTIVE 25 KAKI BUKIT ROAD 4 #01-49 SYNERGY @ KB SINGAPORE 417800		

Remarks

Estimate Days of Repair

A) THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.

ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days

B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.