

IMPERIUM AUTOMOTIVE

25 Kaki Bukit Road 4 # 01-47 Synergy@KB, Singapore 417800

HP : 9748 9940 Shawn Tan

Email : shawn7530@hotmail.com

no t Authorized
all
merch
5/11/24
1/2 8 1600
2 days
theophan

05 NOVEMBER 2024

Vehicle No: SNH24Z

Model : MERCEDES BENZ GLB180

QTY	List Items	AMOUNT
1	Rear Bumper cut/ torn 1615.32	\$2367.90
1	Rear Bumper Lower su	\$578.30
2	Rear Bumper Bracket ^ ^	\$160.00
1	Rear Bumper Lower Spoiler Chrome ^ ^	\$732.40
1	Rear Bumper Reinforcement ^ ^	\$480.00
2	Rear Bumper Side Retainers ^ ^	\$170.00
6	Rear Bumper PDC Sensors ^ ^	\$1740.00
2	Rear Bumper Reflector ^ ^	\$88.00
1	Rear Bumper Rear Arch ^ ^	\$280.40
2	Rear Exhaust Chrome Tail Pipes ^ ^	\$470.00
		\$7067.00
Less 5% 10%		\$353.35
		\$6713.65

Special Nett Items

1	Rear Bumper Clip (1 set)	su \$120.00 50 S/N
		\$120.00

Labour Charges

To Remove, Replaced Damaged Lamps and check up Rear Wiring	\$80.00	40
To Remove & Refit Rear Reverse Sensor	\$200.00	
To Apply undercoating	11 \$100.00	X
Panel Beating	\$1000.00	200
To Re-Spray Painting on the affected areas	\$1000.00	280
	\$2380.00	
	Grand Total	\$9213.65

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) in the resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insu

LKK Auto Consultants hence notify the Repairer of the following:

- To survey before/after spray painting
- To display damaged part(s) for the survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurer

Acknowledged by Repairer
Signature:
Date: