



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS SOMPO INSURANCE SINGAPORE PL	Ref:	CS/SMO24060251/Uvp3
50 RAFFLES PLACE #03-03	Date:	30/08/2024
SINGAPORE LAND TOWER SINGAPORE 048623	Code:	SMO

1. Policy Particulars :- OWN DAMAGE CLAIM

Insured Veh.	-	Veh. Inspected	SLR 230R
Policy No.	D23MTPV01010038	Coverage	0
Claim No.	CMTD2402080/JYC	Excess	\$0.00
Assign From	GRACE TEO	Assign Date	24/06/2024

2. Vehicle Details

Make & Model	NISSAN PULSAR (A)	C.C	1197
Engine No.	HRA2406175A	Year of Reg.	28/07/2017
Chassis No.	VSKDDAC13U0104996	Colour	BLUE
Odometer	45467 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	205/50ZR17	DUNLOP	5
L/H Front Tyre	205/50ZR17	DUNLOP	5
R/H Rear Tyre	205/50ZR17	DUNLOP	5
L/H Rear Tyre	205/50ZR17	DUNLOP	5

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	21/06/2024	Inspection Date	25/06/2024
Survey held at	AUTOLUTION INDUSTRIAL PTE LTD 19 UBI ROAD 4 SINGAPORE 408623		

5a. Remarks

A)THE MARKET VALUE IS S\$42,000.00(EST. AVERAGE)
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days