

AUTOLUTION INDUSTRIAL PTE. LTD.

AUTOLUTION INDUSTRIAL PTE LTD  
1000 ROAD 4  
SINGAPORE 408623  
TEL: 6846 8888 FAX: 6846 7483

ESTIMATE : ACCIDENT/BODY REPAIRS

REFERENCE : INS/IC/H/0222/24  
DATE : 24-JUN-2024

M/S SOMPO INSURANCE SINGAPORE PTE LTD  
50 RAFFLES PLACE  
#03-03 SINGAPORE LAND TOWER  
S(048623)  
TEL : 64616555  
FAX : 62213147  
ATTN : MOTOR CLAIM MANAGER

OWNER'S NAME : MR WOO JIUN WEI (WU JUNWEI)  
ADDRESS : BLK 405 PASIR RIS DRIVE 6  
#02-495  
S(510405)  
TELEPHONE NO : 98324134

TYPE OF CLAIM : OD OR OD RECOVERY CLAIM  
POLICY NO : D23MTPV01010038  
VEHICLE NO : SLR230R  
MODEL CODE : DRLARDZC13UEAB-F-E  
MODEL/YEAR : NISSAN PULSAR 1.2 MY2016  
ENGINE NO : HRA2406175A-C13S/CL  
CHASSIS NO : VSKDDAC13U0104996  
MILEAGE : 45467 KM  
DATE IN : 24/06/2024  
LIABILITY : 0.00  
EXCESS CLAUSE : 0.00  
ESTIMATE BY : HAMZAH  
ACCIDENT DATE : 21/06/2024

not Authorized  
with  
meant  
90296608  
25/6/24 @ 12pm

Take photo separately.

EXCESS & WAIVER  
6 days

2/2 @ 14549.70

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) before resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLR230R

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	ZZ/001	LABOUR CHARGES TO REPAIR BOTH FRT FENDER, RENEW RADIATOR SUPPORT, BONNET AND FRONT BUMPER. <i>180</i>	1200.00	<i>720</i>
<i>150</i>	2	ZZ/002 CHARGES TO SPRAY PAINTING SAME. <i>180 y6</i>	1200.00	<i>1080</i>
3	ZZ/003	RENEW HEADLAMP AND FOCUS.	48.00	✓
4	ZZ/004	RENEW A/COND CONDENSER, VACUUM AND REFILL FREON GAS.	120.00	✓
5	ZZ/005	APPLY SEALANT TO BONNET.	100.00	✓
6	ZZ/006	SUPPLY FRONT LICENSE PLATE.		
7	ZZ/007	TOWING CHARGES BY AUTOSWIFT W/O T212008	<i>FOC</i> 80.00	<i>X</i>
TOTAL LABOUR CHARGES			2748.00	<i>X</i>

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLR230R

DAMAGED PARTS & PRICES						
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	REMAR
1	SUNDRIES	NPN		nu	50.00	30
2	FRT LICENCE PLATE	FLP		39e	35.00	30
3	EMBLEM RAD GRILLE	62890-1DA0B		one	43.70	
4	HORN	25610-3ZL0B		svl	78.20	X
5	HOSE FLEXIBLE A/COND	92480-3ZU0A		17	94.40	X
6	HOSE-FLEXIBLE A/COND	92490-BV81A		17	215.00	X
7	A/COND HIGH PRESSURE PIPE	92440-3ZU1A		17	74.30	X
8	AIR GUIDE OIL COOLER OUTER	21609-3ZL5A		17	243.00	X
9	AIR GUIDE OIL COOLER INNER	21609-3ZL0A		17	242.50	X
10	OIL COOLER	21606-3ZL0A		17	261.50	X
11	HOSE UPPER RADIATOR	21501-3ZU1A		17	129.10	X
12	HOSE-BOTTOM RADIATOR	21503-3ZU0A		17	41.20	X
13	RADIATOR OVERFLOW TANK	21711-3ZU0A		one	102.90	2
14	RADIATOR FAN MOTOR	21481-HX52A		one/buy	678.60	?
15	A/COND AMBIENT SENSOR	27722-BV80C		17	81.90	X
16	RADIATOR COOLANT	NC-01		nu	19.00	
17	RADIATOR <i>photo?</i>	21410-HX51B		buy	585.20	
18	A/COND CONDENSER <i>photo?</i>	92100-BA61B		buy	435.20	
19	WIPER WASHER TANK	28910-3ZL1B		17	250.80	X
20	BONNET LOCK	65601-3ZP0A		nu,	113.80	
21	BONNET RUBBER SEAL	65820-3ZL0A		nu	42.50	
22	BONNET	F5100-3ZLMA		buy	3533.20	
23	AIR GUIDE FRT LH	62823-3ZL0A		10in	96.80	
24	AIR GUIDE FRT RH	62822-3ZL0A		17	65.90	X
25	HOOD LOCK STAY	62550-3ZL0A		buy	238.80	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLR230R

		DAMAGED PARTS & PRICES			
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT REMAR
26	RADIATOR SUPPORT STAY LH	F2521-3ZLMA ✓		321	160.40 ✓
27	RADIATOR SUPPORT STAY RH	F2520-3ZLMA		11	160.40 X
28	RADIATOR SUPPORT TOP LH	F2513-3ZLMA		11	589.60 X
29	RADIATOR SUPPORT TOP RH	F2512-3ZLMA		11	589.60 X
30	RADIATOR SUPPORT TOP CENTRE	F2511-3ZLMA ✓		10.5	632.50 ✓
31	CLIP RAD GRILLE @ \$1.00 EACH	01553-09321 ✓		111	13.00 ✓
32	RADIATOR SUPPORT TOP GARNISH	62322-3ZL0A ✓		2.5	329.60 ✓
33	RADIATOR GRILLE	62310-3ZL0A ✓		320	383.90 ✓
34	HEADLAMP LH	26060-3ZP5A ✓		320	970.90 ✓
35	HEADLAMP RH	26010-3ZP5A ✓		CM	970.90 ✓
36	FRT BUMPER TOW COVER	622A0-3ZL0H ✓		11.5	13.50 ✓
37	FOG LAMP LH	26155-1HA0B		17	232.30 X
38	FOG LAMP RH	26150-1HA0B		17	232.30 X
39	FOG LAMP GARNISH LH	62257-3ZL2A		17	175.90 X
40	FOG LAMP GARNISH RH	62256-3ZL2A		17	175.90 X
41	FRT BUMPER CHASSIS STAY LH	G5115-3ZLMA		11	475.41 X
42	FRT BUMPER CHASSIS STAY RH	G5114-3ZLMA		11	384.80 X
43	FRT BUMPER LOWER COVER	62663-3ZL0A		11	83.30 X
44	FRT BUMPER REINFORCEMENT	F2030-3ZLAA		11	2475.60 X
45	ENERGY ABSORBER FRT BUMPER	62090-3ZL0A ✓		70.11	296.00 ✓
46	FRT BUMPER SIDE BRKT LH	62225-3ZL0A ✓		321	12.90 ✓
47	FRT BUMPER SIDE BRKT RH	62224-3ZL0A ✓		321	12.90 ✓
48	CLIP FRT BUMPER @ !.00 EACH	01553-05933 ✓		111	20.00 ✓
49	FASCIA KIT FRT	F2022-3ZLMH ✓		Dis	976.90 ✓

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLR230R

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
		NETT	LIST	S/NETT REMAR
SUB TOTAL		0.00	0.00	18121.01
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		0.00	0.00	0.00
GRAND TOTAL		0.00	0.00	18121.01
OVERALL TOTAL		18121.01		

LEGEND: REMARKS ( OK ) = APPROVED, REMARKS ( X ) = NOT APPROVED

Front bumper spoiler 8380 7121 ✓

AUTOLUTION INDUSTRIAL PTE. LTD.

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLR230R

-----  
TOTAL LABOUR CHARGES                    2748.00  
TOTAL SPARE PARTS CHARGES            18121.01  
-----  
GRAND TOTAL                            20869.01 \*  
-----

\* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

-----  
NAME                                    :  
SURVEYED DATE                        :  
AUTHORIZED DATE                      :  
EXCESS CLAUSE                        :            0.00  
LIABILITY                              :            0.00  
REMARKS                                :

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.



**Autolution Industrial Pte Ltd**  
Tan Chong Motor Sales Pte Ltd's Authorised Dealer  
19 Ubi Road 4  
Singapore 408623  
Tel (65) 64909666 / 67038680  
Fax (65) 68467483  
Business Reg. No.: 199500871W

20-August-2024

INS/SC/H/0295/24

Sompo Insurance Singapore Pte Ltd  
50 Raffles Place, #03-03, S'pore Land Tower  
Singapore 048623

Attn : Motor Claim Manager  
Claim Dept

Dear Sir

**SUPPLEMENTARY CLAIM**

REGN. NO. : SLR230R  
POLICY NO: D23MTPV01010038

Further to our claim INS/IC/H/0222/24 we are submitting a supplementary claim for the below mentioned labor and part for the above mentioned case.

**Labor charges**

1	Renew intake manifold.	\$	234.00	✓
---	------------------------	----	--------	---

**Replacement of Damaged Items**

1	Front bumper spoiler ✓	<i>Total</i>	\$	380.00	S/Nett ✓
2	Bonnet hinge RH ✓	<i>Part</i>	\$	83.20	S/Nett ✓
3	Bonnet hinge LH ✓	<i>Part</i>	\$	83.20	S/Nett ✓
4	Intake manifold ✓	<i>Part</i>	\$	778.50	S/Nett ✓
5	Bonnet insulator ✓	<i>Total</i>	\$	179.70	S/Nett ✓

We trust the above supplementary claim will meet with your kind approval and we will forward to you the final repair bill together with the satisfaction note on completion repairs.

Yours faithfully  
**AUTOLUTION INDUSTRIAL PTE LTD**

  
Hamzah Sa'ad  
Insurance Claim Dept

Cc: Surveyor-Mr. Marcus (LKK)

