

AUTOLUTION INDUSTRIAL PTE. LTD.

AUTOLUTION INDUSTRIAL PTE LTD  
11 ROAD 4  
SINGAPORE 408623  
PHONE: 6846 7483 FAX: 6846 7483

ESTIMATE : ACCIDENT/BODY REPAIRS

REFERENCE : INS/IC/H/0222/24

DATE : 24-JUN-2024

M/S SOMPO INSURANCE SINGAPORE PTE LTD  
50 RAFFLES PLACE  
#03-03 SINGAPORE LAND TOWER  
S(048623)  
TEL : 64616555  
FAX : 62213147  
ATTN : MOTOR CLAIM MANAGER

OWNER'S NAME : MR WOO JIUN WEI (WU JUNWEI)

ADDRESS : BLK 405 PASIR RIS DRIVE 6  
#02-495  
S(510405)

TELEPHONE NO : 98324134

TYPE OF CLAIM : OD OR OD RECOVERY CLAIM  
POLICY NO : D23MTPV01010038  
VEHICLE NO : SLR230R  
MODEL CODE : DRLARDZC13UEAB-F-E  
MODEL/YEAR : NISSAN PULSAR 1.2 MY2016  
ENGINE NO : HRA2406175A-C13S/CL  
CHASSIS NO : VSKDDAC13U0104996  
MILEAGE : 45467 KM  
DATE IN : 24/06/2024  
LIABILITY : 0.00  
EXCESS CLAUSE : 0.00  
ESTIMATE BY : HAMZAH  
ACCIDENT DATE : 21/06/2024

Not Authorized  
LKK  
Meraj  
90296608  
25/6/24 @ 12pm

Take photo separately.

Excess & waiver  
6 days

P/P 14549.70

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts in the resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLR230R

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	ZZ/001	LABOUR CHARGES TO REPAIR BOTH FRT FENDER, RENEW RADIATOR SUPPORT, BONNET AND FRONT BUMPER.	1200.00	720
150	2	CHARGES TO SPRAY PAINTING SAME.	1200.00	1080
3	ZZ/003	RENEW HEADLAMP AND FOCUS.	48.00	✓
4	ZZ/004	RENEW A/COND CONDENSER, VACUUM AND REFILL FREON GAS.	120.00	✓
5	ZZ/005	APPLY SEALANT TO BONNET.	100.00	✓
6	ZZ/006	SUPPLY FRONT LICENSE PLATE.		
7	ZZ/007	TOWING CHARGES BY AUTOSWIFT W/O T212008	80.00	X
TOTAL LABOUR CHARGES			2748.00	

180

180 Y6

FOC

X

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLR230R

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
			NETT	LIST	S/NETT REMAR
1	SUNDRIES	NPN		nu	50.00 30
2	FRT LICENCE PLATE	FLP		3ge	35.00 30
3	EMBLEM RAD GRILLE	62890-1DA0B		one	43.70
4	HORN	25610-3ZL0B		su	78.20 X
5	HOSE FLEXIBLE A/COND	92480-3ZU0A		17	94.40 X
6	HOSE-FLEXIBLE A/COND	92490-BV81A		17	215.00 X
7	A/COND HIGH PRESSURE PIPE	92440-3ZU1A		17	74.30 X
8	AIR GUIDE OIL COOLER OUTER	21609-3ZL5A		17	243.00 X
9	AIR GUIDE OIL COOLER INNER	21609-3ZL0A		17	242.50 X
10	OIL COOLER	21606-3ZL0A		17	261.50 X
11	HOSE UPPER RADIATOR	21501-3ZU1A		17	129.10 X
12	HOSE-BOTTOM RADIATOR	21503-3ZU0A		17	41.20 X
13	RADIATOR OVERFLOW TANK	21711-3ZU0A		one	102.90 2
14	RADIATOR FAN MOTOR	21481-HX52A		one/buy	678.60 2
15	A/COND AMBIENT SENSOR	27722-BV80C		17	81.90 X
16	RADIATOR COOLANT	NC-01		nu	19.00
17	RADIATOR <i>photo</i>	21410-HX51B		buy	585.20
18	A/COND CONDENSER <i>photo</i>	92100-BA61B		buy	435.20
19	WIPER WASHER TANK	28910-3ZL1B		17	250.80 X
20	BONNET LOCK	65601-3ZP0A		nu	113.80
21	BONNET RUBBER SEAL	65820-3ZL0A		nu	42.50
22	BONNET	F5100-3ZLMA		buy	3533.20
23	AIR GUIDE FRT LH	62823-3ZL0A		10in	96.80
24	AIR GUIDE FRT RH	62822-3ZL0A		17	65.90 X
25	HOOD LOCK STAY	62550-3ZL0A		buy	238.80

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLR230R

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
			NETT	LIST	S/NETT REMAR
26	RADIATOR SUPPORT STAY LH	F2521-3ZLMA ✓		311	160.40 /
27	RADIATOR SUPPORT STAY RH	F2520-3ZLMA		11	160.40 X
28	RADIATOR SUPPORT TOP LH	F2513-3ZLMA		11	589.60 X
29	RADIATOR SUPPORT TOP RH	F2512-3ZLMA		11	589.60 X
30	RADIATOR SUPPORT TOP CENTRE	F2511-3ZLMA ✓		105	632.50 /
31	CLIP RAD GRILLE @ \$1.00 EACH	01553-09321 ✓		111	13.00 /
32	RADIATOR SUPPORT TOP GARNISH	62322-3ZL0A ✓		D.S	329.60 /
33	RADIATOR GRILLE	62310-3ZL0A ✓		BRO	383.90 /
34	HEADLAMP LH	26060-3ZP5A ✓		BRO	970.90 /
35	HEADLAMP RH	26010-3ZP5A ✓		CM	970.90 /
36	FRT BUMPER TOW COVER	622A0-3ZL0H ✓		M.S	13.50 /
37	FOG LAMP LH	26155-1HA0B		11	232.30 X
38	FOG LAMP RH	26150-1HA0B		11	232.30 X
39	FOG LAMP GARNISH LH	62257-3ZL2A		11	175.90 X
40	FOG LAMP GARNISH RH	62256-3ZL2A		11	175.90 X
41	FRT BUMPER CHASSIS STAY LH	G5115-3ZLMA		11	475.41 X
42	FRT BUMPER CHASSIS STAY RH	G5114-3ZLMA		11	384.80 X
43	FRT BUMPER LOWER COVER	62663-3ZL0A		11	83.30 X
44	FRT BUMPER REINFORCEMENT	F2030-3ZLAA		R	2475.60 X
45	ENERGY ABSORBER FRT BUMPER	62090-3ZL0A ✓		7011	296.00 /
46	FRT BUMPER SIDE BRKT LH	62225-3ZL0A ✓		311	12.90 /
47	FRT BUMPER SIDE BRKT RH	62224-3ZL0A ✓		311	12.90 /
48	CLIP FRT BUMPER @ 1.00 EACH	01553-05933 ✓		111	20.00 /
49	FASCIA KIT FRT	F2022-3ZLMH ✓		D.S	976.90 /

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLR230R

-----

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
			NETT	LIST	S/NETT REMAR
	SUB TOTAL		0.00	0.00	18121.01
	LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		0.00	0.00	0.00
	GRAND TOTAL		0.00	0.00	18121.01
	OVERALL TOTAL		18121.01		

LEGEND: REMARKS( OK ) = APPROVED, REMARKS( X ) = NOT APPROVED

Front bumper spoiler 8380 7111 ✓

AUTOLUTION INDUSTRIAL PTE. LTD.

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLR230R

-----  
TOTAL LABOUR CHARGES                    2748.00  
TOTAL SPARE PARTS CHARGES               18121.01  
-----  
GRAND TOTAL                               20869.01 \*  
-----

\* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

-----  
NAME                                        :  
SURVEYED DATE                            :  
AUTHORIZED DATE                          :  
EXCESS CLAUSE                            :            0.00  
LIABILITY                                  :            0.00  
REMARKS                                    :

PLS NOTE : This estimate is based on visual inspection of the  
          affected vehicle. Should we require further labour  
          charges & spare parts in the process of repairs, we  
          shall inform you accordingly.