

AUTOLUTION INDUSTRIAL PTE. LTD.

AUTOLUTION INDUSTRIAL PTE LTD  
50 RAFFLES PLACE  
SINGAPORE 048623  
TEL: 6846 7486 FAX: 6846 7485

ESTIMATE : ACCIDENT/BODY REPAIRS

REFERENCE : INS/IC/H/0222/24  
DATE : 24-JUN-2024

M/S SOMPO INSURANCE SINGAPORE PTE LTD  
50 RAFFLES PLACE  
#03-03 SINGAPORE LAND TOWER  
S(048623)  
TEL : 64616555  
FAX : 62213147  
ATTN : MOTOR CLAIM MANAGER

OWNER'S NAME : MR WOO JIUN WEI (WU JUNWEI)  
ADDRESS : BLK 405 PASIR RIS DRIVE 6  
#02-495  
S(510405)  
TELEPHONE NO : 98324134

TYPE OF CLAIM : OD OR OD RECOVERY CLAIM  
POLICY NO : D23MTPV01010038  
VEHICLE NO : SLR230R  
MODEL CODE : DRLARDZC13UEAB-F-E  
MODEL/YEAR : NISSAN PULSAR 1.2 MY2016  
ENGINE NO : HRA2406175A-C13S/CL  
CHASSIS NO : VSKDDAC13U0104996  
MILEAGE : 45467 KM  
DATE IN : 24/06/2024  
LIABILITY : 0.00  
EXCESS CLAUSE : 0.00  
ESTIMATE BY : HAMZAH  
ACCIDENT DATE : 21/06/2024

not Authorized  
with  
meaus  
90296608  
25/6/24 @ 12pm

take photo separately.

Excess \$  
6 hrs

LKK Auto Consultants hence notify  
the Repairer of the following:

- To recovery before/after spray painting
- To display damaged parts for recovery
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be recovered and is subject to final approval from Insurers Company

Acknowledged by Repairer

Signature:

Date:

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLR230R

| S/NO                 | JOB CODE | NATURE OF JOB                                                                              | ESTIMATED CHARGES | SURVEYOR'S RECOMMENDATION |
|----------------------|----------|--------------------------------------------------------------------------------------------|-------------------|---------------------------|
| 1                    | ZZ/001   | LABOUR CHARGES TO REPAIR BOTH FRT FENDER, RENEW RADIATOR SUPPORT, BONNET AND FRONT BUMPER. | 1200.00           | 720                       |
| 2                    | ZZ/002   | CHARGES TO SPRAY PAINTING SAME.                                                            | 1200.00           | 1080                      |
| 3                    | ZZ/003   | RENEW HEADLAMP AND FOCUS.                                                                  | 48.00             | ✓                         |
| 4                    | ZZ/004   | RENEW A/COND CONDENSER, VACUUM AND REFILL FREON GAS.                                       | 120.00            | ✓                         |
| 5                    | ZZ/005   | APPLY SEALANT TO BONNET.                                                                   | 100.00            | ✓                         |
| 6                    | ZZ/006   | SUPPLY FRONT LICENSE PLATE.                                                                |                   |                           |
| 7                    | ZZ/007   | TOWING CHARGES BY AUTOSWIFT W/O T212008                                                    | 80.00             | ✓                         |
| TOTAL LABOUR CHARGES |          |                                                                                            | 2748.00           |                           |

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLR230R

| S/NO | PARTS DESCRIPTION          | PARTS NUMBER | DAMAGED PARTS & PRICES |      |              |
|------|----------------------------|--------------|------------------------|------|--------------|
|      |                            |              | NETT                   | LIST | S/NETT REMAR |
| 1    | SUNDRIES                   | NFN          |                        |      | 50.00 ?      |
| 2    | FRT LICENCE PLATE          | FLP          |                        | 3ge  | 35.00 /      |
| 3    | EMBLEM RAD GRILLE          | 62890-1DA0B  |                        | one  | 43.70 /      |
| 4    | HORN                       | 25610-3ZL0B  |                        |      | 78.20 ?      |
| 5    | HOSE FLEXIBLE A/COND       | 92480-3ZU0A  |                        | 17   | 94.40 X      |
| 6    | HOSE-FLEXIBLE A/COND       | 92490-BV81A  |                        | 17   | 215.00 X     |
| 7    | A/COND HIGH PRESSURE PIPE  | 92440-3ZU1A  |                        | 17   | 74.30 X      |
| 8    | AIR GUIDE OIL COOLER OUTER | 21609-3ZL5A  |                        |      | 243.00 ?     |
| 9    | AIR GUIDE OIL COOLER INNER | 21609-3ZL0A  |                        |      | 242.50 ?     |
| 10   | OIL COOLER                 | 21606-3ZL0A  |                        |      | 261.50 ?     |
| 11   | HOSE UPPER RADIATOR        | 21501-3ZU1A  |                        |      | 129.10 ?     |
| 12   | HOSE-BOTTOM RADIATOR       | 21503-3ZU0A  |                        |      | 41.20 ?      |
| 13   | RADIATOR OVERFLOW TANK     | 21711-3ZU0A  |                        |      | 102.90 ?     |
| 14   | RADIATOR FAN MOTOR         | 21481-HX52A  |                        |      | 678.60 ?     |
| 15   | A/COND AMBIENT SENSOR      | 27722-BV80C  |                        |      | 81.90 ?      |
| 16   | RADIATOR COOLANT           | NC-01        |                        | one  | 19.00 /      |
| 17   | RADIATOR phv.?             | 21410-HX51B  |                        | one  | 585.20 /     |
| 18   | A/COND CONDENSER phv.?     | 92100-BA61B  |                        | one  | 435.20 /     |
| 19   | WIPER WASHER TANK          | 28910-3ZL1B  |                        | 17   | 250.80 X     |
| 20   | BONNET LOCK                | 65601-3ZP0A  |                        | one  | 113.80 /     |
| 21   | BONNET RUBBER SEAL         | 65820-3ZL0A  |                        | one  | 42.50 /      |
| 22   | BONNET                     | F5100-3ZLMA  |                        | one  | 3533.20 /    |
| 23   | AIR GUIDE FRT LH           | 62823-3ZL0A  |                        | one  | 96.80 /      |
| 24   | AIR GUIDE FRT RH           | 62822-3ZL0A  |                        |      | 65.90 ?      |
| 25   | HOOD LOCK STAY             | 62550-3ZL0A  |                        | one  | 238.80 /     |

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLR230R

| S/NO | PARTS DESCRIPTION             | PARTS NUMBER | DAMAGED PARTS & PRICES |      |              |
|------|-------------------------------|--------------|------------------------|------|--------------|
|      |                               |              | NETT                   | LIST | S/NETT REMAR |
| 26   | RADIATOR SUPPORT STAY LH      | F2521-3ZLMA  |                        | 321  | 160.40 /     |
| 27   | RADIATOR SUPPORT STAY RH      | F2520-3ZLMA  |                        |      | 160.40 ?     |
| 28   | RADIATOR SUPPORT TOP LH       | F2513-3ZLMA  |                        |      | 589.60 ?     |
| 29   | RADIATOR SUPPORT TOP RH       | F2512-3ZLMA  |                        |      | 589.60 ?     |
| 30   | RADIATOR SUPPORT TOP CENTRE   | F2511-3ZLMA  |                        | D.S  | 632.50 /     |
| 31   | CLIP RAD GRILLE @ \$1.00 EACH | 01553-09321  |                        | RM   | 13.00 /      |
| 32   | RADIATOR SUPPORT TOP GARNISH  | 62322-3ZL0A  |                        | D.S  | 329.60 /     |
| 33   | RADIATOR GRILLE               | 62310-3ZL0A  |                        | BRD  | 383.90 /     |
| 34   | HEADLAMP LH                   | 26060-3ZP5A  |                        | BRD  | 970.90 /     |
| 35   | HEADLAMP RH                   | 26010-3ZP5A  |                        |      | 970.90 ?     |
| 36   | FRT BUMPER TOW COVER          | 622A0-3ZL0H  |                        | m.s  | 13.50 /      |
| 37   | FOG LAMP LH                   | 26155-1HA0B  |                        | 17   | 232.30 X     |
| 38   | FOG LAMP RH                   | 26150-1HA0B  |                        | 17   | 232.30 X     |
| 39   | FOG LAMP GARNISH LH           | 62257-3ZL2A  |                        | 17   | 175.90 X     |
| 40   | FOG LAMP GARNISH RH           | 62256-3ZL2A  |                        | 17   | 175.90 X     |
| 41   | FRT BUMPER CHASSIS STAY LH    | G5115-3ZLMA  |                        |      | 475.41 ?     |
| 42   | FRT BUMPER CHASSIS STAY RH    | G5114-3ZLMA  |                        |      | 384.80 ?     |
| 43   | FRT BUMPER LOWER COVER        | 62663-3ZL0A  |                        |      | 83.30 ?      |
| 44   | FRT BUMPER REINFORCEMENT      | F2030-3ZLAA  |                        |      | 2475.60 ?    |
| 45   | ENERGY ABSORBER FRT BUMPER    | 62090-3ZL0A  |                        | Torn | 296.00 /     |
| 46   | FRT BUMPER SIDE BRKT LH       | 62225-3ZL0A  |                        | 321  | 12.90 /      |
| 47   | FRT BUMPER SIDE BRKT RH       | 62224-3ZL0A  |                        | 321  | 12.90 /      |
| 48   | CLIP FRT BUMPER @ 1.00 EACH   | 01553-05933  |                        | RM   | 20.00 /      |
| 49   | FASCIA KIT FRT                | F2022-3ZLMH  |                        | D.S  | 976.90 /     |

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLR230R

| S/NO | PARTS DESCRIPTION                                     | PARTS NUMBER | DAMAGED PARTS & PRICES |      |              |
|------|-------------------------------------------------------|--------------|------------------------|------|--------------|
|      |                                                       |              | NETT                   | LIST | S/NETT REMAR |
|      | SUB TOTAL                                             |              | 0.00                   | 0.00 | 18121.01     |
|      | LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%) |              | 0.00                   | 0.00 | 0.00         |
|      | GRAND TOTAL                                           |              | 0.00                   | 0.00 | 18121.01     |
|      | OVERALL TOTAL                                         |              | 18121.01               |      |              |

LEGEND: REMARKS ( OK ) = APPROVED, REMARKS ( X ) = NOT APPROVED

Front bumper spoiler

7/1/11 ✓

AUTOLUTION INDUSTRIAL PTE. LTD.

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLR230R

-----  
TOTAL LABOUR CHARGES                    2748.00  
TOTAL SPARE PARTS CHARGES            18121.01  
-----  
GRAND TOTAL                            20869.01 \*  
-----

\* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

-----  
NAME                                    :  
SURVEYED DATE                        :  
AUTHORIZED DATE                      :  
EXCESS CLAUSE                        :            0.00  
LIABILITY                              :            0.00  
REMARKS                                :

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.