

Marcus - CKE

AUTOLUTION INDUSTRIAL PTE. LTD.

AUTOLUTION INDUSTRIAL PTE LTD
19 UBI ROAD 4
SINGAPORE 408623
TEL: 6490 9666 FAX: 6846 7483

FINALIZED : ACCIDENT/BODY REPAIRS

REFERENCE : INS/IC/H/0222/24

DATE : 24-JUN-2024

M/S SOMPO INSURANCE SINGAPORE PTE LTD
50 RAFFLES PLACE
#03-03 SINGAPORE LAND TOWER
S(048623)
TEL : 64616555
FAX : 62213147
ATTN : MOTOR CLAIM MANAGER

6 days

OWNER'S NAME : MR WOO JIUN WEI (WU JUNWEI)
ADDRESS : BLK 405 PASIR RIS DRIVE 6
#02-495
S(510405)
TELEPHONE NO : 98324134

TYPE OF CLAIM : OD OR OD RECOVERY CLAIM
POLICY NO : D23MTPV01010038
VEHICLE NO : SLR230R
MODEL CODE : DRLARDZC13UEAB-F-E
MODEL/YEAR : NISSAN PULSAR 1.2 MY2016
ENGINE NO : HRA2406175A-C13S/CL
CHASSIS NO : VSKDDAC13U0104996
MILEAGE : 45467 KM
DATE IN : 24/06/2024
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : HAMZAH
ACCIDENT DATE : 21/06/2024

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLR230R

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	ZZ/001	LABOUR CHARGES TO REPAIR BOTH FRT FENDER, RENEW RADIATOR SUPPORT, BONNET AND FRONT BUMPER.	1200.00	720.00
2	ZZ/002	CHARGES TO SPRAY PAINTING SAME.	1200.00	1080.00
3	ZZ/003	RENEW HEADLAMP AND FOCUS.	48.00	48.00
4	ZZ/004	RENEW A/COND CONDENSER, VACUUM AND REFILL FREON GAS.	120.00	120.00
5	ZZ/005	APPLY SEALANT TO BONNET.	100.00	100.00
6	ZZ/006	SUPPLY FRONT LICENSE PLATE.		
7	ZZ/007	TOWING CHARGES BY AUTOSWIFT W/O T212008	80.00	.00
8	ZZ/008	RENEW INTAKE MANIFOLD.	234.00	234.00
TOTAL LABOUR CHARGES			2982.00	2302.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLR230R

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			REMAR
			NETT	LIST	S/NETT	
1	BONNET INSULATOR	65840-3ZL0A			179.70	OK
2	BONNET HINGE LH	65401-3DN0A			83.20	OK
3	BONNET HINGE RH	65400-3DN0A			83.20	OK
4	FRONT BUMPER SPOILER	YK6010-00C13			380.00	OK
5	MANIFOLD INTAKE	14003-00Q3D			778.50	OK
6	RADIATOR OVERFLOW TANK	21711-3ZU0A			102.90	OK
7	RADIATOR FAN MOTOR	21481-HX52A			678.60	OK
8	RADIATOR COOLANT	NC-01			19.00	OK
9	RADIATOR	21410-HX51B			585.20	OK
10	A/COND CONDENSER	92100-BA61B			435.20	OK
11	BONNET LOCK	65601-3ZP0A			113.80	OK
12	BONNET RUBBER SEAL	65820-3ZL0A			42.50	OK
13	BONNET	F5100-3ZLMA			3533.20	OK
14	AIR GUIDE FRT LH	62823-3ZL0A			96.80	OK
15	HOOD LOCK STAY	62550-3ZL0A			238.80	OK
16	RADIATOR SUPPORT STAY LH	F2521-3ZLMA			160.40	OK
17	RADIATOR SUPPORT TOP CENTRE	F2511-3ZLMA			632.50	OK
18	CLIP RAD GRILLE @ \$1.00 EACH	01553-09321			13.00	OK
19	RADIATOR SUPPORT TOP GARNISH	62322-3ZL0A			329.60	OK
20	RADIATOR GRILLE	62310-3ZL0A			383.90	OK
21	HEADLAMP LH	26060-3ZP5A			970.90	OK
22	HEADLAMP RH	26010-3ZP5A			970.90	OK
23	FRT BUMPER TOW COVER	622A0-3ZL0H			13.50	OK
24	ENERGY ABSORBER FRT BUMPER	62090-3ZL0A			296.00	OK
25	FRT BUMPER SIDE BRKT LH	62225-3ZL0A			12.90	OK

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLR230R

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			REMAR
			NETT	LIST	S/NETT	
26	SUNDRIES	NPN			30.00	OK
27	FRT LICENCE PLATE	FLP			30.00	OK
28	EMBLEM RAD GRILLE	62890-1DA0B			43.70	OK
29	FRT BUMPER SIDE BRKT RH	62224-3ZL0A			12.90	OK
30	CLIP FRT BUMPER @ 1.00 EACH	01553-05933			20.00	OK
31	FASCIA KIT FRT	F2022-3ZLMH			976.90	OK
SUB TOTAL			0.00	0.00	12247.70	
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			0.00	0.00	0.00	
GRAND TOTAL			0.00	0.00	12247.70	
OVERALL TOTAL			12247.70			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

AUTOLUTION INDUSTRIAL PTE. LTD.

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO SLR230R

NETT ITEM	0.00
LESS 20.00%)	0.00
NETT AMOUNT	0.00
LIST ITEM	0.00
LESS 30.00%)	0.00
LIST AMOUNT	0.00
SPECIAL NETT ITEM	12247.70
LESS .00%)	0.00
SPECIAL NETT AMOUNT	12247.70
TOTAL LABOUR CHARGES	2302.00
TOTAL SPARE PARTS CHARGES	12247.70
TOTAL CHARGES	14549.70
ADD 9 % GST	1309.47
GRAND TOTAL	15859.17
