

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Date: **04.11.2024**

Chassis: **ZWR900167228**

Vehicle Number : **SKX4848M**
Vehicle Model : **TOYOTA NOAH HYBRID**
Accident Date : **02.11.2024**
Original Reg Date : **04.06.2024**

ESTIMATE

1	1 pc	Tailgate Assy <i>Orghashed</i>		3,577.60	✓ 2385
2	1 pc	Tailgate Badge <i>Neu</i>		145.60	+
3	1 pc	Tailgate Emblem <i>Neu</i>		95.60	+
4	1 pc	Tailgate Hybrid Synergy Emblem <i>Neu</i>		135.60	✓
5	1 pc	Tailgate Centre Garnish <i>Neu</i>		1,156.80	+
6	1 set	Tailgate Centre Garnish Clips <i>Neu</i>		60.00	+
7	1 pc	Tailgate Opener Switch <i>Neu</i>		456.80	+
8	1 pc	Tailgate Windscreen Inner Seal <i>3/4</i>		243.20	✓
9	1 set	Tailgate Windscreen Moulding		312.70	✓
10	2 pcs	Tailgate Side Stopper (Male) <i>3/4</i>	98.00	196.00	+
11	2 pcs	Tailgate Side Stopper (Female) <i>1/4</i>	145.00	290.00	+
12	1 pc	Tailgate Pocket Handle <i>Neu</i>		87.00	+
13	1 pc	Tailgate Inner Trim <i>Orghashed</i>		1,633.50	✓ 865
14	1 pc	Tailgate Inner Trim Cover Centre <i>Neu</i>		243.20	+
15	1 pc	Tailgate Inner Trim Side <i>Neu</i>	231.20	462.40	+
16	1 set	Tailgate Inner Trim Clips <i>Neu</i>		40.00	30
17	1 pc	Tailgate Inner Lock <i>Orghashed</i>		575.30	✓ 498
18	1 pc	Tailgate Lock Catch <i>Neu</i>		78.60	+
19	1 pc	Tailgate Weatherstrip <i>Orghashed</i>		386.60	✓
20	1 pc	Tailgate motor <i>Neu</i>		2,687.54	+
21	2 pcs	Tailgate Hinges <i>Neu</i>	245.60	491.20	+
22	1 pc	Rear Bumper (Japan model with paint) <i>Orghashed</i>		2,576.20	✓ 1180
23	1 pc	Rear Bumper Side Retainers <i>Neu</i>	99.20	198.40	+
24	1 pc	Rear Bumper Reflector Lamps <i>Orghashed</i>	165.20	330.40	✓
25	1 pc	Rear Bumper towing cover <i>Neu</i>		76.00	+
26	1 set	Rear Bumper Clips <i>Neu</i>		50.00	30
27	2 pc	Rear Bumper Side Lower Cover <i>Neu</i>	167.20	334.40	+
28	4 pcs	Rear Bumper Reverse Sensor <i>2 pieces Orghashed</i>	398.00	1,592.00	✓ 590
29	4 pcs	Rear Bumper Reverse Sensor Holder <i>Neu</i>	68.00	272.00	✓ 100
30	1 pc	Rear Bumper Reverse Sensor Wire Harness <i>Neu</i>		867.20	+
31	1 pc	Rear Corner bumpers <i>Neu</i>	566.20	1,132.40	+
32	1 pc	Rear Corner bumper Retainer <i>Neu</i>	78.90	157.80	✓
33	1 pc	Rear Key Antenna Sensor <i>Orghashed</i>		274.80	✓
34	2 pc	Taillamps Assy <i>Neu</i>	1,392.90	2,785.80	+

35	2 pc	Taillamps Sealer	2	67.00	134.00	+
36	1 set	Taillamps Clips	new		30.00	+
37	2 pc	Taillamp Panel		577.20	1,154.40	+
38	1 pc	End Panel Assy	Defect		1,455.80	- 865
39	1 pc	End Panel Top Trim	Defect		387.50	+
40	1 set	End Panel Top Trim Clips	new		30.00	- 10
41	1 pc	End Panel Inner	Repair		1,122.50	+
42	1 pc	Side Panel	new	683.60	1,367.20	+
43	1 set	Top board set	could		1,672.50	- 895
44	1 set	Rear Floor Panel	Repair		1,455.50	+
45	1 set	Rear Floor Panel Mat	new		980.00	+
46	1 set	Rear Floor Panel Mat Silencer	new		201.40	+
47	2 pc	Rear reinforcement damper	new	195.30	390.60	+
48	1 pc	Wire Harness	new		986.20	+
49	2 pc	Rear Fender	new	2,158.90	4,317.80	+
50	2 pc	Rear Fender Inner Trim	Defect	1,102.50	1,945.00	- 1850
51	2 set	Rear Fender Inner Trim Clips	new		60.00	+
52	2 set	Rear Fender Top Garnish	new	852.30	1,704.60	+
53	1 set	Rear Fender Top Garnish Clips	new		40.00	+
54	1 pc	Rear Air Vent LH	new		197.50	+
55	1 pc	Rear Fender Inner Cowl	new		165.80	+
56	1 pc	Rear Fender Inner Shield	new		165.80	+
57	1 set	Rear Fender Inner Shield Clips	new		30.00	+
				subtotal	43,996.74	
				Parts Disc 25%	32,997.56	

Special Nett

1	1 set	Reverse Camera	new		450.00	+
2	1 pc	Rear Windscreen Sealant	new		60.00	✓
3	1 set	Body Panel Joint Sealant	new		120.00	- 60
4	1 pc	Rear Number Plate with Cover	new		70.00	+
				subtotal	700.00	

Labour charge

Panel Beating		3,000.00	900
Spray painting		2,400.00	900
Check Wiring on tailamp		180.00	30
Anti rust		120.00	60
Conduct Water leak test		80.00	+
Remove and install rear winscreen.		180.00	120
Remove and install tailgate parts.	2230	250.00	60
Remove and install interior upholstery		150.00	60
Remove and install reverse sensor		120.00	50
Remove and install reverse camera.		150.00	50
To program ADAS reset		350.00	x

\$ 41,377.56

Adrian G
P/P 04/11/24.
06 Days

total 10929.10
(P/P) ✓