



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SNR 6285U

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	COVER FRT BUMPER (SN)	SCRATCHED	\$2,026.20	\$2,026.20
1	BRACKET BUMPER INNER BRACKET LH (SN)	SERVICEABLE	\$65.47	\$0.00
1	GUIDE PIEC BUMPER SIDE BRACKET LH (SN)	NECESSARY	\$49.59	\$49.59
1	BRACKET SENSOR BRACKET (SN)	NECESSARY	\$36.16	\$36.16
1	BRACKET SENSOR BRACKET (SN)	NECESSARY	\$36.16	\$36.16
1	COVER FOR LHS FOG LAMP GRILLE (SN)	SERVICEABLE	\$70.17	\$0.00
1	MOLDING LHS FOG LAMP GRILLE MLDG CHROM (SN)	SERVICEABLE	\$176.44	\$0.00
1	TRIM LHS BUMPER LOWER SIDE TRIM (BLACK) (SN)	SCRATCHED	\$68.34	\$68.34
1	LED HEADLI LHS H/LAMP (SN)	SCRATCHED	\$3,893.27	\$3,893.27
1	FENDER LH (SN)	BENT	\$980.20	\$980.20
1	BRACKET LHS FENDER BRACKET (SN)	NECESSARY	\$62.34	\$62.34
1	WHEELHOUSE LHF FENDER LINER (SN)	SERVICEABLE	\$291.54	\$0.00
1	FLAT CONTACT HOUSING WITH FOG LAMP WIRE HOUSING.SCK AO 18/11/24 (SN) (ADDITIONAL)	CRACKED	\$17.30	\$17.30
			\$7,773.18	\$7,169.56

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	B&P CHECK SHORT CIRCUIT/HARNESS REPAIR		\$280.00	\$280.00
	B&P DIAGNOSIS AND PROGRAMMING		\$480.00	\$480.00
	TO ALIGN LED HEADLIGHT		\$100.00	\$100.00
	LABOUR		\$3,360.00	\$1,680.00
	SPRAY PAINT		\$3,200.00	\$1,600.00
			\$7,420.00	\$4,140.00

GRAND TOTAL			\$15,193.18	\$11,309.56
--------------------	--	--	--------------------	--------------------

RECOMMENDED COST OF REPAIRS				\$11,309.56
------------------------------------	--	--	--	--------------------

Report Ref No: CS/SPF24110075/Rqp3m4

NOTES : THE ESTIMATED UPPER RANGE OF REPAIR COST FOR THE DAMAGED VEHICLE IS IN THE REGION OF \$11,309.56-\$12,500.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

MRB

MOHAMMED RASUL BIN MOHD YUNUS

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of repositibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.