



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS AUTOMOTIVE ENGRG. & MGT. DIVISION (TP)	Ref:	CS/SPF24110075/Rqp3m4
ACCIDENT CLAIMS SECTION (SPORE POLICE FORCE)	Date:	27/11/2024
POLICE LOGISTICS BASE (PLB)	Code:	SPF
1 HEMMANT ROAD SINGAPORE 438675		

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	PD 305K	Veh. Inspected	SNR 6285U
Policy No.	-	Coverage	0
Claim No.	ACS/105/009/2024/058(CF)	Excess	\$0.00
Assign From	ENG CUI FEN	Assign Date	04/11/2024

2. Vehicle Details

Make & Model	SKODA OCTAVIA STYLE 1.5 TSI	C.C	1498
Engine No.	DFY074738	Year of Reg.	28/07/2021
Chassis No.	TMBBR7NXXMY171519	Colour	BLUE
Odometer	35786 KM	Steering	IN ORDER
Brakes	IN ORDER	General	FAIR
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	225/45 ZR18	MICHELIN	6
L/H Front Tyre	225/45 ZR18	MICHELIN	6
R/H Rear Tyre	225/45 ZR18	MICHELIN	6
L/H Rear Tyre	225/45 ZR18	MICHELIN	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	03/11/2024	Inspection Date	05/11/2024
Survey held at	BLOCK 464B CLEMENTI AVENUE 1, SINGAPORE 122464		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days