ASS. REC. BY:	
	IGNMENT
From: Date:	
Estimated Cost:	Veh No: SK 7 3) 966 Yr Regn: 01, 16
OD/TP/WS/TP RES/OD RES/EVA/INV/MY	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or
To Inspect Vehicle No:	100
at Workshop m/s Chown Hock	Colour No. Gran AC: Insured / Std / NI / NA
of 1426	Sp.Reading 157472 T/Radio: Insured / Std / NI / NA
Insured:	Eng/No:
Policy No.	CNO: JM6 ENI 07 1 G 0123115
Claims No.	Gen. Cohd: QGod/ Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Inorger / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder/Jammed/Leaked/Burnt or
Make of Veh:	Modi: NII / S/Rim / STD A/Rim or
	Tyre Size: F: 205/55 R16
(Policy Condition)	. R:
Remark: The veh had commenced its N/S O/S repair at the time of inspection.	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUM /
	TOYO/YOKO or Falker
Bal. or Market Value: § 23/6	Front 7 Rear
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. / mm 'R/Bal. / mm
GIA / PR Seen: Consistent?: Yes or No	L/Bal. 7 mm L/Bal. 7 mm
Est. Repairs: 9-5 days Res.: Yes or No	D.O.A. 15/10/24 D.O.I. 5/11/2024
Lum Sum: 20 % 3 Val.: Yes or No	Survey held at
CA / REV. / REP. / 24 HRS	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
Vehicle: IN/OUT	Rea ols
Date:Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction	
	/
R	
11.	
	The second section of the second section is the second section of the second section s
	The second district and the second se
Onto/Time, File Pass to? : Prell. Report Da	ays Of Repair:
-	
	survey No. of Trip: Survey Fee:
Outa/fime, File Return to?	Transportation
Add Fee:	: Site insp (\$)_s-RSSi
Sand Francis	: Interview (\$), Firsts
Report Format :	Tech Invs (\$) Others
Lump Sum / I.B.I: (\$.	Weekend (\$
La manus de la manus partir de la companya de la co	
	ICTAL

CHOON HOCK MOTOR TRADING CO

1 November 2024

Not Notherial
USy &
Rearry Able Pains
4-5day,

ESTIMATE REPAIR BILL ON SKZ3196G MAZDA 5 SKYACTIV

1 pce rear tailgate		R, \$ 1	,350.00	_
1 pce rear tailgate reflector RH		\$	350.00	7
1 pce "MAZDA" logo		Mg\$	65.00	_
1 pce "MAZDA 5" plate		nes	80.00	
1 pce "SKYACTIV" plate		ne s	55.00	_
1 pce rear bumper assy.		cms	950.00	_
1 pce rear bumper reflector RH		s- \$	48.00	X
2 pcs rear side retainer	Ols	Dit\$	150.00	4
1 pce rear bumper reinforcement		\$	350.00	7
1 pce rear tailgate inner rubber		\$	230.00	7
1 pce rear panel		\$	550.00	7
		\$	4,178.00	
	less 20%	\$	835.60	
			3,342.40	
	100000	-		

LABOUR

1 set rear windscreen sealant 1 set rear sensor	sun \$	80.00 220.00	2003m
Remove, refit rear windscreen	\$	200.00	
Remove, refit rear sensor	\$ \$	100.00 150.00	
Remove, refit rear tailgate Panel beating	\$	00.000,1	
Spray painting		1,000.00 6,092.40	6001
Total amount:	2	0,092.40	NEII

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- · No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Mailing address: 28 Surrey Road #18-03 Singapore 307762 Reg No: 30568200L Tel: (65) 64530778 Email: choonhockmotor@gmail.com SF0F24B1M002 / FALCON-AIR AUTO SERVICES PTE LTD [575721] ENTRY DATE & TIME: 01/11/2024 12:31 (SGT) SUBMITTED BY: Florence Loh VERSION: 1 (01/11/2024 12:31 (SGT))

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

IMPCOLIANT NOTICE

1. Please report <u>correctly</u> the details of the accident to speed up the claims process.

2. This Form must be <u>completed by the Policyholder and/or the Actual Driver</u>

3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate

Information provided must be as truthed and acceptance as possible. Any white misrepresentation of withouting of material tests and policy liability.
 The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
 Any false reporting may be referred to the Police for investigation.
 This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
 By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of First Submission Reported by **Date of Accident Exact Location of Accident** Additional Location Information Country/State of Loss

01/11/2024 12:31 (SGT) Both Policyholder and Actual Driver 15/10/2024 19:50 (SGT) Singapore PASIR RIS DR 6 SLIP ROAD INTO PASIR RIS DR 3 Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number

SKZ3196G

INSURED/POLICYHOLDER

Is company? Name Of Registered Owner NRIC No **Fmail Address** Mobile Phone No Alternative Phone No

No WANG WENG KANG S0076142G wangwk100@gmail.com (Phone) +65-96157487

VEHICLE PARTICULARS

Manufacturer Model

Variant

Exact purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to

your vehicle? Vehicle Category **Transmission**

CC

Vehicle Fuel

First Regisration Date

Chassis no

Effective Date/Time of Ownership

MAZDA5 5-DOOR WAGON 2.0L SP.6EAT SUNROOF

No - Claiming third party

Private car Auto

1998

Petrol

18/01/2016

JM6CW1071G0123115

18/01/2016 02:01 (SGT)

INSURANCE COMPANY

Name of Insurance Company Policy Number / Cover Note Number Income Insurance Limited 5086997743-07

DRIVER

Resure De 3

I was driving along Pasir Ris Drive & on 15th ort 2004 around & Signi.

I stopped to check if there are any cars before throng left to Pasir Ris Drive 3

Vehicle SHCX8M suddenly knecked the back of my car.

I have a flight to Catch on 15th oct night. Therefore was not able to make any personal report. My son in law tried to report many rehalf but was rejected.

Attached boarding pass and airticized as supporting electrospats.