

CHOON HOCK MOTOR TRADING CO

1 November 2024

Not Authorized
 11/11/24 @ 3:30pm
 Recovery After Paint
 5 days

ESTIMATE REPAIR BILL ON SKZ3196G MAZDA 5 SKYACTIV

1 pce rear tailgate	R \$ 1,350.00	✓
1 pce rear tailgate reflector RH	Went \$ 350.00	✓
1 pce "MAZDA" logo	R \$ 65.00	✓
1 pce "MAZDA 5" plate	R \$ 80.00	✓
1 pce "SKYACTIV" plate	R \$ 55.00	✓
1 pce rear bumper assy.	CM \$ 950.00	✓
1 pce rear bumper reflector RH	R \$ 48.00	X
2 pcs rear side retainer	dis Dir \$ 150.00	✓
1 pce rear bumper reinforcement	R \$ 350.00	✓
1 pce rear tailgate inner rubber	W \$ 230.00	50/100 11/11/24
1 pce rear panel	R \$ 550.00	✓
	\$ 4,178.00	
less 20%	\$ 835.60	
	\$ 3,342.40	

LABOUR

1 set rear windscreen sealant	\$ 80.00	40/11/24
1 set rear sensor	Sur \$ 220.00	200/11/24
Remove, refit rear windscreen	\$ 200.00	120/
Remove, refit rear sensor	\$ 100.00	50/
Remove, refit rear tailgate	\$ 150.00	60/
Panel beating	\$ 1,000.00	600/
Spray painting	\$ 1,000.00	600/
Total amount :	\$ 6,092.40	NETT

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: