





**PHOTOGRAPHS FOR VEHICLE NO. : SMT 2237L**



**PHOTOGRAPHS FOR VEHICLE NO. : SMT 2237L**



**PHOTOGRAPHS FOR VEHICLE NO. : SMT 2237L**



**PHOTOGRAPHS FOR VEHICLE NO. : SMT 2237L**




**PHOTOGRAPHS FOR VEHICLE NO. : SMT 2237L**





**PHOTOGRAPHS FOR VEHICLE NO. : SMT 2237L**



**PHOTOGRAPHS FOR VEHICLE NO. : SMT 2237L**



**PHOTOGRAPHS FOR VEHICLE NO. : SMT 2237L**



**PHOTOGRAPHS FOR VEHICLE NO. : SMT 2237L**



**PHOTOGRAPHS FOR VEHICLE NO. : SMT 2237L**



**PHOTOGRAPHS FOR VEHICLE NO. : SMT 2237L**





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

INSPECTION PHOTOS (Page 12 of 16)

### PHOTOGRAPHS FOR VEHICLE NO. : SMT 2237L






## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

INSPECTION PHOTOS (Page 13 of 16)


### PHOTOGRAPHS FOR VEHICLE NO. : SMT 2237L



**PHOTOGRAPHS FOR VEHICLE NO. : SMT 2237L**



**PHOTOGRAPHS FOR VEHICLE NO. : SMT 2237L**



**PHOTOGRAPHS FOR VEHICLE NO. : SMT 2237L**

