



QUOTATION

CODE: F0001
 CUSTOMER: MS FIRST CAPITAL INSURANCE LTD
 ADDRESS: 16 RAFFLES QUAY
 #42-01
 HONG LEONG BUILDING
 SINGAPORE 048581
 ATTN:MOTOR CLAIM DEPT
 CONTACT NO.: 6507 3848
 MODEL: MAZDA5 SKYACTIVE
 CHASSIS NO.: JM6CW1071G0123932
 ENGINE NO.: PE10349699
 REG NO.: SLD8621S
 REGN DATE: 29/06/2016

PAGE NO.: 1
 DOCUMENT NO.: 1629
 DOCUMENT DATE: 03/12/2024
 POS ID:MU
 PRINTED BY: Wong Chun Wei
 SERVICE ADV:
 CSP/OP CODE: Wong Chun Wei
 DEPT: I
 WIP NO.: 21928
 REF. NO.:
 DATE IN:
 EXT. WTY:
 MILEAGE: 0

DESCRIPTION:

Item	Description	Qty.	Unit Price	Stk/Status	Gross amount	GST Code
			SGD		SGD	
NOTES	MS FIRST TP CLAIM				0.00	O
SUB	MZ 5 UBI TO REMOVE & REPLACE REAR BUMPER & TAILGATE. AND ALL ACCIDENT AFFECTED AREA. - PO24063				1,584.00	S
SUB	MZ 5 UBI TO RESPRAY REAR BUMPER & TAILGATE. - PO24063				1,512.00	S
SUB	MZ 5 UBI TO SUPPLY NUMBER PLATE. - PO24063				70.00	S
SUB	MZ 5 UBI TO TRANSFER REVERSE SENSORS. - PO24063				180.00	S
SUB	MZ 3 UBI TO TRANSFER TAILGATE MECHANISM. - PO24063				396.00	S
SUB	MZ 5 UBI TO REMOVE & REFIT THE WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST.				670.00	S

**This is only an estimate from our visual inspection and should there be more damages found during the process of works you will then be informed for your approval before proceeding with the repairs.*

**Take note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of \$180.00 will be applied and it will varies depending on the time unit that was taken for the checking and diagnosis of your vehicle.*



Corporate Head Office : Trans Eurokars Pte Ltd, 11 Kung Chong Road Singapore 159147
 Tel: 6363 3003, Fax: 63693003, BRN: 199103859N, GST Regn. No.: M90364005A

ZOOM-ZOOM

Showrooms & Service Centres :
 5 Ubi Close Singapore 408605 23 Leng Kee Road Singapore 159095
 Sales Tel: 6395 8888 Service Tel: 6395 8899 Sales Tel: 6603 6118 Service Tel: 6603 6128
 Sales Fax: 68461700 Service Fax: 6744 9402 Sales Fax: 6476 7073 Service Fax: 6476 7417



QUOTATION

CODE: F0001
CUSTOMER: MS FIRST CAPITAL INSURANCE LTD
ADDRESS: 16 RAFFLES QUAY
#42-01
HONG LEONG BUILDING
SINGAPORE 048581
ATTN:MOTOR CLAIM DEPT
CONTACT NO.: 6507 3848
MODEL: MAZDA5 SKYACTIVE
CHASSIS NO.: JM6CW1071G0123932
ENGINE NO.: PE10349699
REG NO.: SLD8621S
REGN DATE: 29/06/2016

PAGE NO.: 2
DOCUMENT NO.: 1629
DOCUMENT DATE: 03/12/2024
POS ID: MU
PRINTED BY: Wong Chun Wei
SERVICE ADV:
CSP/OP CODE: Wong Chun Wei
DEPT: I
WIP NO.: 21928
REF. NO.:
DATE IN:
EXT. WTY:
MILEAGE: 0

DESCRIPTION:

Item	Description	Qty.	Unit Price	Stk/Status	Gross amount	GST Code
			SGD		SGD	
SUB	- PO24063 MZ 5 UBI TO SUPPLY SEALER ON THE WINDSCREEN GLASS.				120.00	S
SUB	- PO24063 MZ 5 UBI TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.				150.00	S
SUB	- PO24063 MZ 5 UBI TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.				180.00	S
SUB	- PO24063 MZ 5 UBI SUNDRIES.				20.00	S
C513-50-221EB	REAR BUMPER CW	1.00	916.78	*ISSUED	916.78	S
BN8F-50-355	RIVET	4.00	4.64	*ISSUED	18.56	S
G043-62-864A	TAPE,PROTECTOR	2.00	2.95	*ISSUED	5.90	S
D350-51-5L0E	REFLECTOR LHR,REFLEX-	1.00	55.13	*ISSUED	55.13	S

**This is only an estimate from our visual inspection and should there be more damages found during the process of works you will then be informed for your approval before proceeding with the repairs.*

**Take note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of \$180.00 will be applied and it will varies depending on the time unit that was taken for the checking and diagnosis of your vehicle.*



Corporate Head Office : Trans Eurokars Pte Ltd, 11 Kung Chong Road Singapore 159147
Tel: 6363 3003, Fax: 63693003, BRN.199103859N, GST Regn. No.: M90364005A

ZOOM-ZOOM

Showrooms & Service Centres :
5 Ubi Close Singapore 408605 23 Leng Kee Road Singapore 159095
Sales Tel: 6395 8888 Service Tel: 6395 8899 Sales Tel: 6603 6118 Service Tel: 6603 6128
Sales Fax: 68461700 Service Fax: 6744 9402 Sales Fax: 6476 7073 Service Fax: 6476 7417



QUOTATION

CODE: F0001
 CUSTOMER: MS FIRST CAPITAL INSURANCE LTD
 ADDRESS: 16 RAFFLES QUAY
 #42-01
 HONG LEONG BUILDING
 SINGAPORE 048581
 ATTN:MOTOR CLAIM DEPT
 CONTACT NO.: 6507 3848
 MODEL: MAZDA5 SKYACTIVE
 CHASSIS NO.: JM6CW1071G0123932
 ENGINE NO.: PE10349699
 REG NO.: SLD8621S
 REGN DATE: 29/06/2016

PAGE NO.: 3
 DOCUMENT NO.: 1629
 DOCUMENT DATE: 03/12/2024
 POS ID: MU
 PRINTED BY: Wong Chun Wei
 SERVICE ADV:
 CSP/OP CODE: Wong Chun Wei
 DEPT: I
 WIP NO.: 21928
 REF. NO.:
 DATE IN:
 EXT. WTY:
 MILEAGE: 0

DESCRIPTION:

Item	Description	Qty.	Unit Price	Stk/Status	Gross amount	GST Code
			SGD		SGD	
CGY3-62-02XF	BODY,LIFT GATE CW	1.00	1,590.90	*ISSUED	1,590.90	S
GHP9-58-867	VALVE,ONEWAY	2.00	12.06	*ISSUED	24.12	S
EG21-51-SJ3	CLIP	3.00	5.57	*ISSUED	16.71	S
C513-50-611	MOULD,RR.WINDOW CW	1.00	61.62	*ISSUED	61.62	S
D204-50-896A	FASTENER	6.00	2.36	*ISSUED	14.16	S
DJ01-50-897	SPACER	1.00	6.49	*ISSUED	6.49	S
C273-50-896	FASTENER	2.00	7.42	*ISSUED	14.84	S
GJ6A-50-897	SPACER	4.00	11.13	*ISSUED	44.52	S
G21E-63-938B	PIN,STUD	1.00	10.20	*ISSUED	10.20	S
C513-51-160D	LAMP(L),RR COMB.CW	1.00	596.58	*ISSUED	596.58	S
GJ6A-51-14Y	FASTENER,LAMP	2.00	14.84	*ISSUED	29.68	S
EA01-51-146B	GROMMET,SCREW-R.COMB	2.00	2.53	*ISSUED	5.06	S
EA02-51-146A	GROMMET,SCREW-R.COMB	2.00	2.53	*ISSUED	5.06	S
B01W-51-142B	GROMMET,SCREW-R.COMB	4.00	2.62	*ISSUED	10.48	S
C513-51-3G0G	LAMP(L),TRUNK LID CW	1.00	397.75	*ISSUED	397.75	S
C513-51-3H8	GASKET(R),LAMP-TRUNK CW	1.00	102.83	*ISSUED	102.83	S
C513-51-3J8	GASKET(L),LAMP-TRUNK CW	1.00	102.83	*ISSUED	102.83	S
C513-50-810F8E	GARNISH,LIFT GATE CW	1.00	492.49	*ISSUED	492.49	S
CGY0-51-711	ORNAMENT,CAR NAME-RR CW	1.00	51.67	*ISSUED	51.67	S
CGY0-51-721	ORNAMENT,CAR NAME-RE CW	1.00	40.63	*ISSUED	40.63	S

*This is only an estimate from our visual inspection and should there be more damages found during the process of works you will then be informed for your approval before proceeding with the repairs.

*Take note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of \$180.00 will be applied and it will varies depending on the time unit that was taken for the checking and diagnosis of your vehicle.



Corporate Head Office : Trans Eurokars Pte Ltd, 11 Kung Chong Road Singapore 159147
 Tel: 6363 3003, Fax: 63693003, BRN.199103859N, GST Regn. No.: M90364005A



Showrooms & Service Centres :
 5 Ubi Close Singapore 408605 23 Leng Kee Road Singapore 159095
 Sales Tel: 6395 8888 Service Tel: 6395 8899 Sales Tel: 6603 6118 Service Tel: 6603 6128
 Sales Fax: 68461700 Service Fax: 6744 9402 Sales Fax: 6476 7073 Service Fax: 6476 7417



QUOTATION

CODE: F0001
 CUSTOMER: MS FIRST CAPITAL INSURANCE LTD
 ADDRESS: 16 RAFFLES QUAY
 #42-01
 HONG LEONG BUILDING
 SINGAPORE 048581
 ATTN:MOTOR CLAIM DEPT
 CONTACT NO.: 6507 3848
 MODEL: MAZDA5 SKYACTIVE
 CHASSIS NO.: JM6CW1071G0123932
 ENGINE NO.: PE10349699
 REG NO.: SLD8621S
 REGN DATE: 29/06/2016

PAGE NO.: 4
 DOCUMENT NO.: 1629
 DOCUMENT DATE: 03/12/2024
 POS ID: MU
 PRINTED BY: Wong Chun Wei
 SERVICE ADV:
 CSP/OP CODE: Wong Chun Wei
 DEPT: I
 WIP NO.: 21928
 REF. NO.:
 DATE IN:
 EXT. WTY:
 MILEAGE: 0

DESCRIPTION:

Item	Description	Qty.	Unit Price	Stk/Status	Gross amount	GST Code
			SGD		SGD	
C514-51-958A	CLIP,SPOILER	3.00	6.49	*ISSUED	19.47	S
C525-51-958A	CLIP,SPOILER	1.00	7.42	*ISSUED	7.42	S

	* GST Code	Rate	Service/Goods	GST	Before GST	GST	Total
Parts	O	-		-			
Surcharge	S	9.00%	9,523.88	857.15	9,523.88	857.15	10,381.03
Labour							
Menus							
Amount Due					9,523.88	857.15	10,381.03

*This is only an estimate from our visual inspection and should there be more damages found during the process of works you will then be informed for your approval before proceeding with the repairs.

*Take note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of \$180.00 will be applied and it will varies depending on the time unit that was taken for the checking and diagnosis of your vehicle.

**Deposit tax invoice No.:

CASH / NETS / AMEX / VISA / MASTER / CHEQUE
 No.

Date: _____ Customer signature _____ Authorised signature _____

TRANS EUROKARS Eurokars Group Corporate Head Office : Trans Eurokars Pte Ltd, 11 Kung Chong Road Singapore 159147
 Tel: 6363 3003, Fax: 63693003, BRN.199103859N, GST Regn. No.: M90364005A

ZOOM-ZOOM Showrooms & Service Centres :
 5 Ubi Close Singapore 408605 23 Leng Kee Road Singapore 159095
 Sales Tel: 6395 8888 Service Tel: 6395 8899 Sales Tel: 6603 6118 Service Tel: 6603 6128
 Sales Fax: 68461700 Service Fax: 6744 9402 Sales Fax: 6476 7073 Service Fax: 6476 7417