

哈 汽 車 貿 易 服 務

HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: 3161/11/24

Your Ref:

Date: 4th Nov 2024

The Claim's Manager
Motor Claims Dept.
INDIA INTERNATIONAL INSURANCE PTE. LTD.
6, Raffles Quay, #22-00, S(048580)

Name Of Insured : Mr Kwek Siew Chuan Jason
Date Of Accident : 03/11/24 (19:30hrs)
Policy Number : D18MPC0003164_05

Not Authorised
mercus
Excess \$750

6 days. L/s \$7900
wh ph the thing.

Estimate cost of repair to TOYOTA WISH (A) 2.0 MPV - SLT 4012 S

1 pc tail gate door	Body	\$ 2,821.30	✓
1 set rear windscreen glass seal	ru	199.80	✓
1 pc rear windscreen glass inner damper	ru	143.00	✓
1 pc rear windscreen glass sealant	ru	60.00	40 S/W
1 pc tail gate door logo emblem	ru	73.50	✓
1 pc licence lamp chrome moulding	Body/ru	342.30	✓
1 pc 'Broneo Motor' emblem	ru	57.30	✓
1 pc tail gate door o/s reflecter	one	315.70	✓
1 pc tail gate door handle cover	ms	31.90	✓
1 pc tail gate door inner lock	Dayle	571.50	✓
1 pc tail gate door lock stricker	11	56.70	X
1 pc tail gate door weatherstrip	ru	463.00	✓
1 pc trim board cover	oc/Body	503.50	✓
16 pcs trim board clips	11	60.80	X
1 pc wiper motor	su	1,035.30	X
1 pc top spoiler sealant	11	60.00	X
10 pcs top spoiler clips	11	42.00	X
1 pc top spoiler damper seal	ru	38.80	✓
1 pc rear bumper	215	911.60	✓
10 pcs rear bumper clips	11	60.00	✓
1 pc rear bumper o/s top retainer	one	70.20	✓
1 pc rear bumper o/s side retainer	one/Body	149.10	✓
1 pc rear bumper o/s stay bracket	11	74.70	✓
1 set rear bumper reverse sensor	multibon	268.80	✓
1 pc rear bumper o/s reflecter	su	83.40	X
1 pc rear exhaust muffler	R	1,823.40	X
2 pcs rear exhaust muffler mounting	11	136.40	X
1 pc rear end panel	Body	817.70	✓
1 pc rear end panel top garnish	11	413.40	✓
6 pcs rear end panel top garnish clips	11	36.00	✓
1 pc rear floor board cover	11	999.00	✓
1 pc spare tyre carrier	su	455.40	✓
1 pc spare tyre carrier lock nut	11	55.30	✓
1 pc rear o/s fender	R	1,652.70	X
1 pc rear o/s fender inner wheel guard	11	92.50	X
1 pc o/s tail lamp assy	CM	461.80	✓
8 pcs rear o/s fender inner shield clips	11	48.00	✓
1 pc Luggage room box separator	one	559.30	✓

Less 25% \$ 15,645.10
\$ 3,911.28

Balance C/F.....
\$ 11,733.82

哈 汽 車 貿 易 服 務

HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: 3161/11/24 Your Ref: Date: 4th NOV 2024

M/S INDIA INTERNATIONAL INSURANCE PTE. LTD.,

Balance B/F... \$ 11,733.82

1 pc body sealant
1 pc rear number plate

11 60.00 S.N. X
SCN 45.00 S.N. 40

To wiring check up & transfer affected wiring system. camera,

100.00 30

To remove & refix rear windscreen glass & o/s quarter glass.

250.00 120

To remove & refix tail gate door hinge, shock absorber, inner lock, wiper motor, arm, trim board cover, handle & necessary parts into new door.

180.00 60

To remove & refix carpet, floor mat, garnish, floor board cover, spare tyre, tool set & necessary parts.

150.00 80

To transfer tail gate door top spoiler & pump sealant.

11 150.00 X

To jack, straighten rear exhaust muffler & tail pipe.

180.00 60

Labour charge to remove & cut out damaged parts, to jack, straighten & knocking out rear o/s fender, rear floor board panel & necessary parts, to weld, renew & align above parts.

1,800.00 1200

To putty & respray painting on all affected accident parts.

1,600.00 1200

\$ 16,248.82
=====

Dollars : Sixteen Thousand Two Hundred Forty Eight And Eighty Two Only.

HUP MOTOR TRADING & SERVICE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

9432.2
252
7074.15
80
2750
9904.15
202
7923